



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Ref: CC3/ASM19013565/Kea3q2	
			Date: 08/03/2021	
			Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 5005M	Veh. Inspected	SHB 7695T	
Policy No.	VFX/P1680520	Coverage (\$)	0.00	
Claim No.	S9M01VOQ	Excess (\$)	0.00	
Assign From		Assign Date	01/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU403080156	Colour	M.P WHITE / RED	
Odometer	22483 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	8 mm	
L/H Front Tyre	195/65 R15	SAILUN	8 mm	
R/H Rear Tyre	195/65 R15	SAILUN	8 mm	
L/H Rear Tyre	195/65 R15	SAILUN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/07/2019	Inspection Date	01/08/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	