

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: MSIG	DATE	: 02/08/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLQ2560E		
MODEL	: VOLKSWAGEN GOLF		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
DATE	: 01-08-2019		
TIME	: 07:25 HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT SIDE MIRROR ASSY RH <i>cracked</i>	1	\$ 830.50	\$ 830.50
2	FRONT BUMPER <i>Repl</i>	1	\$ 1,355.40	\$ 1,355.40
3	FRONT BUMPER SIDE RETAINER RH <i>new</i>	1	\$ 90.00	\$ 90.00
4	FRONT FENDER RH <i>Dented</i>	1	\$ 722.50	\$ 722.50
5	FRONT FENDER INNER COWLING RH <i>new</i>	1	\$ 166.90	\$ 166.90
6	FRONT KNUCKLE RH <i>2</i>	1	\$ 655.00	\$ 655.00
7	FRONT WHEEL HUB WITH BEARING RH <i>1</i>	1	\$ 380.00	\$ 380.00
8	FRONT LOWER ARM RH <i>1</i>	1	\$ 488.30	\$ 488.30
9	FRONT SHOCK ABSORBER RH	1	\$ 420.00	\$ 420.00
10	HEADLAMP RH	1	\$ 2,558.60	\$ 2,558.60
11	HEADLAMP LOWER BRACKET RH <i>new</i>	1	\$ 92.50	\$ 92.50
12	FRONT DOOR RH <i>Dented</i>	1	\$ 1,988.50	\$ 1,988.50
13	FRONT DOOR HINGE <i>new</i>	2	\$ 98.50	\$ 197.00
14	FRONT DOOR CHECKER <i>new</i>	1	\$ 280.00	\$ 280.00
15	FRONT DOOR POWER WINDOW REGULATION <i>new</i>	1	\$ 430.00	\$ 430.00
16	FRONT DOOR POWER WINDOW MOTOR <i>new</i>	1	\$ 630.00	\$ 630.00
17	REAR DOOR RH <i>Dented</i>	1	\$ 1,988.50	\$ 1,988.50

TOTAL PRICE \$ 13,273.70