

INS. CASE OWNER:

Loh Chee Heng

CC4/AIG19013645/Kea3

LKK:

IDAC:

## ASSIGNMENT

Surveyor:

KENNETH

DOI: 05/08/2019

Date / Time : 05/08/2019

Registered in Merimen: 05/08/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SKP 218A

Claim No. : 5346362561SG

Name of Insured : CHONG LEIGH HSIANG

Policy No. : 1800138437

Insured Tel No. : HP: +65-90408967

Make / Model : VOLKSWAGEN SHARAN

Excess Sec II : S\$

D.O.A : 03/08/2019 14:55

Place of Accident : ECP TOWARDS CHANGI AIRPORT

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SMG 8242A

INSRS:  
WSP: Massive  
Tel: Trading  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

| Date/ Time |                                                  | STAGE                                    | DATE / PIC |
|------------|--------------------------------------------------|------------------------------------------|------------|
|            | SMG 8242A - X                                    | Non-Reporting Itr (1st):                 |            |
|            | SKP 218A - CS/GAI19012696/R1vf3e2; DOA: 01/07/19 | Non-Reporting Itr (2nd):                 |            |
|            |                                                  | Non-Reporting Itr (Final):               |            |
|            |                                                  | Notification Itr (if non-pickup):        |            |
|            |                                                  | Call OI: EMAIL 01/10/19                  |            |
|            |                                                  | After call Itr to OE                     |            |
| 10/10/19   | FILE PASS TO TYPIST TO PREPARE REPORT.           | Documentation Check List: Handler Typist |            |
|            |                                                  | Notification Itr (if non-pickup)         |            |
|            |                                                  | After call Itr to OE                     |            |
|            |                                                  | Authorisation To Act:                    |            |
|            |                                                  | Release Voucher:                         |            |
|            |                                                  | Final Repair Bill:                       |            |
|            |                                                  | Car Rental Invoice:                      |            |
|            |                                                  | Towing Invoice                           |            |
|            |                                                  | LTA / GIA :                              |            |
|            |                                                  | Medical Bill:                            |            |
|            |                                                  | PIR:                                     |            |
|            |                                                  | Mandate/Reject Instruction:              |            |
|            |                                                  | LOD                                      |            |
|            |                                                  | Payment Breakdown Form:                  |            |
|            |                                                  | Post-Repair Photos:                      |            |
|            |                                                  | Others:                                  |            |

|                                                                                                                                                      |                                             |                           |                        |                                                                         |                               |
|------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|---------------------------|------------------------|-------------------------------------------------------------------------|-------------------------------|
| <b>PRELIMINARY ADVICE</b> Date/Time:                                                                                                                 |                                             | Sent By:                  |                        | Confirm by: KSC                                                         |                               |
| <b>FINALIZATION</b> Date/Time: 15/08/19                                                                                                              |                                             | Confirm with: Anthony     |                        | Confirm by: KSC                                                         |                               |
| Repair Cost:                                                                                                                                         | S\$ 21,350                                  | ( 18 days) Reduction:     | 30 %                   | Email <input checked="" type="checkbox"/>                               | Call <input type="checkbox"/> |
| <b>FINAL SETTLEMENT</b> Date/Time: 06/12/19                                                                                                          |                                             | Confirm with: Anthony     |                        | Email <input checked="" type="checkbox"/> Call <input type="checkbox"/> |                               |
| Final Liability:                                                                                                                                     | % 100 (Agreed / Assessed) BOLA S/N No. : 37 | If NO or B 28, Ass. Lia : |                        |                                                                         |                               |
| Repair Cost:                                                                                                                                         | S\$ 21,350.00                               | 01. FINAL ENDORSE TP      |                        |                                                                         |                               |
| Loss of Rental (LOR):                                                                                                                                | S\$ - ( days)                               |                           |                        |                                                                         |                               |
| Loss of Use (LOU):                                                                                                                                   | S\$ 1,520.00 (S\$ 60 x 25 days)             |                           |                        |                                                                         |                               |
| Loss of Income (LOI):                                                                                                                                | S\$ - (S\$ x days)                          |                           |                        |                                                                         |                               |
| LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> | [Tick only one]                             |                           |                        |                                                                         |                               |
| GIA/LTA Search                                                                                                                                       | S\$ -                                       |                           |                        |                                                                         |                               |
| Medical:                                                                                                                                             | S\$ -                                       |                           |                        |                                                                         |                               |
| Disbursement:                                                                                                                                        | S\$ - (e.g. Tow/Independent)                |                           |                        |                                                                         |                               |
| Legal Cost                                                                                                                                           | S\$ -                                       |                           |                        |                                                                         |                               |
| <b>Total:</b>                                                                                                                                        | S\$ 22,870.00                               | <b>Global Sum S\$:</b>    |                        |                                                                         |                               |
| <b>FINAL PAYMENT</b> Date/Time: 06/12/19                                                                                                             |                                             | Confirm with: Anthony     |                        | Email <input checked="" type="checkbox"/> Call <input type="checkbox"/> |                               |
| Payee 1:                                                                                                                                             | S\$ 22,870.00                               | Name 1:                   | MASSIVE TRADING & AUTO |                                                                         |                               |
| Payee 2: (Strike if N.A.)                                                                                                                            | S\$                                         | Name 2:                   |                        |                                                                         |                               |
| Payee 3: (Strike if N.A.)                                                                                                                            | S\$                                         | Name 3:                   |                        |                                                                         |                               |

COPY SENT 21/12/19

22/03/2019

ASS. REC. BY:

REF: CS/AIG/19013645/K f3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Hor Vinrul

of

AIG

Date/Time: 3.8.19 2.32pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMG 8242A

Insured: SKP 218A

at Workshop m/s MASSIVE Trading &amp; Auto

Tel: 91082728

of Bldg 5038 Amt Industrial Park ) #01-405

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 3.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5.8.19 2.43p.m

Person Contacted: Anthony

Vehicle IN OUT

| Date/Time | Action/Instruction (✓) Estimate                                                                         |
|-----------|---------------------------------------------------------------------------------------------------------|
|           | SMG 8242A ✓                                                                                             |
|           | SKP 218A - CS/GA/19013645/R14321 RGA - 01/07/2019                                                       |
| 27/9/19   | According to Asher, the wksp agreed to do 'DS' & will withdraw TP lawyer. Put Asher name as BS handler. |
|           |                                                                                                         |
|           |                                                                                                         |

ASS. REC. BY:

REF: MG/Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Merrine

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 872k

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 18 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMG-82421 Yr Regn: 12.18Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or TrMake: Honda Fit c.c. 1496Colour: M.D. Blue A/C: Insured / Std / NI / NASp. Reading: 22447 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GP 5 . 1334747Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrakes: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 3/8/19

Survey held at

Des. of Damages: Frt Rear O/S / N/S / UIC / Rooftop orThe UIC / ~~Chassis frame~~ Body Structure affected due to collision. ✓

Date / Time

Action / Instruction

1/ File pass to  
5/8 Car jamm, unable to escape

46: 22.350 (BSP: 9.337A) 30%

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1) Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Blok 5038 #01-405 Ang Mo Kio Industrial Park 2 Singapore 569541  
H/p 91082728

Fax : 64816131

Dong Jinmei  
90 Edgedale Plains  
#16-22  
Singapore 828685.

Vehicle No : SMG 8242 A  
Make : Honda Fit  
Year : 2018

Not Withstand  
11 Lys 82,350k  
Phenyl After Pain  
18 day

| Qty | Description | Unit Price | Amount |
|-----|-------------|------------|--------|
|-----|-------------|------------|--------|

### Estimate Cost Of Repair

| QTY   | DESCRIPTION                                  | UNIT PRICE | TOTAL PRICE | REMARKS |
|-------|----------------------------------------------|------------|-------------|---------|
| 1 pc  | Rear tail-gate assy                          | \$881.30   | \$881.30    |         |
| 1 pc  | Rear tail-gate glass moulding                | \$105.10   | \$105.10    |         |
| 2 pcs | Rear tail-gate lamp                          | \$475.30   | \$950.60    |         |
| 1 pc  | Rear tail-gate emblem " FIT "                | \$45.10    | \$45.10     |         |
| 1 pc  | Rear tail-gate emblem " Hybrid "             | \$55.20    | \$55.20     |         |
| 1 pc  | Rear tail-gate chrome handle                 | \$219.70   | \$219.70    |         |
| 1 pc  | Rear tail-gate inner lock sensor             | \$185.70   | \$185.70    |         |
| 1 pc  | Rear tail-gate inner lock                    | \$195.10   | \$195.10    |         |
| 1 pc  | Rear tail-gate inner trim board              | \$152.60   | \$152.60    |         |
| 2 pcs | Rear no plate lamp                           | \$55.10    | \$110.20    |         |
| 1 pc  | Rear tail-gate wiper motor                   | \$287.10   | \$287.10    |         |
| 2 pcs | Rear fender                                  | \$685.60   | \$1,371.20  |         |
| 2 pcs | Rear fender inner trim board                 | \$205.10   | \$410.20    |         |
| 1 pc  | Rear n/s fender air vent                     | \$57.10    | \$57.10     |         |
| 1 pc  | Rear end panel                               | \$384.60   | \$384.60    |         |
| 1 pc  | Rear end panel inner garnish                 | \$191.10   | \$191.10    |         |
| 1 pc  | Rear boot rubber                             | \$103.40   | \$103.40    |         |
| 1 pc  | Rear spare tyre panel                        | \$1,072.50 | \$1,072.50  |         |
| 1 pc  | Rear spare tyre panel top cover board        | \$215.90   | \$215.90    |         |
| 2 pcs | Rear tail-lamp assy                          | \$483.80   | \$967.70    |         |
| 1 pc  | Rear n/s tail-lamp panel                     | \$108.10   | \$108.10    |         |
| 1 pc  | Rear bumper                                  | \$791.30   | \$791.30    |         |
| 1 pc  | Rear bumper lower garnish ( centre portion ) | \$95.10    | \$95.10     |         |
| 2 pcs | Rear bumper reflector garnish                | \$115.20   | \$230.40    |         |
| 2 pcs | Rear bumper side retainer                    | \$45.10    | \$90.20     |         |
| 2 pcs | Rear bumper sponge                           | \$75.10    | \$150.20    |         |
| 1 pc  | Rear antenna                                 | \$95.60    | \$95.60     |         |
| 1 pc  | Rear buzzer                                  | \$92.10    | \$92.10     |         |
| 1 pc  | Rear axle assy                               | \$1,100.80 | \$1,100.80  |         |
| 2 pcs | Rear shock absorber                          | \$247.10   | \$494.20    |         |
| 2 pcs | Rear hub assy                                | \$326.90   | \$653.80    |         |
|       | balance c/h                                  |            | \$11,788.10 |         |

SMG 8242 A

|       |                                         |
|-------|-----------------------------------------|
| 1 pc  | Rear exhaust silencer                   |
| 1 pc  | Rear exhaust silencer heat shield       |
| 1 pc  | Hybrid battery                          |
| 1 pc  | Hybrid battery top chrome cover         |
| 1 pc  | Hybrid battery fan discharge motor assy |
| 1 pc  | Hybrid battery air discharge hose       |
| 1 pc  | Hybrid battery control unit             |
| 1 pc  | Hybrid battery tray                     |
| 1 pc  | Rear towing hook                        |
| 2 pcs | Rear reverse sensor                     |

} photo

price error

|                |                     |           |
|----------------|---------------------|-----------|
| balance b/f    | \$11,788.10         | 10 992.30 |
| B <sub>1</sub> | \$495.30            | —         |
| B <sub>2</sub> | \$45.10             | —         |
| D <sub>1</sub> | \$12,985.60         | —         |
| B <sub>2</sub> | \$299.70            | —         |
| D <sub>1</sub> | <del>\$800.00</del> | —         |
| D <sub>1</sub> | \$499.20            | —         |
| D <sub>1</sub> | \$1,912.30          | —         |
| D <sub>1</sub> | \$256.10            | —         |
| D <sub>1</sub> | \$115.20            | X         |
| \$287.90       | \$575.80            | —         |
|                | \$29,521.80         | 28,926.60 |
| Less 20 %      | \$5,904.30          | 5,785.32  |
|                | \$23,617.44         | 23,141.28 |

S Nett

|        |                         |   |
|--------|-------------------------|---|
| 1 pc   | Rear reverse camera     | ? |
| 1 pc   | Rear no plate           | — |
| 1 pc   | Rear no plate holder    | — |
| 1 pc   | Rear windscreen sealant | — |
| 20 pcs | Rear bumper clip        | — |

|    |          |        |
|----|----------|--------|
| re | \$300.00 | X      |
| re | \$45.00  | 4.50   |
| re | \$45.00  | 4.50   |
| re | \$55.00  | 40.10  |
| re | \$60.00  | —      |
|    | \$505.00 | 205.00 |

Labour Charges

|                                                                                      |                     |         |
|--------------------------------------------------------------------------------------|---------------------|---------|
| Remove/renew the above parts including knocking, welding & cutting.                  | \$2,000.00          | 1600    |
| To putty & spray paint rear accident affected portion.                               | \$1,600.00          | 1400    |
| Check/reconnect wiring.                                                              | \$45.00             | 30      |
| To spray anti rust on accident affected portion.                                     | \$200.00            | 100     |
| Remove/refit rear tail-gate wiper motor and lock mechanism and rear boot upholstery. | \$150.00            | 20 60   |
| Remove/renew rear exhaust silencer                                                   | \$120.00            | 60      |
| Remove/refit rear windscreen to facilitate repair.                                   | \$120.00            | —       |
| Remove/renew rear hybrid battery including diagnostic check                          | <del>\$550.00</del> | —       |
| Four wheel trolley towing                                                            | \$150.00            | 120     |
| Remove/renew rear axle and undercarriages                                            | \$550.00            | 400 240 |
| Check and realign wheel alignment                                                    | \$80.00             | 60      |
| Remove/renew hybrid battery including diagnostic check and programming               | <del>\$800.00</del> | 600     |
|                                                                                      | \$30,287.44         | 4690.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 278D

**Vehicle Details**

Vehicle No.: SMG8242A  
Vehicle to be Exported: No  
Intended Deregistration Date: 06 Aug 2019  
Vehicle Make: HONDA  
Vehicle Model: FIT HYBRID 1.5F AUTO  
Primary Colour: Blue  
Manufacturing Year: 2018  
Engine No.: LEB1441754  
Chassis No.: GP51334747  
Maximum Power Output: 101.0 kW (135 bhp)  
Open Market Value: \$19,233.00  
Original Registration Date: 31 Dec 2018  
First Registration Date: 31 Dec 2018  
Transfer Count: 0  
Actual ARF Paid: \$9,233.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 30 Dec 2028  
PARF Rebate Amount: \$6,924.00

**Intended COE Rebate Details**

COE Expiry Date: 30 Dec 2028  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$31,101.00  
COE Rebate Amount: \$29,228.00  
**Total Rebate Amount: \$36,152.00**

The information contained herein is correct as at 06 Aug 2019

OK

# Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541  
H/p 91082728

Fax : 64816131

Dong Jinmei  
90 Edgedale Plains  
#16-22  
Singapore 828685

*Not Notion*  
*1/1 Sup & ?*  
*Resurvey After Paint*

Vehicle No : SMG 8242 A  
Make : Honda Fit  
Year : 2018

| Qty                            | Description                                             | Unit Price  | Amount       |
|--------------------------------|---------------------------------------------------------|-------------|--------------|
| <u>Estimate Cost Of Repair</u> |                                                         |             |              |
| 1 pc                           | Rear tail-gate assy                                     |             | \$881.30 ✓   |
| 1 pc                           | Rear tail-gate glass moulding                           |             | \$105.10 ✓   |
| 2 pcs                          | Rear tail-gate lamp <i>L/H crack R/H ? photo N/S cm</i> | \$475.30    | \$950.60     |
| 1 pc                           | Rear tail-gate emblem " FIT "                           |             | \$45.10 ✓    |
| 1 pc                           | Rear tail-gate emblem " Hybrid "                        |             | \$55.20 ✓    |
| 1 pc                           | Rear tail-gate chrome handle                            |             | \$219.70 ✓   |
| 1 pc                           | Rear tail-gate inner lock sensor ?                      |             | \$185.70 ?   |
| 1 pc                           | Rear tail-gate inner lock                               |             | \$195.10 ✓   |
| 1 pc                           | Rear tail-gate inner trim board ? photo                 |             | \$152.60 ✓   |
| 2 pcs                          | Rear no plate lamp ?                                    | \$55.10     | \$110.20 ?   |
| 1 pc                           | Rear tail-gate wiper motor ?                            |             | \$287.10 ?   |
| 2 pcs                          | Rear fender <i>L/H bent N/S Bu</i>                      | \$685.60    | \$1,371.20 ✓ |
| 2 pcs                          | Rear fender inner trim board ? photo                    | \$205.10    | \$410.20 ?   |
| 1 pc                           | Rear n/s fender air vent                                |             | \$57.10 ✓    |
| 1 pc                           | Rear end panel                                          |             | \$384.60 ✓   |
| 1 pc                           | Rear end panel inner garnish                            |             | \$191.10 ✓   |
| 1 pc                           | Rear boot rubber                                        |             | \$103.40 ✓   |
| 1 pc                           | Rear spare tyre panel                                   |             | \$1,072.50 ✓ |
| 1 pc                           | Rear spare tyre panel top cover board                   |             | \$215.90 ✓   |
| 2 pcs                          | Rear tail-lamp assy <i>L/H crack R/H ? photo N/S cm</i> | \$483.80    | \$967.70     |
| 1 pc                           | Rear n/s tail-lamp panel                                |             | \$108.10 ✓   |
| 1 pc                           | Rear bumper                                             |             | \$791.30 ✓   |
| 1 pc                           | Rear bumper lower garnish ( centre portion )            |             | \$95.10 ✓    |
| 2 pcs                          | Rear bumper reflector garnish                           | \$115.20    | \$230.40 ✓   |
| 2 pcs                          | Rear bumper side retainer                               | \$45.10     | \$90.20 ✓    |
| 2 pcs                          | Rear bumper sponge                                      |             | \$75.10 ✓    |
| 1 pc                           | Rear antenna                                            |             | \$95.60 ✓    |
| 1 pc                           | Rear buzzer                                             |             | \$92.10 ✓    |
| 1 pc                           | Rear axle assy                                          |             | \$1,100.80 ✓ |
| 2 pcs                          | Rear shock absorber                                     | \$247.10    | \$494.20 ✓   |
| 2 pcs                          | Rear hub assy                                           | \$326.90    | \$653.80 ✓   |
|                                |                                                         | balance c/f | \$11,788.10  |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMG 8242 A

|       |                                         |
|-------|-----------------------------------------|
| 1 pc  | Rear exhaust silencer                   |
| 1 pc  | Rear exhaust silencer heat shield       |
| 1 pc  | Hybrid battery                          |
| 1 pc  | Hybrid battery top chrome cover         |
| 1 pc  | Hybrid battery fan discharge motor assy |
| 1 pc  | Hybrid battery air discharge hose       |
| 1 pc  | Hybrid battery control unit             |
| 1 pc  | Hybrid battery tray                     |
| 1 pc  | Rear towing hook                        |
| 2 pcs | Rear reverse sensor                     |

} photo

|             |                      |
|-------------|----------------------|
| balance b/f | \$11,788.10          |
|             | <i>A1</i> \$495.30 / |
|             | <i>A1</i> \$45.10 /  |
|             | \$12,985.60 /        |
|             | \$299.70 /           |
|             | \$599.40 /           |
|             | \$449.20 /           |
|             | \$1,912.30 /         |
|             | \$256.10 /           |
|             | \$115.20 /           |
| \$287.90    | \$575.80 /           |
|             | \$29,521.80          |
| Less 20 %   | \$5,904.30           |
|             | \$23,617.44          |

S Nett

|        |                         |   |
|--------|-------------------------|---|
| 1 pc   | Rear reverse camera     | ? |
| 1 pc   | Rear no plate           | / |
| 1 pc   | Rear no plate holder    | / |
| 1 pc   | Rear windscreen sealant | / |
| 20 pcs | Rear bumper clip        | / |

|        |                   |          |
|--------|-------------------|----------|
|        | \$300.00          | ?        |
|        | <i>Ad</i> \$45.00 | } \$5.00 |
|        | \$45.00           |          |
|        | <i>M</i> \$55.00  | 60.00    |
| \$3.00 | <i>M</i> \$80.00  | /        |
|        | \$505.00          |          |

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$2,000.00 *1800*

To putty & spray paint rear accident affected portion.

\$1,600.00 *1400*

Check/reconnect wiring.

\$45.00 *200*

To spray anti rust on accident affected portion.

\$200.00 *1200*

Remove/refit rear tail-gate wiper motor and lock mechanism and rear boot upholstery.

\$150.00 *1200*

Remove/renew rear exhaust silencer

\$120.00 *600*

Remove/refit rear windscreen to facilitate repair.

\$120.00 ✓

Remove/renew rear hybrid battery including diagnostic check

\$550.00 *3000*

Four wheel troller towing

(Bill) \$150.00 ?

Remove/renew rear axle and undercarriages

\$550.00 *2200*

Check and realign wheel alignment

\$80.00 *600*

Remove/renew hybrid battery including diagnostic check and programming

\$600.00 ?  
\$30,287.44



张景祥大律師樓  
(律師兼公証人及宣誓官)

# Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098  
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676 / 5688

Email: KSTEOCO@singnet.com.sg  
(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

PDX Intercompany Exchange Pte Ltd



010008762426

FROM TEO KENG SIANG LLC

PDX Box No. 8902

Our Ref : TKSF/M492-ACC-42326.19/sf (mc)  
Your Ref : SKP 218 A  
Date : 5 August 2019

Secretary in charge: Janice

Tel : 6333 4222 (ext 60)  
Fax : 6333 5676 / 6333 5688  
Email : janice.kee@ksteoptr.com

To: AIG Asia Pacific Insurance Pte. Ltd  
AIG Building  
78 Shenton Way  
#07-16 Singapore 079120  
Attn: Motor Claims Dept

**WITHOUT PREJUDICE**  
**BY PDX# 8181 & FAX 6835 7416 ONLY**

Cc: Chong Leigh Hsiang (Owner & Driver)  
62 Greenleaf View  
Singapore 279301

**BY POST ONLY**

Dear Sirs

**RE: ACCIDENT INVOLVING SMG 8242 A / SKP 218 A ON 3/8/19 ALONG ECP TOWARDS FORT ROAD**

We are instructed by **Dong JinMei** to notify you of a road traffic accident on **3/8/19** at about **15:00 hours** at **ALONG ECP TOWARDS FORT ROAD** involving our client's vehicle registration number **SMG 8242 A** and vehicle registration number **SKP 218 A** driven by you at the material time. A copy of our client's Singapore accident statement is enclosed. Kindly let us have a copy your Singapore accident statement report on an urgent basis.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle **SMG 8242 A** is now at the following workshop:-

**Massive Trading & Auto**  
Blk 5038 Ang Mo Kio Industrial Park 2  
#01-405  
Singapore 569541  
Contact: 9108 2728 Anthony

Yours faithfully,

M/s Teo Keng Siang LLC  
encs

**\*\*Survey was conducted by:-**

Name of Surveyor:

Date of Survey:

Time of Survey:

Signature

Teo Keng Siang  
LL.M(Singapore),  
LL.B (Hons) (Singapore)

Wong Yung Sheng, Kenneth  
LL.B (Hons) University of Bristol

## PRE-REPAIR INSPECTION REQUEST – SKP218A vs SKP218A (OI) on D.O.A.: 03/08/2019

From: - Hor, Yinnul  
 To: 'assignments@lkkauto.com'; Admin A (admin-a@lkkauto.com)  
 Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairidina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divy  
 Sent: Monday, 5 August 2019 2:32:24 PM  
 Attachments: 20190805110356643.pdf; 20190805110356643.pdf

Hi,

Please refer to the enclosed request from **Teo Keng Siang LLC**.  
 Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.  
 Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Yinnul)  
 AIG  
 FNOL, 4quarter I  
 Singapore FNOL | Claims Operations – Auto

Yinnul.Hor@aig.com | www.aig.sg

From: Janice Kee [mailto:janice.kee@kstoplr.com]  
 Sent: Monday, August 05, 2019 12:38 PM  
 To: Hor, Yinnul  
 Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairidina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashri; Tong, Waheini; Anthony Cheong  
 Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKP218A AND SMG8242A ON 03/08/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir

Our client has agree to the usage of Mr Kenneth Kong from LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage Mr Kenneth Kong from LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you

Regards,  
 Janice Kee  
 c/o Teo Keng Siang LLC  
 111 North Bridge Road,  
 #29-07/08 Peninsula Plaza,  
 Singapore 179098  
 Tel: 6333 4222 Fax: 6333 5676

On Mon, Aug 5, 2019 at 11:58 AM Hor, Yinnul <Yinnul.Hor@aig.com> wrote:



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如果要阅读此信息，请打开附件。

இந்த மின்னஞ்சல் பாதுகாக்கப்பட்ட செய்தி ஆகும். அதைப் படிக்க முன் இதைத் திறக்க வேண்டும்.

이것은 안전하고 암호화된 메세지입니다. 그것을 읽으려면 첨부파일을 열어야 합니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-08-12 11:57 +08 to read your message.  
 After that, open the attachment.

[More info](#)

Disclaimer: This email and its contents are confidential and intended solely for the use of the individual named. Please notify the sender if a security-related disclosure is made or simply delete it.

Secured by Privileged Communication Copyright © 2008-2017 Priv@com, Inc. All rights reserved.

#### IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul Hor@aiig.com

To: janice.kee@kateoptr.com

Cc: Andy-SY.Fong@aiig.com; Lee-

Ying.Chin@aiig.com; NoorManessa.AbuKassim@aiig.com; Syazairidina.Azlan@aiig.com; yokeeshi.chen@aiig.com; ShengYang.Lim@aiig.com; Aashweenjeetkaur.Mithoosingh@aiig.com; Theerthan.Parthiba

Subject: aigenoypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKP218A AND SMG8242A ON 03/08/2019

Date: Mon, 5 Aug 2019 03:57:42 +0000

Without Prejudice

Your Reference : TK5F/M492-ACC-42326.19/sf)

Our Reference : SKP218A

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

| Name of Surveyor         | Company Name                           |
|--------------------------|----------------------------------------|
| AIG In House Surveyor    | AIG Asia Pacific Insurance Pte Ltd     |
| Lawrence Ng Chun Kae     | Priority Services                      |
| Jeffrey Ong Leng Kiat    | Priority Services                      |
| Jimmy Lee                | Priority Services                      |
| EC Looi                  | Automobile Inspection Services Pte Ltd |
| Pang Kiah Kaen (Frankie) | Formteam Adjusters Pte Ltd             |
| Ng You Han               | Formteam Adjusters Pte Ltd             |
| Seon HanXin (Gary)       | Formteam Adjusters Pte Ltd             |
| Chow Bo Xiong            | Formteam Adjusters Pte Ltd             |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd             |
| Kalvin Ang               | LKK Auto Consultants Pte Ltd           |
| Xing Guo Qiang           | LKK Auto Consultants Pte Ltd           |
| Marcus Chua              | LKK Auto Consultants Pte Ltd           |
| Mohamad Taufikh          | LKK Auto Consultants Pte Ltd           |
| Adrian Ling              | LKK Auto Consultants Pte Ltd           |
| Mohammed Ranaul          | LKK Auto Consultants Pte Ltd           |
| Kenneth Kung             | LKK Auto Consultants Pte Ltd           |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hui Yim Rul (Vivienne)

AIG

PNOL, 4000001

Singapore PNOL | Claims Operations – Auto

[Yinnul.Hor@aiig.com](mailto:Yinnul.Hor@aiig.com) | [www.aiig.sg](http://www.aiig.sg)

From: Janice Kee [mailto:janice.kee@kateoptr.com]

Sent: Monday, August 05, 2019 11:06 AM

To: Hor, Yinnul; AIG SGP, Claims-Survey

Cc: Anthony Cheong

Subject: [EXTERNAL] Pre Repair Survey for SMG 8242 A (Your Ref: SKP 218 A Our Ref: TK5F/M492-ACC-42326.19/sf)

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

We attach herewith our Pre-repair survey letter for your attention.

Kindly let us have the surveyor list for our attention.

Thank you

Regards,

Janice Kee

c/o Teo Keng Siang LLC

111 North Bridge Road,

#29-07/08 Peninsula Plaza,

Singapore 179098

Tel: 6333 4222 Fax: 6333 5676



## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Tuesday, 1 October 2019 11:26 AM  
**To:** Anthony Cheong  
**Subject:** Accident Involving SMG 8242A & SKP 218A on 03/08/2019

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear Sir/Madam,

**Accident Involving SMG 8242A & SKP 218A on 03/08/2019**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Anthony Cheong <[cheonganthony@yahoo.com.sg](mailto:cheonganthony@yahoo.com.sg)>  
**Sent:** Wednesday, 25 September 2019 11:44 AM  
**To:** Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>  
**Subject:** Fw: SMG8242A

Hi Asher

Enclosed video footage for above

Thanks

Anthony

## Claim Audit

| AUDIT TRAIL |                   |                                  |                                                                                                                                                  |                                   |
|-------------|-------------------|----------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|
| No.         | On                | Audit                            | Remarks                                                                                                                                          | By                                |
| 1           | 05 Aug 2019 15:01 | <b>Cim Dtl Modified</b>          | Claimant's Name: -> DONG JINMEI. Claimant's ID: -> S7461278D.                                                                                    | [A] LEE SU THING                  |
| 2           | 05 Aug 2019 15:01 | <b>Cim Veh Model Changed</b>     | (202188) HONDA FIT 1.3 (A).                                                                                                                      | [A] LEE SU THING                  |
| 3           | 05 Aug 2019 15:01 | <b>Cim Created</b>               | Reg No: SMG8242A. Acct Date: 2019/08/03. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: Massive Trading & Auto () | [A] LEE SU THING                  |
| 4           | 05 Aug 2019 15:01 | <b>Adj Co Assigned</b>           | LKK Auto Consultants Pte Ltd (HQ):                                                                                                               | [A] LEE SU THING                  |
| 5           | 05 Aug 2019 15:01 | <b>Adj Next Rpt Changed</b>      | Next Rpt:Final Rpt.Due Date:2019/08/16                                                                                                           | [A] LEE SU THING                  |
| 6           | 05 Aug 2019 15:01 | <b>Adj Mandate Set</b>           | Approved:0.00,Reinsp:Adj decides.                                                                                                                | [A] LEE SU THING                  |
| 7           | 05 Aug 2019 15:01 | <b>Cim Ins Co Changed</b>        | [200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)                                    | [I] Merimen Administrator         |
| 8           | 05 Aug 2019 15:01 | <b>Adj Adjuster Assigned</b>     | [None] -> KENNETH KONG                                                                                                                           | [A] LEE SU THING                  |
| 9           | 07 Aug 2019 16:42 | <b>Cim Registration Modified</b> | Acct Time:15:00:00-> 14:00:00.                                                                                                                   | [I] AIG OneClaim Integration User |
| 10          | 01 Oct 2019 15:38 | <b>Label Added</b>               | (23):Express.                                                                                                                                    | [A] Asher Sng Rong Yi             |
| 11          | 03 Dec 2019 13:44 | <b>Video Downloaded</b>          | Downloaded TP VIDEO                                                                                                                              | [I] Loh, Chee-Heng                |
| 12          | 04 Dec 2019 11:11 | <b>Adj Rpt Initiated</b>         |                                                                                                                                                  | [A] JOANNE LEE KHANG MIN          |
| 13          | 04 Dec 2019 11:11 | <b>Cim Dtl Modified</b>          | JPJ Reg. Date: -> 2018/12/31.                                                                                                                    | [A] JOANNE LEE KHANG MIN          |
| 14          | 04 Dec 2019 11:11 | <b>Cim Details Notified</b>      |                                                                                                                                                  | [A] JOANNE LEE KHANG MIN          |
| 15          | 04 Dec 2019 11:53 | <b>Adj Mandate Request</b>       | Cur.Reg:22790.00:LIABILITY: 100% B:27 OI REAR ENDED TP                                                                                           | [A] Asher Sng Rong Yi             |

Date From



Date To



Audit Type None



Go

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

| Bill Ref No | Bill Date            | Bill Type             | Acc Type | Acc Name                             | Co Name (SUBJECT)                              | Rpt 1    | Rpt 2             | Amount |
|-------------|----------------------|-----------------------|----------|--------------------------------------|------------------------------------------------|----------|-------------------|--------|
| 2236497     | 05 Aug 2019 15:06:06 | TP Case (Insurer)     | Motor    | LKK Auto Consultants Pte Ltd         | AIG Asia Pacific Insurance Pte. Ltd. (Express) | SMG8242A | SKP218A           | 11.77  |
| 2341430     | 11 Nov 2019 14:33:18 | Video Upload          | Motor    | AIG Asia Pacific Insurance Pte. Ltd. | AIG Asia Pacific Insurance Pte. Ltd. (SG)      | SMG8242A | Asher Sng Rong Yi | xx.xx  |
| 2366879     | 04 Dec 2019 11:11:53 | OD/TP Case (Adjuster) | Motor    | LKK Auto Consultants Pte Ltd         | LKK Auto Consultants Pte Ltd (HQ)              | SMG8242A | SKP218A           | 11.77  |

12/6/2019

Merimen e-Claims

## Print Received Message

This mail is associated with :

**\*SMG8242A (5346362561SG)**  
**[SKP218A]**  
TP  
DONG JINMEI  
Aug 3 2019 2:00PM  
[Chong Leigh Hsiang]  
Massive Trading & Auto

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 05/12/2019 08:30 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$22670.00) - SMG8242A - Claim Handler: Loh, Chee-Heng

Approved:22670.00:COR \$21,350 LOU \$1,320 (22 days x \$60)



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

## CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                         | Adj Rpt                                               | Adj Submitted                                   | Ins Auth'd | Status                                                          |
|------|-----------------------------------------|---------------|------------------------------------------------------|-------------------------------------------------------|-------------------------------------------------|------------|-----------------------------------------------------------------|
| Main | 05 Aug 2019<br><a href="#">Edit Reg</a> |               | 03 Aug 2019<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$21,350.00</b><br><a href="#">Edit Estimates</a> | <b>S\$21,350.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                                                                              | Reference                                                                                                                               | Claim Details          | Documents                                                                  | Show All |         |             |              |            |       |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|------------------------|----------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>                                                                                                                                           |                                                                                                                                         |                        |                                                                            |          |         |             |              |            |       |
| Insured:                                                                                                                                                                                                                          | <b>Chong Leigh Hsiang</b> , ID: S7470054C                                                                                               |                        |                                                                            |          |         |             |              |            |       |
| Main Claimant:                                                                                                                                                                                                                    | <b>DONG JINMEI</b> , ID: S7461278D                                                                                                      |                        |                                                                            |          |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                                                                                                                                 | <b>SMGB242A</b>                                                                                                                         | Date of Loss:          | 03/08/2019 14:00 - :59<br>[7 Months and 3 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:                                                                                                                                                                                                                       | <b>TP / 5346362561SG</b>                                                                                                                | Policy/Cover Note No.: | 1800138437 (Comprehensive)                                                 |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                                                                                                                                       | <b>SKP218A</b>                                                                                                                          | Policy No. (Claimant): | 5106687339                                                                 |          |         |             |              |            |       |
|                                                                                                                                                                                                                                   |                                                                                                                                         | Excess:                |                                                                            |          |         |             |              |            |       |
| Repairer:                                                                                                                                                                                                                         | <b>Massive Trading &amp; Auto ( )</b> Blk 503B #01-405, Ang Mo Kio Industrial Pk 2, 569541 Ang Mo Kio - Tel:                            |                        |                                                                            |          |         |             |              |            |       |
| Handling Insurer:                                                                                                                                                                                                                 | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loh, Chee-Heng</b> ] Chee-Heng.Loh@aig.com |                        |                                                                            |          |         |             |              |            |       |
| Claimant's Insurer:                                                                                                                                                                                                               | <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:                                                                               |                        |                                                                            |          |         |             |              |            |       |
| Adjuster:                                                                                                                                                                                                                         | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 16/08/2019]          |                        |                                                                            |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                                                                     |                                                                                                                                         |                        |                                                                            |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (05/12/2019): Alert - Adj Mandate Approved (S\$22670.00) - SMGB242A - Claim Handler: Loh, Chee-...</li> <li>AIG_SG (06/08/2019): Request To Upload TP GIA Report</li> </ul> |                                                                                                                                         |                        |                                                                            |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>                                                     |                                                                                                                                         |                        |                                                                            |          |         |             |              |            |       |
| Due Date                                                                                                                                                                                                                          | Priority                                                                                                                                | Type                   | Task Group                                                                 | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                                                                       |                                                                                                                                         |                        |                                                                            |          |         |             |              |            |       |

## Claim Documents

\*SMG8242A (5346362561SG)  
[SKP218A]  
TP  
DONG JINMEI  
Aug 3 2019 2:00PM  
[Chong Leigh Hsiang]  
Massive Trading & Auto

|                                  |                 |                                                    |                                    |                              |                                                                                                |                                                                                 |  |
|----------------------------------|-----------------|----------------------------------------------------|------------------------------------|------------------------------|------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|--|
| <a href="#">Upload Documents</a> |                 | <a href="#">Upload Photos</a>                      | <a href="#">Compose New Letter</a> | <a href="#">Upload Video</a> | <a href="#">Upload Audio</a>                                                                   | <b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>    |  |
| <b>Video</b>                     |                 |                                                    |                                    |                              |                                                                                                | 1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> |  |
| No                               | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                  |                                    |                              | Thumbnail                                                                                      | Print                                                                           |  |
| 1                                | 11/11/19 14:33  | TP VIDEO                                           |                                    |                              |  Load MP4   |                                                                                 |  |
| <b>Letters/Correspondences</b>   |                 |                                                    |                                    |                              |                                                                                                | 1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> |  |
| No                               | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                  |                                    |                              | Thumbnail                                                                                      | Print                                                                           |  |
| 1                                | (Draft)         | Third Party Express Settlement - Payment Breakdown |                                    |                              |  Edit       |                                                                                 |  |
| <b>Photos/Images</b>             |                 |                                                    |                                    |                              |                                                                                                | 3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> |  |
| No                               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                  |                                    |                              | Thumbnail                                                                                      | Print                                                                           |  |
| 1                                | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG   | <input checked="" type="checkbox"/>                                             |  |
| 2                                | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG   | <input checked="" type="checkbox"/>                                             |  |
| 3                                | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG   | <input checked="" type="checkbox"/>                                             |  |
| 4                                | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG   | <input checked="" type="checkbox"/>                                             |  |
| 5                                | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG  | <input checked="" type="checkbox"/>                                             |  |
| 6                                | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 7                                | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 8                                | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 9                                | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 10                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 11                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 12                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 13                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 14                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 15                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 16                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 17                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 18                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 19                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 20                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 21                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 22                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 23                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 24                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 25                               | 10/10/19 14:14  | Chassis Number                                     |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 26                               | 10/10/19 14:14  | General View                                       |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 27                               | 10/10/19 14:14  | Odometer Reading                                   |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 28                               | 10/10/19 14:15  | Reinspection Photo                                 |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 29                               | 10/10/19 14:15  | Reinspection Photo                                 |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 30                               | 10/10/19 14:15  | Reinspection Photo                                 |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 31                               | 10/10/19 14:15  | Reinspection Photo                                 |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 32                               | 10/10/19 14:15  | Reinspection Photo                                 |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 33                               | 10/10/19 14:15  | Reinspection Photo                                 |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 34                               | 10/10/19 14:15  | Reinspection Photo                                 |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 35                               | 10/10/19 14:15  | Reinspection Photo                                 |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |
| 36                               | 10/10/19 14:15  | Reinspection Photo                                 |                                    |                              |  Load JPG | <input checked="" type="checkbox"/>                                             |  |

| Video         |                 |                                           |  | 1 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-------------------------------------------|--|------------|-------------------------------------|
| No            | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)         |  | Thumbnail  | Print                               |
| 37            | 10/10/19 14:15  | Reinspection Photo                        |  | Load JPG   | <input checked="" type="checkbox"/> |
| 38            | 10/10/19 14:15  | Reinspection Photo                        |  | Load JPG   | <input checked="" type="checkbox"/> |
| 39            | 10/10/19 14:15  | Reinspection Photo                        |  | Load JPG   | <input checked="" type="checkbox"/> |
| 40            | 10/10/19 14:15  | Reinspection Photo                        |  | Load JPG   | <input checked="" type="checkbox"/> |
| 41            | 10/10/19 14:15  | Reinspection Photo                        |  | Load JPG   | <input checked="" type="checkbox"/> |
| 42            | 10/10/19 14:15  | Reinspection Photo                        |  | Load JPG   | <input checked="" type="checkbox"/> |
| 43            | 10/10/19 14:15  | Reinspection Photo                        |  | Load JPG   | <input checked="" type="checkbox"/> |
| 44            | 10/10/19 14:15  | Reinspection Photo                        |  | Load JPG   | <input checked="" type="checkbox"/> |
| 45            | 10/10/19 14:15  | Reinspection Photo                        |  | Load JPG   | <input checked="" type="checkbox"/> |
| 46            | 10/10/19 14:15  | Reinspection Photo                        |  | Load JPG   | <input checked="" type="checkbox"/> |
| Documentation |                 |                                           |  | 1 per page | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         |  | Thumbnail  | Print                               |
| 1             | 06/08/19 14:09  | TP GIA REPORT                             |  | Load PDF   |                                     |
| 2             | 25/09/19 18:09  | EMAIL FROM AIG DD 05.08.2019              |  | Load PDF   |                                     |
| 3             | 25/09/19 18:09  | NOTIFICATION FROM LAWYER +TP GIA REPORT   |  | Load PDF   |                                     |
| 4             | 26/09/19 11:09  | TP ESTIMATE - MARKED                      |  | Load PDF   |                                     |
| 5             | 01/10/19 15:38  | LETTER TO OI                              |  | Load PDF   |                                     |
| 6             | 16/12/19 10:21  | WORKSHOP INVOICE                          |  | Load PDF   |                                     |
| 7             | 16/12/19 10:21  | AUTHORISATION TO ACT FORM                 |  | Load PDF   |                                     |
| 8             | 16/12/19 10:21  | Release Voucher                           |  | Load PDF   |                                     |
| 9             | 16/12/19 10:21  | LOD                                       |  | Load PDF   |                                     |
| No            | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) |  | Thumbnail  | Print                               |
| 1             | 06/08/19 11:11  | OI GIA REPORT                             |  | Load PDF   |                                     |
| 2             | 03/12/19 13:48  | OI GIA addendum #1                        |  | Load PDF   |                                     |
| 3             | 03/12/19 13:48  | TP GIA                                    |  | Load PDF   |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                | Reset | Save | Print |
|----------------------------------------------------------------------------------------------------------------------------------------------------|-------|------|-------|
| There are no document checklists configured.                                                                                                       |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                    |        |                   |
|-------------------|--------------------|--------|-------------------|
| Vehicle No:       | SKP218A (Insd veh) | Model: | HONDA FIT 1.3 (A) |
|                   | SMG8242A (TP veh)  |        |                   |
| Date of Accident: | 03/08/2019         |        |                   |

|                       |       |     |         |           |
|-----------------------|-------|-----|---------|-----------|
| Global Sum Settlement | : [ ] | Yes | : [ X ] | No        |
| Repair Estimate       | :     | \$  |         | 30,687.92 |
| Final Repair Cost     | :     | \$  |         | 21,350.00 |
| Loss of Use           | :     | \$  |         | 1,320.00  |
| Rental (if any)       | :     | \$  |         | 0.00      |
| LTA / GIA Search Fee  | :     | \$  |         | 0.00      |
| Others:               | :     | \$  |         | 0.00      |
|                       | :     | \$  |         |           |
| Final Settlement Sum  | :     | \$  |         | 22,670.00 |

22.00 days at \$60.00 per day  
days

|                                                                                                      |  |                                                    |     |       |    |                         |
|------------------------------------------------------------------------------------------------------|--|----------------------------------------------------|-----|-------|----|-------------------------|
| Is Third Party Workshop GIA Registered?                                                              |  | [ ]                                                | YES | [ X ] | NO | (Kindly indicate below) |
| A) For <b>Non GIA Registered Workshop</b> :                                                          |  | Agreed Liability ____ 100 ____ (%)                 |     |       |    |                         |
| B) For <b>GIA Registered Workshop</b> :                                                              |  | BOLA Applicable: Yes/ No    BOLA Scenario No: ____ |     |       |    |                         |
| BOLA Liability: ____ (%)                                                                             |  | Assessed Liability (*): ____ (%)                   |     |       |    |                         |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply. |  |                                                    |     |       |    |                         |
| Remarks _____                                                                                        |  |                                                    |     |       |    |                         |

| Payment Instruction: Payee's Breakdown |                        |      |           |
|----------------------------------------|------------------------|------|-----------|
| 1)                                     | Massive Trading & Auto | : \$ | 22,670.00 |
| 2)                                     |                        | : \$ |           |

JOANNE LEE KHANG MIN

16 Dec  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19013645/KEA3Q2

Date: 16/12/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800138437  
 Claimant: SMG8242A Insured Vehicle No: SKP218A  
 Vehicle No: SMG8242A  
 Date of Loss: 03/08/2019 Nature of Claim: TP Claim No: 5346362561SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SMG8242A  
 Make & Model: HONDA FIT, 1.3 (A) Engine No: LEB1441754  
 Reg. Date: 31/12/2018 (Man. Year: 2018) Chassis No: GP51334747  
 Colour: Metallic Dark Blue Odometer: 22447 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm  
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                   | Repairer's       | Adjuster's       | Difference      | Diff %       |
|--------------------------------------------------|------------------|------------------|-----------------|--------------|
| Parts                                            | 24,322.92        | 22,283.72        | 2,039.20        | 8.38         |
| Miscellaneous Items                              | 0.00             | 0.00             | 0.00            |              |
| Labour                                           | 6,365.00         | 4,380.00         | 1,985.00        | 31.19        |
| Paintwork Labour                                 | 0.00             | 0.00             | 0.00            |              |
| Towing                                           | 0.00             | 0.00             | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>              | <b>30,687.92</b> | <b>26,663.72</b> | <b>4,024.20</b> | <b>13.11</b> |
| <b>Approved Total (Overridden) (S\$)</b>         |                  | <b>21,350.00</b> |                 |              |
| <b>Nett Amount (S\$)</b>                         | <b>30,687.92</b> | <b>21,350.00</b> | <b>9,337.92</b> | <b>30.43</b> |
| <b>+ Loss of Use (22.0 x S\$60.00/day) (S\$)</b> |                  | <b>1,320.00</b>  |                 |              |
| <b>Nett Liability (S\$)</b>                      |                  | <b>22,670.00</b> |                 |              |

## INSPECTION

Date of Assignment: 03/08/2019  
 Date Inspected: 05/08/2019 Inspected At: Massive Trading & Auto  
 Blk 5038 #01-405, Ang Mo Kio  
 Industrial Pk 2  
 Singapore 569541  
 Estimated Period of Repair: 18.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                                 | Condition                | Repairer's   | Amount        |
|-----|-----|----------|---------------------------------------------|--------------------------|--------------|---------------|
| 1   | 1   |          | *REAR TAIL-GATE ASSY                        | Bent                     | 881.30 FL    | *881.30 FL    |
| 2   | 1   |          | *REAR TAIL-GATE GLASS MOULDING              | Necessary                | 105.10 FL    | *105.10 FL    |
| 3   | 2   |          | *REAR TAIL-GATE LAMP                        | Cracked                  | 950.60 FL    | *950.60 FL    |
| 4   | 1   |          | *REAR TAIL-GATE EMBLEM FIT                  | Necessary                | 45.10 FL     | *45.10 FL     |
| 5   | 1   |          | *REAR TAIL-GATE EMBLEM HYBDR                | Necessary                | 55.20 FL     | *55.20 FL     |
| 6   | 1   |          | *REAR TAIL-GATE CHROME HANDLE               | Warped                   | 219.70 FL    | *219.70 FL    |
| 7   | 1   |          | *REAR TAIL-GATE INNER LOCK SENSOR           | Cracked                  | 185.70 FL    | *185.70 FL    |
| 8   | 1   |          | *REAR TAIL-GATE INNER LOCK                  | Jammed                   | 195.10 FL    | *195.10 FL    |
| 9   | 1   |          | *REAR TAIL-GATE INNER TRIM BOARD            | Mtg Distorted            | 152.60 FL    | *152.60 FL    |
| 10  | 2   |          | *REAR NO PLATE LAMP                         | Serviceable              | 110.20 FL    | *- FL         |
| 11  | 1   |          | *REAR TAIL-GATE WIPER MOTOR                 | Not Necessary            | 287.10 FL    | *- FL         |
| 12  | 1   |          | *REAR FENDER                                | N/S Buckled / O/S Repair | 1,371.20 FL  | *685.60 FL    |
| 13  | 2   |          | *REAR FENDER INNER TRIM BOARD               | Cracked                  | 410.20 FL    | *410.20 FL    |
| 14  | 1   |          | *REAR N/S FENDER AIR VENT                   | Dented                   | 57.10 FL     | *57.10 FL     |
| 15  | 1   |          | *REAR END PANEL                             | Bent                     | 384.60 FL    | *384.60 FL    |
| 16  | 1   |          | *REAR END PANEL INNER GARNISH               | Dented                   | 191.10 FL    | *191.10 FL    |
| 17  | 1   |          | *REAR BOOT RUBBER                           | Dented / Cut             | 103.40 FL    | *103.40 FL    |
| 18  | 1   |          | *REAR SPARE TYRE PANEL                      | Bent / Buckled           | 1,072.50 FL  | *1,072.50 FL  |
| 19  | 1   |          | *REAR SPARE TYRE PANEL TOP COVER BOARD      | Distorted                | 215.90 FL    | *215.90 FL    |
| 20  | 2   |          | *REAR TAIL -LAMP ASSY                       | Cracked                  | 967.70 FL    | *967.70 FL    |
| 21  | 1   |          | *REAR N/S TAIL-LAMP PANEL                   | Bent                     | 108.10 FL    | *108.10 FL    |
| 22  | 1   |          | *REAR BUMPER                                | Bent                     | 791.30 FL    | *791.30 FL    |
| 23  | 1   |          | *REAR BUMPER LOWER GARNISH (CENTRE PORTION) | Bent                     | 95.10 FL     | *95.10 FL     |
| 24  | 2   |          | *REAR BUMPER REFLECTOR GARNISH              | Distorted                | 230.40 FL    | *230.40 FL    |
| 25  | 2   |          | *REAR BUMPER SIDE RETAINER                  | Cracked                  | 90.20 FL     | *90.20 FL     |
| 26  | 2   |          | *REAR BUMPER SPONGE                         | Cracked                  | 75.10 FL     | *75.10 FL     |
| 27  | 1   |          | *REAR ANTENNA                               | Cracked                  | 95.60 FL     | *95.60 FL     |
| 28  | 1   |          | *REAR BUZZER                                | Cracked                  | 92.10 FL     | *92.10 FL     |
| 29  | 1   |          | *REAR AXLE ASSY                             | Bent                     | 1,100.80 FL  | *1,100.80 FL  |
| 30  | 1   |          | *REAR SHOCK ABSORBER                        | N/S Bent                 | 494.20 FL    | *247.10 FL    |
| 31  | 2   |          | *REAR HUB ASSY                              | Serviceable              | 653.80 FL    | *- FL         |
| 32  | 1   |          | *REAR EXHAUST SILENCER                      | Bent                     | 495.30 FL    | *495.30 FL    |
| 33  | 1   |          | *REAR EXHAUST SILENCER HEAT SHIELD          | Bent                     | 45.10 FL     | *45.10 FL     |
| 34  | 1   |          | *HYBRID BATTERY                             | Dented                   | 12,985.60 FL | *12,985.60 FL |
| 35  | 1   |          | *HYBRID BATTERY TOP CHROME COVER            | Buckled                  | 299.70 FL    | *299.70 FL    |
| 36  | 1   |          | *HYBRID BATTERY FAN DISCHARGE MOTOR ASSY    | Damaged                  | 800.00 FL    | *800.00 FL    |
| 37  | 1   |          | *HYBRID BATTERY AIR DISCHARGE HOSE          | Distorted / Dented       | 499.20 FL    | *499.20 FL    |
| 38  | 1   |          | *HYBRID BATTERY CONTROL UNIT                | Dented                   | 1,912.30 FL  | *1,912.30 FL  |
| 39  | 1   |          | *HYBRID BATTERY TRAY                        | Distorted                | 256.10 FL    | *256.10 FL    |
| 40  | 1   |          | *REAR TOWING HOOK                           | Repair                   | 115.20 FL    | *- FL         |
| 41  | 2   |          | *REAR REVERSE SENSOR                        | Dented                   | 575.80 FL    | *575.80 FL    |
| 42  | 1   |          | *REAR REVERSE CAMERA                        | Serviceable              | 300.00 FS    | *- FS         |
| 43  | 1   |          | *REAR NO PLATE )                            | Dented                   | 45.00 FS     | *45.00 FS     |
| 44  | 1   |          | *REAR NO PLATE HOLDER )                     | Dented                   | 45.00 FS     | *- FS         |
| 45  | 1   |          | *REAR WINDSCREEN SEALANT                    | Necessary                | 55.00 FS     | *40.00 FS     |
| 46  | 20  |          | *REAR BUMPER CLIP                           | Necessary                | 60.00 FS     | *60.00 FS     |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 30,277.40 27,818.40

- List Item Discount on L Items 20.00/20.00% (\$\$) 5,954.48 5,534.68

Report was unsubmitted during this print-out.

| No.                                           | Qty | Part<br>No. | Particulars | Condition | Repairer's        | Amount    |
|-----------------------------------------------|-----|-------------|-------------|-----------|-------------------|-----------|
|                                               |     |             |             |           | Total Parts (S\$) | 24,322.92 |
|                                               |     |             |             |           |                   | 22,283.72 |
| Report was unsubmitted during this print-out. |     |             |             |           |                   |           |



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                         | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                     |          |                 |                 |
| 1                              | REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING                  | New      | 2,000.00        | 1,600.00        |
| 2                              | TO PUTTY & SPRAY PAINT REAR ACCIDENT AFFECTED PORTION                               | New      | 1,600.00        | 1,400.00        |
| 3                              | CHECK /RECONNECT WIRING                                                             | New      | 45.00           | 20.00           |
| 4                              | TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION                                     | New      | 200.00          | 100.00          |
| 5                              | REMOVE/REFIT REAR TAIL-GATE WIPER MOTOR AND LOCK MECHANISM AND REAR BOOT UPHOLSTERY | New      | 150.00          | 60.00           |
| 6                              | REMOVE/RENEW REAR EXHAUST SILENCER                                                  | New      | 120.00          | 60.00           |
| 7                              | REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIR                                   | New      | 120.00          | 120.00          |
| 8                              | REMOVE/RENEW HYBRID BATTERY INCLUDING DIAGNOSTIC CHECK AND PROGRAMMING )            | New      | 800.00          | 600.00          |
| 9                              | REMOVE/RENEW REAR HYBRID BATTERY INCLUDING DIAGNOSTIC CHECK )                       | New      | 550.00          | 0.00            |
| 10                             | FOUR WHEEL TROLLER TOWING                                                           | New      | 150.00          | 120.00          |
| 11                             | REMOVE/RENEW REAR AXLE AND UNDERCARRIAGES                                           | New      | 550.00          | 240.00          |
| 12                             | CHECK AND REALIGN WHEEL ALIGNMENT                                                   | New      | 80.00           | 60.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                                                     |          | <b>6,365.00</b> | <b>4,380.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >