

CHOO MOTOR SPRAY PAINTER
BLK1 KAKI BUKIT AVE 6
#01-39 AUTOBAY
SINGAPORE 417883

not Authorized
4/5 5000/
5/8/19
Theoph. Atherington
6dy.

VEHICLE NO: SJP 1227D

QTY	PARTICULAR			
1 PCS	BONNET			
1 PCS	FRONT BUMPER	480.60	2	\$1,102.00 X
1 PCS	FRONT BUMPER CENTRE GRILLE	105.20	2	\$655.00
1 PCS	FRONT BUMPER FOG LAMP COVER N/S	66.30	2	\$185.00
1 PCS	FRONT BUMPER SPONGE	185.20	1	\$95.00
1 PCS	FRONT BUMPER REINFORCEMENT		1	\$199.00
1 PCS	FRONT BUMPER SIDE RETAINER N/S		1	\$431.50 X
1 PCS	FRONT BUMPER CLIPS		1	\$66.50
1 PCS	FRONT SUPPORT PANEL	958.00	1	\$50.00
1 PCS	FRONT FENDER N/S	405.30	1	\$1,018.00
1 PCS	FRONT FENDER INNERSHIELD N/S		1	\$620.00
1 SET	FRONT FENDER INNERSHIELD CLIPS N/S		1	\$266.00
1 PCS	FRONT DOOR N/S		1	\$50.00
1 PCS	HEADLAMP N/S	650.60	2	\$1,245.00 X
1 PCS	FRONT SHOCK ABSORBER N/S		1	\$850.00
1 PCS	FRONT KNUCKLE ARM N/S		1	\$622.00 X
1 PCS	FRONT KNUCKLE ARM BEARING N/S	265.00	1	\$654.00
1 PCS	FRONT LOWER ARM N/S		1	\$350.00
1 PCS	FRONT DRIVESHAFT N/S		1	\$599.00
1 PCS	AIR CON CONDENSER		1	\$1,280.00 X
1 PCS	RADIATOR ASSY		1	\$950.00 X
1 PCS	FRONT SPORT RIM N/S		1	\$885.00 X
			10/13/19	\$600.00 3805.00
				\$12,773.00
	LABOUR CHARGES			
	TO CHECK WIRING			\$80.00 - 20
	TO REFILL AIR CON GAS			\$150.00 - 100
	TO CONDUCT WHEEL ALIGNMENT			\$125.00 - 80
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE			\$380.00 - 120
	TO SPRAY RUST PROOFING			\$150.00 - 30
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$1,080.00 - 800
	TO PUTTY & SPRAY PAINTING			\$1,580.00 - 800
				\$16,318.00 880
			TOTAL	\$16,318.00

(20%)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4801.7
3841.36
6217.36
5001