

Cecilia

ETHOZ

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 03/08/2019

To : INDIA INTERNATIONAL INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : CHONG LEE YEE

: AXA INSURANCE PTE LTD

Certificate No : GA145437/1

Accident Date : 26/07/2019

Vehicle No : SLH-7252-J

Make & Model : TOYOTA LEXUS IS250 AUTO STANDARD HII

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	REAR DOOR RH <i>4-</i>	1,345.20	
1	REAR DOOR HINGE RH (UPPER) <i>X</i>	75.60	
1	REAR DOOR HINGE RH (LOWER) <i>X</i>	75.60	
1	REAR DOOR CHECKER RH <i>X</i>	241.50	
1	REAR DOOR LOCK RH <i>X</i>	457.30	
1	REAR DOOR GLASS OUTER MOULDING RH <i>an</i>	195.30	
1	REAR DOOR GLASS REGULATOR RH <i>? H</i>	268.20	
1	REAR DOOR GLASS REGULATOR MOTOR RH <i>? an</i>	755.10	
1	REAR DOOR TRIMBOARD RH <i>? cm</i>	1,312.20	

Date : 03/08/2019

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : CHONG LEE YEE

AXA INSURANCE PTE LTD

Certificate No : GA145437/1

Accident Date : 26/07/2019

Vehicle No : SLH-7252-J

Make & Model : TOYOTA LEXUS IS250 AUTO STANDARD HII

ESTIMATED REPAIR COST DETAILS

Excess :

0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR DOOR HANDLE OUTER RH <i>X 9/2</i>	242.60	
1	REAR DOOR LOCK CAP RH <i>X 8/2</i>	85.30	
1	REAR DOOR HANDLE OUTER BRACKET RH <i>X 20/2</i>	314.60	
1	ROCKER PANEL GARNISH RH <i>repair</i>	755.40	
10	ROCKER PANEL GARNISH CLIP <i>X 1/1</i>	45.00	
1	REAR FENDER RH <i>repair</i>		RESTORE
1	REAR FENDER INNER SHIELD RH <i>X 9/2</i>	421.50	
10	REAR FENDER INNER SHIELD CLIP <i>X 1/1</i>	45.00	
1	REAR FENDER PROTECTOR RH <i>re-</i>	58.80	
1	REAR BUMPER <i>repair</i>	954.30	

Date : 03/08/2019

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department** FAX :

Owner : CHONG LEE YEE
: AXA INSURANCE PTE LTD

Certificate No : GA145437/I Accident Date : 26/07/2019

Vehicle No : SLH-7252-J Make & Model : TOYOTA LEXUS IS250 AUTO STANDARD HII

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
10	REAR BUMPER CLIP <i>x 10</i>	45.00	
1	REAR BUMPER SIDE RETAINER RH <i>x 1</i>	95.50	
1	REAR SPORT RIM RH <i>SCA</i>	2,423.10	<i>S/N 500</i>
1	REAR SHOCK ABSORBER RH <i>X</i>	755.40	
1	REAR UPPER ARM RH (INNER) <i>X</i>	469.20	
1	REAR UPPER ARM RH (OUTER) <i>X</i>	412.40	
1	REAR LOWER ARM RH (INNER) <i>X</i>	475.10	
1	REAR LOWER ARM RH (OUTER) <i>X</i>	384.20	
1	REAR TOE CONTROL RH <i>X</i>	195.40	
1	REAR STABILIZER BAR LINK RH <i>X</i>	241.30	

Date : 03/08/2019

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : CHONG LEE YEE
AXA INSURANCE PTE LTD

Certificate No : GA145437/1

Accident Date : 26/07/2019

Vehicle No : SLH-7252-J

Make & Model : TOYOTA LEXUS IS250 AUTO STANDARD HII

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR KNUCKLE ARM RH ? <i>Yes</i>	984.30	
1	REAR WHEEL BEARING RH ? <i>Yes</i>	552.70	
	Sub Total	14682.10	
	Discount 25% On Parts	(3670.53)	
	<u>Special Nett Item</u>		
1	BRAKE FLUID X <i>nn</i>	20.00	
	Sub Total	20.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILIATE REPAIR	800.00 <i>500</i>	
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	

Date : 03/08/2019

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : CHONG LEE YEE
AXA INSURANCE PTE LTD

Certificate No : GA145437/1

Accident Date : 26/07/2019

Vehicle No : SLH-7252-J

Make & Model : TOYOTA LEXUS IS250 AUTO STANDARD HII

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO SPRAY PAINTING ON AFFECTED AREAS	900.00	200
	TO TRANSFER REAR DOOR RH FITTING	100.00	60
	TO REMOVE & RENEW REAR UNDERCARRIAGE RH TO FACILITATE REPAIR	250.00	80 X 111
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	100.00	60
	Sub Total	2185.00	

Remarks:

13,216.57

6 days - Linyan

SUB TOTAL

GST 7.0 % 925.16

TOTAL 14,141.74

Surveyor's name:

Rahul - Hp 90010068

Principal's name: CHONG LEE YEE

Survey Date & Time: 08/08/19 @ 0930

Date : 06/09/2019

To : INDIA INTERNATIONAL INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : CHONG LEE YEE

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA145437/1

Accident Date : 26/07/2019

Vehicle No : SLH-7252-J

Make & Model : TOYOTA LEXUS IS250 AUTO STANDARD HIL

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	REAR DOOR RH	1345.20	1345.20
1	REAR DOOR HINGE RH (UPPER)	75.60	0.00
1	REAR DOOR HINGE RH (LOWER)	75.60	0.00
1	REAR DOOR CHECKER RH	241.50	0.00
1	REAR DOOR LOCK RH	457.30	0.00
1	REAR DOOR GLASS OUTER MOULDING RH	195.30	195.30
1	REAR DOOR GLASS REGULATOR RH	268.20	268.20
1	REAR DOOR GLASS REGULATOR MOTOR RH	755.10	755.10
1	REAR DOOR TRIMBOARD RH	1312.20	1312.20
1	REAR DOOR HANDLE OUTER RH	242.60	0.00
1	REAR DOOR LOCK CAP RH	85.30	0.00
1	REAR DOOR HANDLE OUTER BRACKET RH	314.60	314.60

PAGE : 1



Date : 06/09/2019

To : INDIA INTERNATIONAL INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : CHONG LEE YEE

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA145437/1

Accident Date : 26/07/2019

Vehicle No : SLH-7252-J

Make & Model : TOYOTA LEXUS IS250 AUTO STANDARD HII

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	ROCKER PANEL GARNISH RH	755.40	0.00
10	ROCKER PANEL GARNISH CLIP	45.00	0.00
1	REAR FENDER RH RESTORE	0.00	0.00
1	REAR FENDER INNER SHIELD RH	421.50	0.00
10	REAR FENDER INNER SHIELD CLIP	45.00	0.00
1	REAR FENDER PROTECTOR RH	58.80	58.80
1	REAR BUMPER	954.30	0.00
10	REAR BUMPER CLIP	45.00	0.00
1	REAR BUMPER SIDE RETAINER RH	95.50	0.00
1	REAR SHOCK ABSORBER RH	755.40	0.00
1	REAR UPPER ARM RH (INNER)	469.20	0.00
1	REAR UPPER ARM RH (OUTER)	412.40	0.00
1	REAR LOWER ARM RH (INNER)	475.10	0.00
1	REAR LOWER ARM RH (OUTER)	384.20	0.00
1	REAR TOE CONTROL RH	195.40	0.00

PAGE : 2



Date : 06/09/2019

To : INDIA INTERNATIONAL INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : CHONG LEE YEE

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA145437/1

Accident Date : 26/07/2019

Vehicle No : SLH-7252-J

Make & Model : TOYOTA LEXUS IS250 AUTO STANDARD HII

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	REAR STABILIZER BAR LINK RH	241.30	0.00
1	REAR KNUCKLE ARM RH	984.30	0.00
1	REAR WHEEL BEARING RH	552.70	0.00
Sub Total		12259.00	4249.40
Discount 25% On Parts		(0.00)	(1062.35)
Special Nett Item			
1	REAR SPORT RIM RH	2423.10	500.00
1	BRAKE FLUID	20.00	0.00
Sub Total		2443.10	500.00
Labour & Misc			
LABOUR TO FACILIATE REPAIR		800.00	500.00
TO CHECK AND RECONNECT ALL NECESSARY WIRINGS		35.00	35.00

PAGE : 3



Date : 06/09/2019

To : INDIA INTERNATIONAL INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : CHONG LEE YEE

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA145437/1

Accident Date : 26/07/2019

Vehicle No : SLH-7252-J

Make & Model : TOYOTA LEXUS IS250 AUTO STANDARD HIL

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	TO SPRAY PAINTING ON AFFECTED AREAS	900.00	700.00
	TO TRANSFER REAR DOOR RH FITTING	100.00	60.00
	TO REMOVE & RENEW REAR UNDERCARRIAGE RH TO FACILITATE REPAIR	250.00	0.00
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	100.00	60.00
	Sub Total	2185.00	1355.00

PAGE : 4



Date : 06/09/2019

To : INDIA INTERNATIONAL INSURANCE PTE LTD

Attn : Motor Claim Department

FAX :

Owner : CHONG LEE YEE

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA145437/1

Accident Date : 26/07/2019

Vehicle No : SLH-7252-J

Make & Model : TOYOTA LEXUS IS250 AUTO STANDARD HIL

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	13,822.35	5,042.05
	GST 7.0 %	967.56	352.94
	Total	14,789.	5,394.99

COR: \$4,000.00 (4% REPAIR)

6 days REPAIR

Surveyor Name : RASUL - LKK

Date & Time : 08/08/2019 9:30:00 AM

Lee Chen Sin

CLAIM DEPARTMENT

DID : 66547520

FAX :

Parts \$4,249.40 - 25%

- \$3,187.05

SLN - \$800.00

LABOUR - \$1,355.00

\$5,042.05

- 20%

\$4,033.64

PAGE: 5