

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 52210**  
Date Estimated : **02/08/2019**  
Prepared By : **Chua Kee Sin**

**- ESTIMATE REPAIR FOR -**  
**Lim Oon Cheng**

**Bukit Tunggai Road**

**Singapore 309715**

**30.00**

**- ACCOUNT - 121**  
**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLZ5225G</b>	<b>WBAJV22000BE461</b>	<b>10/04/2018</b>	<b>630i GT</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including remove attachments to facilitate repairs.	850.00		850.00
To respray rear bumper	934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR BUMPER CARRIER	934.50	1.00		934.50
REAR BUMPER BOTTOM REINFORCEMENT	84.75	1.00		84.75
REAR BUMPER TRIM PANEL PAINTED (M)	455.35	1.00		455.35
REAR BUMPER PANEL PRIMED (M)	1,821.30	1.00		1,821.30

# SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	3,295.90
Total Labour & Parts :	5,309.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,309.90
GST @7%:	371.69
<b>Grand Total :</b>	<b>5,681.59</b>

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 52210**  
Date Estimated : **02/08/2019**  
Prepared By : **Chua Kee Sin**

**- ESTIMATE REPAIR FOR -**  
**Lim Oon Cheng**

**Bukit Tunggal Road**

**Singapore 309715**

**30.00**

**- ACCOUNT - 121**  
**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLZ5225G</b>	<b>WBAJV22000BE461</b>	<b>10/04/2018</b>	<b>630i GT</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including remove attachments to facilitate repairs.	850.00		850.00
To respray rear bumper	1,038.00	934	1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR BUMPER CARRIER	934.50	1.00		934.50
REAR BUMPER BOTTOM REINFORCEMENT	84.75	1.00		84.75
REAR BUMPER TRIM PANEL PAINTED (M)	455.35	1.00		455.35
REAR BUMPER PANEL PRIMED (M)	1,821.30	1.00		1,821.30

# SUPPLEMENTARY ITEMS

Total Labour :	2,118.00
Total Parts :	3,295.90
Total Labour & Parts :	5,413.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,413.90
GST @7%:	378.97
<b>Grand Total :</b>	<b>5,792.87</b>

5309.9

3 days

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Supplementary

Estimate No. : **b1 52210**  
Date Estimated : **02/08/2019**  
Prepared By : **Chua Kee Sin**

**- ESTIMATE REPAIR FOR -**  
**Lim Oon Cheng**

**Bukit Tunggal Road**

**Singapore 309715**

**30.00**

**- ACCOUNT - 121**  
**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLZ5225G</b>	<b>WBAJV22000BE461</b>	<b>10/04/2018</b>	<b>630i GT</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# REAR BUMPER CARRIER	934.50	1.00		934.50 <i>bt</i>
-----------------------	--------	------	--	------------------

# SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	934.50
Total Labour & Parts :	934.50

BMW Dealer

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



*28/8/2019  
Survey & repair*

*Due Date  
13/8*

*19/8/2019 morning  
Survey & repair*

GST REG. NO : M2 - 0020081 - X

02 AUG 2019

## ESTIMATE

**TLK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed

Page No. 1 of 4

Estimate No. : b1 52210  
Date Estimated : 02/08/2019  
Prepared By : Chua Kee Sin

**- ESTIMATE REPAIR FOR -**  
Lim Oon Cheng  
Bukit Tunggul Road  
Singapore 309715

**- ACCOUNT**  
Complementary items surveyed and is subject to final approval from Insurance Company  
Cash Sales - Service  
Singapore  
Signature:  
Date:

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ5225G	BE46166	10/04/2018	630i GT	0

DESCRIPTION	VALUE
Replace Rear bumper and remove attachment etc include knock on accident area	850 1,275.00
Spray painting rear bumper	1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 80.00
<b>Total Labour 1:</b>	<b>2,570.00</b>

DESCRIPTION	QTY	PRIC	VALUE
Abrasion gua	1	5.50	5.50
Abrasion gua	1	5.50	5.50
REAR BUMPER BOTTOM REINFORCEMENT	1	84.75	84.75
REAR BUMPER CENTRE GUIDE	1	73.80	73.80
REAR BUMPER TOWING EYE FLAP (M)	1	87.25	87.25
REAR BUMPER TRIM PANEL PAINTED (M)	1	455.35	455.35
REAR BUMPER PANEL PRIMED (M)	1	1,821.30	1,821.30
DECOUPLING RING PDC TORQUE CONVERTER	6	5.05	30.30
ULTRASONIC SENSOR MINERALWEISS (WA96)	4	368.80	1,475.20
<b>Total Parts :</b>			<b>4,038.95</b>

Claims Settlement  
Regn No. \_\_\_\_\_  
Date & Time 2 Excess S\$ \_\_\_\_\_  
Surveyor's Name Tan Kah Sign [Signature]  
Surveyor's Tel 97445014 Authorized Yes/No \_\_\_\_\_  
Authorised Date 02/08/2019 Time \_\_\_\_\_  
RESURVEY PARTS PHOTO BY SURVEYOR Yes/No PML Yes/No  
Surveyor's E-mail tan@tkkauto.com  
No. of Working Days Recommend 03 days

Labour 1	:	2,570.00
Parts	:	4,038.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	462.63
<b>Grand Total</b>	<b>:</b>	<b>7,071.58</b>

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\***  
**\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***