

22/03/2002

ASS. REC. BY:

REF: CS/SMD19013710 / Tlv f3

Special Instruction:

Surveyor: Taufik H

ASSIGNMENT (Office)

From (Person): Hwang Shang Yi

of SMD

Date/Time: 5.8.19 12.01 p.m

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 7888A

Insured:

GV 1982K

at Workshop m/s Nova Automotive

Tel:

6 2723892 / Ah Wei

of BLK 1008, A 01-04/06/08

Policy No: DIB MPCTE 002449

Claim No: CMTD 1903659

Sum Insured:

Excess:

Make of Veh:

D.O.A 29.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 6.8.19 9.37am

Person Contacted:

Joanne

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SMA 7888A -x

GV 1982K -x

5/9/19

Send preli revised via merimen

10/9/19

@ 228pm Suanna said vehicle still under repair

25/9/19

Final fig \$ 7432.80 (Red 1203.00, 14/9) confirmed by email



**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Hwang Shiang Yi

Date: 05 Sep 2019

**Preliminary Advice**

Insured Vehicle No	: GV1982K	Accident Date	: 29/07/2019
TP Vehicle No	: SMA7888A	Assignment Date	: 05/08/2019
Make	: MERCEDES-BENZ E200	Est. Duration of Repair	: 3
Date of Inspection	: 4/9/2019		
Inspection At	: MOVA AUTOMOTIVE PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,636.00
Revised Amount	:S\$	7,164.60
Check Items (Estimated)	:S\$	761.40
Total	:S\$	7,926.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☒ Other comments :The above survey was conducted on a 'Without Prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2019 Sendback Est	05 Aug 2019 16:44 S\$8,636.00	05 Aug 2019 18:01 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS**

Insured:	KUM ENG HUAT ELECTRIC CO PTE LTD, Co. Reg. No.: 200009171Z		
Main Claimant:	WANG JUN CHUNG, ID: S8176894C		
Vehicle Reg. No.:	SMA7888A	Date of Loss:	29/07/2019 14:00 - :59 [25 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1903659	Policy/Cover Note No.:	D18MTPCVE002449 (Comprehensive)
Vehicle Reg. No. (Insured):	GV1982K	Policy No. (Claimant):	
		Excess:	
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/08/2019]		
Driver/Custodian (Insured):	NG BAK SWEE (), NRIC: S1129622Z, Tel: +6590121279 Email:		

**ASSOCIATED MAIL RECEIVED**
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 25 September 2019 5:47 PM  
**To:** Tan Yoong Wei; Taufikh (LKKAUTO)  
**Cc:** Hsiao Tong (LKKAUTO); SUR  
**Subject:** RE: FINALISE SMA7888A

Dear Yoong Wei,

WITHOUT PREJUDICE

Confirmed finalise \$7432.80 @ 3 working days

**Kindly send Final invoice and all supporting documents directly to SOMPO INSURANCE**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan Yoong Wei <tanyw@mova.com.sg>  
**Sent:** Wednesday, 25 September 2019 11:58 AM  
**To:** Taufikh (LKKAUTO) <Taufikh@lkkauto.com>  
**Cc:** Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>  
**Subject:** FINALISE SMA7888A

Hi Taufikh,

Please advice whether we can finalise cost of repair part by part \$7432.80 3 days?

tq

Best Regards,

Tan Yoong Wei

Estimator

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	03/08/2019 12:04
Date Of Accident	29/07/2019 15:00
Exact Location Of Accident	ALONG BALESTIER ROAD
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA7888A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WANG JUN CHUNG
NRIC No	S8176894C
Email Address	SALES-MARKETING123@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97887888
Alternative Phone No	OTHERS-97887888

#### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200 A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

#### Driver

Name of Driver	WANG JUN CHUNG
NRIC No	S8176894C
Date Of Birth	02/10/1981
Occupation	INDOOR
Date Of Driving Pass	06/03/2009
Driving Experience	10 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97887888
Fax Number	
Contact Number	OTHERS-97887888
Email Address	SALES-MARKETING123@HOTMAIL.COM

Address	BLK 129 BUKIT MERAH VIEW #08-174
Postcode	150129
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHEW PEI YI GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GV1982K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)



## Sketch Plan Pg. 1


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Report Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2




## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SMA7888A	ACCIDENT DATE & TIME: 29/7/19 3pm
CONTACT NUMBER: 97887888	E-MAIL ADDRESS: sales-marketing123@hotmail.com
LOCATION: Along Balestier Road	
<p>I was travelling on Balestier Road, going for keeping on my lane, preparing to turn into moulmein road toward Newton Circus. Suddenly lossy GV1982K cut in abruptly from the my right lane to go into filter lane towards CTE and crack into my top right.</p>	
<p>Accident happen on 29/7/19 but I am only reporting on 3/8/19 because I was travelling to Vietnam from 30/7/19 - 2/8/19. I called into MAA to inform that I will only be doing my report on 3/8/19</p>	
<p>NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION</p>	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:



Repair Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**Main Office :** No. 22, Jalan Klang, Singapore 159419  
Tel: 6476 3333 Fax: 6271 5891

**Service Centre :** Block 1008, Bukit Merah Lane 3,  
#01-04/06/08/115, Singapore 159722  
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314  
www.mova.com.sg  
GST Reg. No: M2-0088864-2

**Mova Spray Centre**  
2K Oven Spray Painting System

**Power-M Automotive Pte Ltd**  
Specialise in Car Air-con Services,  
Car Audio & Hi-Fi System.

**Hilton Car Rental Centre**  
**Hilton Auto Trading**  
Dealing In New/Used Cars, Hire Purchase & Insurance.



**TP INSURER:** Sompoo Insurance Singapore Pte. Ltd. (HQ)  
**KUM ENG HUAT ELECTRIC CO PTE LTD**

#### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	D18MTPCVE002449	Date of Loss:	29/07/2019
Vehicle Reg. No.:	SMA7888A	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	NG BAK SWEE		
Make/Model:	MERCEDES-BENZ E200, 2.0 (A)	Vehicle Reg. Date:	28/06/2017
Vehicle Colour:	SILVER	Chassis No:	WDD2130422A070233
Engine No:	27492030763669		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	I WAS CHANGING LANE FROM SECOND LANE TO FIRST ANE AND VEHICLE B SUDDENLY TURN RIGHT AND HIT ONTO MY VEHICLE REAR LEFT.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

*Handwritten notes:*  
Tangkin 9344 5749  
wp + 1/9/19 730p-  
Resurvey before paint  
2 days surr/blank

#### COST OF CLAIMS

	Amount
Parts	6,966.00
Miscellaneous Items	0.00
Labour	1,670.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$\$)	8,636.00
+ GST 7.00% (\$\$)	604.52
Nett Amount (\$\$)	9,240.52

This claim is handled by: WEI

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2019)
<b>Parts:</b>	143	MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMA7888A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER RH	10.00	0.00	bt *1,315.00 FL
2	1		*FRONT BUMPER RETAINER RH	10.00	0.00	rel *84.00 FL
3	1		*FRONT COWLING RH	10.00	0.00	an *190.00 FL
4	10		*COWLING CLIPS	10.00	0.00	an *90.00 FL
5	1		*FRONT HEADLAMP RH	10.00	0.00	cw *3,940.00 FL
6	1		*FRONT HEADLAMP SUPPORT RH	10.00	0.00	an *268.00 FL
7	1		*FRONT BUMPER	10.00	0.00	de *1,465.00 FL
8	10		*BUMPER RIVET	10.00	0.00	wt *90.00 FL
9	1		*FRONT PARKING SENSOR RH	10.00	0.00	an *298.00 FL
				Sub Total (S\$)		7,740.00
				- List Item Discount on L Items (S\$)		774.00
				Total Parts (S\$)		6,966.00

F=Franchise part, L=ListItemDisc.

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO REPAIR FRONT WHEELHOUSE RH, FRONT SUPPORT PANEL. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS, TO STRAIGHTEN ON ACCIDENT DAMAGED PARTS	New	300. 550.00
2	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	450. 650.00
3	TO INSPECT FRONT HEADLAMP WATER LEAKAGE TEST	New	30. 40.00
4	TO RE-CONFIGURE FRONT HEADLAMP & SETTING	New	120 200.00
5	TO SETTING FRONT PARKING SENSOR & CORDING	New	30 150.00
6	TO RUST PROOF ON ACCIDENT DAMAGED PARTS	New	30 80.00
Gross Labour Cost (S\$)			1,670.00

Report was unsubmitted during this print-out.

Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

8/5/2019

CK135748.

Estimate Report



Main Office : No. 22, Jalan Kilang, Singapore 159419  
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,  
#01-04/06/08/116, Singapore 159722  
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314  
www.mova.com.sg  
GST Reg. No: M2-0068864-2

Mova Spray Centre  
2K Oven Spray Painting System

Power-M Automotive Pte Ltd  
Specialise In Car Air-con Services,  
Car Audio & Hi-Fi System.

Hilton Car Rental Centre  
Hilton Auto Trading  
Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)  
KUM ENG HUAT ELECTRIC CO PTE LTD

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	D18MTPCVE002449	Date of Loss:	29/07/2019
Vehicle Reg. No.:	SMA7888A	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	NG BAK SWEE		
Make/Model:	MERCEDES-BENZ E200, 2.0 (A)	Vehicle Reg. Date:	28/06/2017
Vehicle Colour:	SILVER	Chassis No:	WDD2130422A070233
Engine No:	27492030763669		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	I WAS CHANGING LANE FROM SECOND LANE TO FIRST ANE AND VEHICLE B SUDDENLY TURN RIGHT AND HIT ONTO MY VEHICLE REAR LEFT.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

*Tanpin 9244 5749  
wp. 4/9/19 730p.  
Repair before paint  
2 days sunblock*

**COST OF CLAIMS**

	Amount
Parts	6,966.00
Miscellaneous Items	0.00
Labour	1,670.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>8,636.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>604.52</b>
<b>Nett Amount (S\$)</b>	<b>9,240.52</b>

This claim is handled by: WEI

Generated using Marimen e-Claims Internet Estimation &amp; Adjusting System

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Aug 2019)  
 Parts: 143 MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for SMA7888A)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER RH	10.00	0.00	bf *1,315.00 FL
2	1		*FRONT BUMPER RETAINER RH	10.00	0.00	rel *84.00 FL
3	1		*FRONT COWLING RH	10.00	0.00	? *190.00 FL
4	10		*COWLING CLIPS	10.00	0.00	? *90.00 FL
5	1		*FRONT HEADLAMP RH	10.00	0.00	cr *3,940.00 FL
6	1		*FRONT HEADLAMP SUPPORT RH	10.00	0.00	? *268.00 FL
7	1		*FRONT BUMPER	10.00	0.00	de *1,465.00 FL
8	10		*BUMPER RIVET	10.00	0.00	wt *90.00 FL
9	1		*FRONT PARKING SENSOR RH	10.00	0.00	? *298.00 FL

F=Franchise part, L=ListItemDisc,

Sub Total (\$\$) 7,740.00

- List Item Discount on L Items (\$\$) 774.00

Total Parts (\$\$) 6,966.00

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

Parts \$7192 - 10%

\$6472.80

Labour \$960

Total PIP \$7432.80 3DAUS-

---

 //



## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO REPAIR FRONT WHEELHOUSE RH, FRONT SUPPORT PANEL, TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS, TO STRAIGHTEN ON ACCIDENT DAMAGED PARTS	New	300. 550.00
2	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	45. 650.00
3	TO INSPECT FRONT HEADLAMP WATER LEAKAGE TEST	New	30. 40.00
4	TO RE-CONFIGURE FRONT HEADLAMP & SETTING	New	120. 200.00
5	TO SETTING FRONT PARKING SENSOR & CORDING	New	30. 150.00
6	TO RUST PROOF ON ACCIDENT DAMAGED PARTS	New	30. 80.00
Gross Labour Cost (\$\$)			1,670.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19013710/T1VF3N2

Date: 26/09/2019

## REFERENCE

<b>Handling Insurer:</b>	Sompo Insurance Singapore Pte. Ltd.	<b>Policy No:</b>	D18MTPCVE002449
<b>Claimant Vehicle No :</b>	SMA7888A	<b>Insured Vehicle No :</b>	GV1982K
<b>Date of Loss:</b>	29/07/2019	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	CMTD1903659

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	SMA7888A	<b>Engine No:</b>	27492030763669
<b>Make &amp; Model:</b>	MERCEDES-BENZ E200, 2.0 (A)	<b>Chassis No:</b>	WDD2130422A070233
<b>Reg. Date:</b>	28/06/2017 (Man. Year: 2016)	<b>Odometer:</b>	29373 km
<b>Colour:</b>	Silver		
<b>Engine Capacity:</b>	1991 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (\$\$):</b>	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>		<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

## CONDITION OF TYRES

<b>Front Tyre Size:</b>	225/55R17	<b>Rear Tyre Size:</b>	225/55R17
<b>Front Left Side:</b>	Goodyear 6 mm	<b>Rear Left Side:</b>	Goodyear 6 mm
<b>Front Right Side:</b>	Goodyear 6 mm	<b>Rear Right Side:</b>	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,966.00	6,472.80	493.20	7.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	960.00	710.00	42.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>8,636.00</b>	<b>7,432.80</b>	<b>1,203.20</b>	<b>13.93</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>604.52</b>	<b>520.30</b>	<b>84.22</b>	<b>13.93</b>
<b>Nett Amount (\$\$)</b>	<b>9,240.52</b>	<b>7,953.10</b>	<b>1,287.42</b>	<b>13.93</b>

## INSPECTION

<b>Date of Assignment:</b>	05/08/2019	<b>Present Location:</b>	Mova Automotive Pte Ltd (Bukit Merah)
<b>Date Inspected:</b>	04/09/2019	<b>Inspected At:</b>	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 26 Sep 2019)
<b>Parts:</b> 143	MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMA7888A)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	1,315.00 FL	*1,315.00 FL
2	1		*FRONT BUMPER RETAINER RH	Necessary	84.00 FL	*84.00 FL
3	1		*FRONT COWLING RH	Not Necessary	190.00 FL	*- FL
4	10		*COWLING CLIPS	Not Necessary	90.00 FL	*- FL
5	1		*FRONT HEADLAMP RH	Cracked	3,940.00 FL	*3,940.00 FL
6	1		*FRONT HEADLAMP SUPPORT RH	Not Necessary	268.00 FL	*- FL
7	1		*FRONT BUMPER	Deformed	1,465.00 FL	*1,465.00 FL
8	10		*BUMPER RIVET	Necessary	90.00 FL	*90.00 FL
9	1		*FRONT PARKING SENSOR RH	Not Working	298.00 FL	*298.00 FL
					<b>Sub Total (S\$)</b>	<b>7,740.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>774.00</b>
					<b>Total Parts (S\$)</b>	<b>6,966.00</b>
						<b>6,472.80</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPAIR FRONT WHEELHOUSE RH, FRONT SUPPORT PANEL. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS, TO STRAIGHTEN ON ACCIDENT DAMAGED PARTS	New	550.00	300.00
2	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	650.00	450.00
3	TO INSPECT FRONT HEADLAMP WATER LEAKAGE TEST	New	40.00	30.00
4	TO RE-CONFIGURE FRONT HEADLAMP & SETTING	New	200.00	120.00
5	TO SETTING FRONT PARKING SENSOR & CORDING	New	150.00	30.00
6	TO RUST PROOF ON ACCIDENT DAMAGED PARTS	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,670.00</b>	<b>960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >