

*memo*

*Cecilia*

## ***Jin Auto Services Pte Ltd***

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Business Registration No:200704370C GST Registration No:200704370C

Date : 22/8/2019

M/S India Int'l Insurance Pte Ltd  
64 CECIL STREET  
#04-00 #06-00 IOB BUILDING  
SINGAPORE 049711

WITHOUT PREJUDICE

Dear Sir/Madam  
Accident Involving Vehicle SJX8070A & SHC8522 Y ON 02/08/19

We are instructed by the owner of SJX8070A to write, negotiate and settle claim on his behalf for the above mentioned accident. Our client's vehicle SJX8070A was inspected and surveyed by your appointed surveyor. As the accident was caused solely due to the negligence of your insured SH7341C we are now seeking the total amount of claim as follow:

|                       |     |         |
|-----------------------|-----|---------|
| 1) Repair cost        | \$  | 4066.00 |
| 2) Loss Of Used 5DAYS |     | 300.00  |
|                       |     | -----   |
|                       | S\$ | 4366.00 |
|                       |     | =====   |

Thank you.

Yours faithfully

  
Jouis Seow  
Email: jouis@jinauto.com.sg



# LETTER OF AUTHORITY

To: Jin Auto Services Pte Ltd  
Block 14 Defu Lane 10  
#01-410/412  
Singapore 539195

Dear Sir

ACCIDENT INVOLVING SJX 8070A & SHC 85224 ON 2/8/19.

I/We, the owner of vehicle no: SJX 8070A hereby instruct and authorise you to commence repairs to the said vehicle.

I/We, hereby appoint you recover my damages sustained in the above accident.

Please recover the following:

1. Cost of repairs/Excess
2. Loss Of Use/Rental fees
3. Survey report fees

You may proceed to apply to the relevant authorities for all necessary reports/documents to enable you to process my claim. Thereafter, you may negotiate with the third party and or his insurers for a settlement. If a settlement cannot be reached, you may without referring to me, commence legal proceedings against third party on my behalf to recover my damages. The entire amount claimed shall belong and make payable to Jin Auto Services Pte Ltd absolutely.

I further authorize you to give an absolute discharge on my behalf and to sign discharge voucher(s), any other documents necessary or incidentals to the conduct and disposal of my/our above claims.

Yours faithfully

X



Name: CHEONG MUN KWONG

NRIC NO: S15 01 317 F

Address:

Dated:

**JIN AUTO SERVICES PTE LTD**

Blk 14 #01- 410/412 Defu Lane 10 Singapore 539195

Tel: 6289 8126 (24 hrs) Fax: 6287 0590

Email: jin@jinauto.com.sg

Company Reg. No: 200704370C GST Reg. No: 200704370C

## TAX INVOICE

M/s India International Insurance Pte Ltd.

Invoice No: 16864

Vehicle No: SJX 8070 A

Date: 22/8/19

[illegible]

N.B No responsibility will be accepted for any loss or damage to any Vehicles or parts left in this workshop for any reason whatsoever.

*E. & O. E.*

**ADD GST**

TOTAL

\$ 266-ω  
\$ 4066-ω



**JIN AUTO SERVICES PTE LTD**

# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

LKK Auto Consult

the Repairer of the

To survey before/after

To display damaged parts

Parts prices are subject to

Third party survey is on

No illegal modification(s)

Supplementary item(s)

is subject to final approval

Acknowledged by Repairer

Signature:

Date:

6/8/2019

Your ref :

M/S INDIA INT'L INSURANCE

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR: 5JX 8070A

## List Items

- |    |       |   |        |
|----|-------|---|--------|
| 1  | 1 PC  | FRONT RH DOOR                           |        |
| 2  | 1 PC  | FRONT RH FENDER                         |        |
| 3  | 1 PC  | FRONT HEADLAMP RH                       |        |
| 4  | 1 PC  | FRONT BUMPER                            | 846.15 |
| 5  | 1 SET | FRONT BUMPER CLIPS                      | 50.00  |
| 6  | 1 PC  | FRONT BUMPER RH RETAINER                | 65.50  |
| 7  | 1 PC  | FRONT RH FENDER SHIELD                  |        |
| 8  | 1 SET | FRONT RH FENDER SHIELD CLIPS            |        |
| 9  | 1 PC  | FRONT RH KNUCKLE ARM                    | 453.50 |
| 10 | 1 PC  | FRONT RH SHOCK ABSORBER                 | 357.35 |
| 11 | 1 PC  | FRONT RH KNUCKLE ARM BEARING            | 288    |
| 12 | 1 PC  | FRONT RH LOWER ARM                      | 366.08 |
| 13 | 1 PC  | TYRE RIM ( FRONT RH )                   |        |
| 14 |       | SPRAY PAINTING                          |        |
| 15 |       | CHECK WIRING                            |        |
| 16 |       | LABOUR CHARGE TO REMOVE AND RENEW PARTS |        |
| 17 |       | TO REMOVE AND REFIX UNDERCARRIAGE PART  |        |
| 18 |       | TUFF KOTE                               |        |
| 19 |       | WHEEL ALIGNMENT                         |        |

|          |    |          |        |
|----------|----|----------|--------|
| 1        | \$ | 1,600.97 | α      |
| 2        | \$ | 600.99   | —      |
| 3        | \$ | 633.96   | α      |
| 4        | \$ | 1,433.60 | —      |
| 5        | \$ | 70.00    | —      |
| 6        | \$ | 130.71   | —      |
| 7        | \$ | 160.97   | —      |
| 8        | \$ | 35.00    | —      |
| 9        | \$ | 800.99   | α      |
| 10       | \$ | 533.70   | α      |
| 11       | \$ | 488.96   | α      |
| 12       | \$ | 533.75   | α      |
|          | \$ | 7,023.60 |        |
| LESS 10% | \$ | (702.36) |        |
|          | \$ | 6,321.24 |        |
| 13       | \$ | 1,399.60 | 680.50 |
| 14       | \$ | 880.00   | 600    |
| 15       | \$ | 50.00    | 20     |
| 16       | \$ | 680.00   | 400    |
| 17       | \$ | 400.00   | 120    |
| 18       | \$ | 80.00    | 30     |
| 19       | \$ | 80.00    | 60     |
|          | \$ | 9,290.84 |        |

Not Allowed  
 1/5 #3800/  
 the pre. At the rep-  
 4 day.  
 6/8/18

3216.54  
 102  
 2894.88  
 4824.88



# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

14/8/2019

**M/S India Insurance**

**DEAR SIR / MADAM**

**SUPPLEMENTARY ITEM FOR SJX8070A**

01) REPROGRAMMING

11 \$ 280.00 X