LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis VEHICLE NO: SLR Silvent amount of the properties of the p	Amount SS
List Item: Signature: Date: 1PCS REAR WINDSCREEN MOULDING	
1PCS TAILGATE 953.93	550.20 S1100.80
2PCS TAILGATE TOP HINGES @\$48.20	17 \$96.40 _V
2PCS TAILGATE DAMPERS @\$192.10	17 \$384.20 X
1PCS TAILGATE WEATHERSTRIP	Yw(\$135.20
2PCS TAILGATE REFLECTORS @\$364.60	CNe \$729.20
1PCS TAILGATE 'VEZEL' EMBLEM	Ner \$56.20
1PCS TAILGATE REAR LOGO	11 \$38.50 X
1PCS TAILGATE OUTER TOP GARNISH	1~ \$315.20 ×
1PCS TAILGATE INNER LOCK	7n1 \$181.90
1PCS TAILGATE INNER TRIM BOARD	De/Z., \$368.20
1SET TAILGATE INNER TRIM BOARD CLIPS	Au \$50.00/
2PCS TAILLAMPS @\$415.20	Me \$930.40
1PCS REAR BUMPER 461.50	\$863.50
2PCS REAR BUMPER REFLECTORS @\$151.00	Mscna \$302.00 12C
2PCS REAR BUMPER SIDES @\$295.00	Z \$590.00 X
1SET REAR BUMPER CLIPS	NU \$39.00
1PCS REAR BUMPER LOWER UNDER COVER	\$266.50
1SET REAR BUMPER LOWER UNDER COVER-CLIPS	× \$45.00
1PCS REAR END PANEL	Sods \$514.00
1PCS REAR END PANEL TOP GARNISH	TWI \$86.40
1PCS REAR FLOOR PANEL //20./0	cramphelsec \$1330.20
1PCS REAR FLOOR PANEL TOP BOARD 20%	Torn \$335.20

FASTECH AUTO PTE LTD

VEHICLE NO: SLC 7169T

Qty	<u>Particular</u>				Amount S\$	
List It	em:					
1PCS	REAR FLOOR PANEL TOOLS SPONGE			0 4	\$326.90	
2PCS	REAR FENDERS @\$981.10			23	\$1962.20	ve.
2PCS	REAR FENDER OUTER PROTECTORS @\$172.40			-	\$344.80	
2PCS	REAR FENDER INNER TRIM BOARDS @\$366.50			1	\$733.00	
1PCS	REAR LOCK SENSOR	[201			\$225.10	
1PCS	REAR EXHAUST	(2004)	/	1	\$774.20 N	
1PCS	REAR EXHAUST HEAT SHIELD	197	/	11	\$774.20 A \$181.00 A	
2PCS	REAR EXHAUST MOUNTINGS @\$34.90		1	1	\$69.80	
List Item Total:					8/028	
						\$102 St
<u>Specia</u>	l Nett Item:					6482
1PCS	REAR WINDSCREEN SEALANT		/	nec	\$80.00 40 5.	N
1PCS	REAR LICENCE PLATE W/HOLDER		1	1	\$80.00 🗶	
1SET	REAR BUMPER REVERSE SENSOR				\$280.00 200	
1PCS	REAR END PANEL SEALANT		N	u	\$50.00	
1PCS	REAR FLOOR PANEL INSULATOR		1.		\$300.00 🗶	
Special	Nett Total:	* eu. *-			\$790.00 280	
	en e				V10	
Labour	Charac	a self assessed				
Labour	Charge:					
TO CHE	CK WIRING.	* *** * ** *** ***			\$80.00 30	
TO DISI	MANTLE & REPLACING REVERSE SENSOR.				\$80.00	
TO DISI	MANTLE & REFIX REAR WINDSCREEN.	man a consistencia con permanente del con-			\$150.00 120	
TO DISI	MANTLE & REFIX TAILGATE COMPONENTS.				\$100.00 60	

FASTECH AUTO PTE LTD

VEHICLE NO: SLC 7169T

Qty <u>Particular</u>	Amount S\$
Labour Charge:	
TO DISMANTLE & REFIX REAR EXHAUST.	\$100.00 🗶
TO DISMANTLE & REFIX SEAT, CUSHION, CUSHION UPHOLSTERY.	\$150.00 &
TO SPRAY RUST PROOFING.	\$120.00 /00
TO DSMANTLE & REFIX PETROL TANK.	\$100.00 60
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS.	\$2000.00 / 200
TO PUTTY & SPRAY PAINTING.	\$2000.00 1000
Labour Charge Total:	\$4880.00 2700

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$19,095.20

7-6482.24 5. N 290.03 10h-2700.00 10h-2700.00 102 1877.29