

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com EST/QUOTE NO. SQ005115

RCB. Reg. / GST Reg. No: 200810440N

LONPAC INSURANCE BHD

300 Beach Road 07 The Concourse

#17-04 SINGAPORE 199555

ATTENTION :

CONTACT : -

FAX NO: 6296 3767

DATE : 16/08/2019
ACCIDENT DATE : 25/07/2019
VEHICLE NO : PA9813S
CHASSIS/ENG.NO : JN1TG4E25Z0784556
VEHICLE MODEL : NISSAN URVAN
CLAIM NO :
POLICY NO :
REMARK : 9813LONPAC TP AGST
GBG195S

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							

							SUB-TOTAL: 0.00
** NETT PRICE **							
1	1	PC	REAR BUMPER	660.60	10	594.54	de 594.54
2	2	PC	REAR BUMPER SIDE RETAINER	17.40	10	15.66	re 31.32
3	1	PC	REAR TAILGATE	1,916.20	10	1,724.58	bt 1,724.58
4	1	PC	REAR TAILGATE LOCK	354.50	10	319.05	nn X 319.05
5	1	PC	REAR TAILGATE EMBLEM	59.70	10	53.73	re 53.73
6	1	PC	REAR TAILGATE 'URVAN' LOGO	19.50	10	17.55	re 17.55
7	1	PC	REAR TAILGATE 3.0DTI COMMONRAIL	19.50	10	17.55	re 17.55
8	1	PC	REAR END PANEL	453.00	10	407.70	Rx 407.70

							SUB-TOTAL 3,166.02
							2439.27
** SPECIAL NETT PRICE **							
1	1	PC	REAR NUMBER PLATE	35.00		35.00	nn X 35.00
2	1	PC	REAR BUMPER REVERSE SENSOR	280.00		280.00	200 280.00
3	1	PC	REAR TAILGATE 70KM/H STICKER	20.00		20.00	re 20.00
4	1	PC	REAR TAILGATE 11PAX STICKER	20.00		20.00	re 20.00
5	1	PC	REAR END PANEL OUTER PANEL	152.40		152.40	nn X 152.40
6	1	PC	REAR WINDSCREEN SEALANT	40.00		40.00	re 40.00

							SUB-TOTAL 547.40
							280

SAM

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com EST/QUOTE NO. SQ005115

RCB. Reg. / GST Reg. No: 200810440N

LONPAC INSURANCE BHD

300 Beach Road 07 The Concourse

#17-04 SINGAPORE 199555

ATTENTION :

CONTACT : -

FAX NO: 6296 3767

DATE : 16/08/2019
ACCIDENT DATE : 25/07/2019
VEHICLE NO : PA9813S
CHASSIS/ENG.NO : JN1TG4E25Z0784556
VEHICLE MODEL : NISSAN URVAN
CLAIM NO :
POLICY NO :
REMARK : 9813LONPAC TP AGST
GBG195S

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** WORK LABOUR **							
			TO CHECK WIRING	30.00		✓	30.00
			TO REMOVE & REFIX REAR WINDSCREEN	150.00		120	150.00
			TO APPLY ANTI RUST COATING	180.00		30	180.00
			TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS	800.00		500	800.00
			TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	850.00		800	850.00
SUB-TOTAL							2,010.00

1280

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Tanpin 77443749

16/8/19 @ 340pm

Resurvey after repair
5 days

sue/llk auto.com

2439.27

280

1280

3999.27

20% / 1/5 \$3200 #
5 days

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 5,723.42

ADD 7% GST. S\$ 400.64

GRAND TOTAL : S\$ 6,124.06

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.