

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 28 Aug 2019

Preliminary Advice

Vehicle No	: SJF345E	Accident Date	: 02/08/2019
Make	: AUDI Q5 SPORT	Policy No.	: 1900093775
Assignment Date	: 07/08/2019	Excess	: S\$1,000.00
Date of Inspection	: 06/08/2019	Est. Duration of Repair	: 9.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	89,504.00 (inclusive supp 1 + 2)
Revised Amount	:S\$	32,961.00 (inclusive supp 1 + 2)
Check Items (Estimated)	:S\$	35,655.00
Total	:S\$	68,616.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	230,000.00
COE / PARF Rebate	:S\$	86,230.00
Salvage Value	:S\$	
Margin for Repair	:S\$	143,770.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary 2 amount is \$ 550.00