



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

Claimant Insurer: Great Eastern General Insurance Limited

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/08/2019
Vehicle Reg. No.:	SLA9241P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LIM WEI LUN		
Make/Model:	TOYOTA ALPHARD, 2.4 (A)	Vehicle Reg. Date:	03/10/2011
Vehicle Colour:	BLACK	Chassis No:	JTEGD21H908185651
Engine No:	2AZH734362		
Odometer:	0 KM		
Paint Type:		Nett Item Discount:	10.00 %
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	-		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	4,332.60
Miscellaneous Items	11.00
Labour	1,990.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	6,333.60
+ GST 7.00% (\$)	443.35
Nett Amount (\$)	6,776.95

This claim is handled by: WEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Aug 2019)

Parts: M1-MPV TOYOTA ALPHARD 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Mova Automotive Pte Ltd/SLA9241P/06/08/2019 15:10

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT <i>bt</i>	25.00	0.00	*1,986.30 FL
2	1		*REAR WINDSCREEN SEALANT <i>nee</i>	0	0.00	*45.00 FS
3	1		*REAR BOOT EMBLEM <i>nee</i>	25.00	0.00	*79.20 FL
4	1		*REAR BOOT LAMP LH <i>X</i>	25.00	0.00	*326.30 FL
5	1		*REAR BOOT LOGO (ALPHARD) <i>nee</i>	25.00	0.00	*79.80 FL
6	1		*REAR BOOT LOCK <i>X</i>	25.00	0.00	*591.00 FL
7	1		*REAR BOOT WEATHERSTRIP <i>nee</i>	25.00	0.00	*222.00 FL
8	1		*REAR BUMPER <i>de</i>	25.00	0.00	*1,442.30 FL
9	10		*BUMPER CLIPS <i>nee</i>	25.00	0.00	*58.00 FL
10	1		*REAR PARKING SENSOR	25.00	0.00	*391.10 FL
11	1		*REFLECTOR LIGHT LH <i>con</i>	25.00	0.00	*84.60 FL
12	2		*TOW COVER <i>cut</i>	25.00	0.00	*78.20 FL
13	1		*END PANEL - REPAIR	25.00	0.00	-
14	1		*END PANEL TOP GARNISH - CHECK	25.00	0.00	-
15	1		*REAR SIDE GARNISH LOWER LH - CHECK	25.00	0.00	-
16	10		*SIDE GARNISH CLIPS <i>nee</i>	25.00	0.00	*72.80 FL
17	1		*REAR BUMPER RETAINER LH <i>nee</i>	25.00	0.00	*98.70 FL
18	1		*REAR TAIL LAMP LOWER BRACKET LH <i>?</i>	25.00	0.00	*206.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,761.80
- List Item Discount on L Items (\$\$)	1,429.20
Total Parts (\$\$)	4,332.60

Mova Automotive Pte Ltd/SLA9241P/06/08/2019 15:10. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO REPAIR REAR END PANEL, REAR FENDER LH, TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS, TO STRAIGHTEN & REALIGN ON ACCIDENT DAMAGED PARTS	New	500	600.00
2	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	600	750.00
3	TO INSPECT REAR TAIL LAMP WATER LEAKAGE TEST	New	X	40.00
4	TO RUST PROOF ON ACCIDENT DAMAGED PARTS	New	60	80.00
5	TO REMOVE REAR WINDSCREEN GLASS	New	120	150.00
6	TO REMOVE REAR BOOT TRIM, BOOT LOCK & OTHER ATTACHMENT PARTS	New	60	120.00
7	TO REMOVE REAR SIDE TRIM BOARD L+R, SPARE TYRE & OTHER ATTACHMENT PARTS	New	60	120.00
8	TO APPLY SEAL ON WELDING JOINT & NEW PARTS	New		50.00
9	TO REMOVE & REFIX REAR PARKING SENSOR	New	60	80.00

Gross Labour Cost (S\$)

1,990.00

Mova Automotive Pte Ltd/SLA9241P/06/08/2019 15:10. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rasul
 Hp 90010068
 5 days
 4/5
 07/08/19 @ 1450
 Resurvey after paint

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: