

ASS. REC. BY:

REF: CS/smo 19013821/kaf3n2

Special Instruction:

Surveilor: Kenneth

ASSIGNMENT (Office)

From (Person): Agnes Chan Shu Hui of SMD

Date/Time: 6.8.19 17.50p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JQH 2441

Insured:

SJH 9261T

at Workshop m/s Ae Auto

Tel:

6453 5654

of 160 Si Ming Drive #06-01

Policy No: D19mtpv01010927

Claim No: CMTD1903692

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31.7.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 7.8.19 9.25a.m

Person Contacted:

Doreen

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

JQH 2441 - X

SJH 9261T - X

21/8- @ 16:47 - Rensed via preli advise

24/8 612 @ 6100d Cabins Used: 9647.87; 61%

ASS. REC. BY:

REF:

SMO/

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6-10 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to  
EM not ready

RECEIVED 26 SEP 2019

Veh No:

JQH 244

Yr Regn:

08, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perodua

A12P

C.C.

1495

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

79193

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

PM 2 M50 23002210274

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

31/7/19

D.O.I.

19/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 26/9 typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

6100/-

Days Of Repair:

10

Resurvey No. of Trlp:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Fees:

Others

TOTAL

450

11

461

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 21 Aug 2019

**Preliminary Advice**

|                    |                                                                                             |                         |              |
|--------------------|---------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SJH9261T                                                                                  | Accident Date           | : 31/07/2019 |
| TP Vehicle No      | : JQH2441                                                                                   | Assignment Date         | : 06/08/2019 |
| Make               | : PERODUA ALZA                                                                              | Est. Duration of Repair | : 10.00      |
| Date of Inspection | : 19/08/2019                                                                                |                         |              |
| Inspection At      | : AE AUTO PTE LTD (HQ)<br>160 SIN MING DRIVE, #06-01, SIN MING AUTOCITY<br>SINGAPORE 575722 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages REAR portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 15,747.87 |
| Revised Amount              | :S\$ | 4,847.60  |
| Check Items (Estimated)     | :S\$ | 5,444.78  |
| Total                       | :S\$ | 10,292.38 |

Lump Sum Repair :S\$

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Survey on "WP"

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                                               |
|------|-------------|---------------|------------------------------------------------|---------|---------------|------------|------------------------------------------------------|
| Main | 01 Aug 2019 |               | 06 Aug 2019<br>17:50<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                          | Reference | Claim Details                                                                                             | Documents              | Show All                           |         |             |              |            |       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------------------------------------------------------------------------------------------------|------------------------|------------------------------------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>                                                                                        |           |                                                                                                           |                        |                                    |         |             |              |            |       |
| Insured:                                                                                                                                                                      |           | LAWRENCE LEE KHIN WEE, ID: S1547281B                                                                      |                        |                                    |         |             |              |            |       |
| Main Claimant:                                                                                                                                                                |           | MERVYN PEE ZE REN, ID: 940217010301                                                                       |                        |                                    |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                                                                             |           | JQH2441                                                                                                   | Date of Loss:          | 31/07/2019 17:00 - :59             |         |             |              |            |       |
| Claim Type:                                                                                                                                                                   |           | TP / CMTD1903692                                                                                          | Policy/Cover Note No.: | D19MTPV01010927<br>(Comprehensive) |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                                                                                   |           | SJH9261T                                                                                                  | Policy No. (Claimant): |                                    |         |             |              |            |       |
|                                                                                                                                                                               |           | Excess:                                                                                                   |                        |                                    |         |             |              |            |       |
| Repairer:                                                                                                                                                                     |           | Ae Auto Pte Ltd (HQ) 160 Sin Ming Drive, #06-01, Sin Ming AutoCity, 575722 Sin Ming - Tel:                |                        |                                    |         |             |              |            |       |
| Handling Insurer:                                                                                                                                                             |           | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327] |                        |                                    |         |             |              |            |       |
| Adjuster:                                                                                                                                                                     |           | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/08/2019]                         |                        |                                    |         |             |              |            |       |
| Driver/Custodian (Insured):                                                                                                                                                   |           | RYAN LEE JIACHEN (), NRIC: S9602448G, Tel: +6591134328 Email:                                             |                        |                                    |         |             |              |            |       |
| Adj Asg. Remarks:                                                                                                                                                             |           | WS: RYAN SOH 93825367 / 64535654                                                                          |                        |                                    |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                 |           |                                                                                                           |                        |                                    |         |             |              |            |       |
| There are no mail for this case.                                                                                                                                              |           |                                                                                                           |                        |                                    |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |           |                                                                                                           |                        |                                    |         |             |              |            |       |
| Due Date                                                                                                                                                                      | Priority  | Type                                                                                                      | Task Group             | Subject                            | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                   |           |                                                                                                           |                        |                                    |         |             |              |            |       |



# SINGAPORE POLICE FORCE



T/20190801/2113

1 of 3

Police Station Of Origin:  
Bukit Panjang North NPP  
27 Marsiling Drive #01-237 SINGAPORE  
730027  
Tel No: 1800-3689999

Report No. T/20190801/2113

## REPORT OF A TRAFFIC ACCIDENT

|                                                         |            |                                                                   |                              |                          |
|---------------------------------------------------------|------------|-------------------------------------------------------------------|------------------------------|--------------------------|
| Date/Time Report Made:<br>01/08/2019 15:36              |            | Vide Report No.:                                                  |                              | Station Diary No.:<br>27 |
| <b>Informant's Particulars</b>                          |            |                                                                   |                              |                          |
| Name of Informant:<br>MERVYN PEE ZE REN                 |            | Address:<br>61 JALAN RUSA 7 CENTURY GARDEN                        |                              |                          |
| ID Type / ID No.:<br>NEW MALAYSIAN IC /<br>940217015327 |            | Contact No.:<br>Home/Office: Mobile: 01128785045                  |                              |                          |
| Nationality:<br>MALAYSIAN                               |            | Email:                                                            |                              |                          |
| Sex:<br>Male                                            | Age:<br>25 | Date of Birth:<br>17/02/1994                                      | Type of Informant:<br>Driver |                          |
| Race:                                                   |            | Language:<br>English                                              | Institution / School Name:   |                          |
| Occupation:<br>Administration manager                   |            | Driving Licence Information:<br>Class: Date of Expiry: 17/02/2021 |                              |                          |

|                                                              |                               |                                    |                                            |                                    |
|--------------------------------------------------------------|-------------------------------|------------------------------------|--------------------------------------------|------------------------------------|
| <b>General Information of the Accident</b>                   |                               |                                    |                                            |                                    |
| Type of Accident:                                            | Non-Injury<br>Foreign Vehicle | Drink Drive:<br>No                 | Date/Time of Accident:<br>31/07/2019 17:45 | Type of Location:<br>Straight Road |
| Location:<br>Along Road 1<br>TAMPINES EXPRESSWAY             |                               |                                    |                                            |                                    |
| Towards Tuas. After Ikea                                     |                               |                                    |                                            |                                    |
| Weather:<br>Clear                                            |                               | Road Surface:<br>Dry               | Road Speed Limit:                          |                                    |
| Traffic Flow:<br>One Way                                     |                               | Traffic Control:<br>Not Controlled | Traffic Volume:<br>Heavy                   |                                    |
| Type of Collision:<br>Between Moving Vehicles - Head To Rear |                               |                                    | Anyone conveyed by ambulance:<br>No        |                                    |

| <b>Details of Vehicle Involved</b> |      |         |       |        |                  |                 |
|------------------------------------|------|---------|-------|--------|------------------|-----------------|
| Vehicle No.                        | Type | Make    | Model | Color  | Condition        | No of Passenger |
| JQH2441                            | Car  | PERODUA | ALZA  | Silver | Slightly Damaged | 3               |
| SJH9261T                           | Car  | HONDA   |       | Silver |                  | 0               |

|                                   |                                |
|-----------------------------------|--------------------------------|
| <b>Details of Person Involved</b> |                                |
| Any Pedestrian Involved: No       |                                |
| No. of Pedestrians Injured: NIL   | Use of Pedestrian Crossing: NA |



**SINGAPORE  
POLICE FORCE**



T/20190801/2113

2 of 3

Report No. T/20190801/2113

Police Station Of Origin:  
Bukit Panjang North NPP  
27 Marsiling Drive #01-237 SINGAPORE  
730027  
Tel No: 1800-3689999

**CONTINUATION OF REPORT**

|                                   |                   |                                        |                                          |
|-----------------------------------|-------------------|----------------------------------------|------------------------------------------|
| <b>Driver</b>                     |                   |                                        |                                          |
| Name                              | MERVYN PEE ZE REN | ID No.                                 | 940217015327                             |
| Related Vehicle                   | JQH2441 (Car)     | Contact No.                            | 01128785045                              |
| Hospital/Clinic                   | NIL               | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: 17/02/2021 |
| Date Treatment                    | NIL               | Date Discharge                         | NIL                                      |
| No. of Days granted Medical Leave | NIL               | Degree of Injury                       | NIL                                      |
| <b>Driver</b>                     |                   |                                        |                                          |
| Name                              | RYAN LEE JIACHEN  | ID No.                                 | S9602448G                                |
| Related Vehicle                   | SJH9261T (Car)    | Contact No.                            | 91134328                                 |
| Hospital/Clinic                   | NIL               | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL        |
| Date Treatment                    | NIL               | Date Discharge                         | NIL                                      |
| No. of Days granted Medical Leave | NIL               | Degree of Injury                       | NIL                                      |

**Brief Details.**

On 31/07/2019 at about 5.45pm along TPE towards Tuas (After Ikea), I was driving my car on the 1st lane when a car in front of mine was observed to be braking and came to a stop. I applied my brakes and stopped behind it as it was a heavy traffic. Suddenly, I felt my car was hit from the rear. I alighted from car and saw a car had hit onto the back of my vehicle. The other car driver alighted from his car. He told me that is either we settled it privately or make a police report. We exchanged particulars and contact number. My car sustained dented rear bumper area and the rear boot cannot be closed properly. No one claimed any injuries at the point of time. No government properties involved. No Ambulance and Traffic Police attended to us. On the same day, when I texted him, he told me that he had already made a police report.



SINGAPORE  
POLICE FORCE



T/20190801/2113

3 of 3

Police Station Of Origin:  
Bukit Panjang North NPP  
27 Marsiling Drive #01-237 SINGAPORE  
730027  
Tel No: 1800-3689999

Report No. T/20190801/2113

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

L /

Sgt 2 MUHAMMAD SHAFUDIN SHAH BIN  
EFFENDI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sgt 3 KOH CHEE SENG, KEVIN

Contact No.: 65472073

Authentication Stamp

NP168

Signature Of Informant:

*[Signature]*

Date/Time:

01/08/2019 15:36

Classification Of Case:

# JABATAN PENGANGKUTAN JALAN MALAYSIA

## PERAKUAN PENDAFTARAN KENDERAAN



NO PENDAFTARAN

**JQH2441**

No. Siri B **7076318**  
**cJjBoPHC**

Nama Pemunya Berdaftar

**LEE YOK ENG**

581014015528  
[MAL]

Alamat

**NO 61 JALAN RUSA 7 TAMAN CENTURY  
80250 JOHOR BAHRU JOHOR**

No. Enjin : **G17B64B**  
No. Casis : **PM2M502G002210274**  
Buatan : **PERODUA**  
Name Model : **ALZA - 1500 AV (AUTO)**  
Keupayaan Enjin : **1495**  
Bahan Bakar : **PETROL**  
Warna : **PERAK**  
Kelas Kegunaan : **PERSENDIRIAN-MOTOKAR INDIVIDU**  
Jenis Badan : **MOTOKAR PELBAGAI UTILITI**  
Tahun Dibuat : **2014**  
Tarikh Pendaftaran : **20/08/2014**  
Jenis Pemunya : **PERSENDIRIAN**  
Muatan Tempatan :  
Duduk : **7**  
Kadar Lesen :  
Kenderaan Motor : **8 bulan 12 bulan**  
**45.00 90.00**

B.D.M/B.G.K : -  
B.T.T. : -  
Berat Kerb : -  
R T M : -  
B.G.1 : -  
B.G.2 : -  
B.G.3 : -  
B.G.4 : -  
B.G.5 : -  
B.G.6 : -  
B.G.7 : -  
B.G.8 : -  
B.G.9 : -  
B.G.10 : -  
B.G.11 : -  
B.G.12 : -

Tandatangan Pemunya Berdaftar

Perakuan Pendaftaran ini dikeluarkan  
oleh Pengarah JPJ Negeri **JPJ NEGERI JOHOR**

### UNTUK KEGUNAAN PEJABAT

1. PEMASANGAN TEMPATAN
- 2.
3. HAK MILIK DITUNTUT OLEH : TOYOTA CAPITAL MALAYSIA S/B NO SIRI : 40014080650949
- 4.
- 5.
- 6.
- 7.
- 8.
- 9.
- 10.
- 11.
- 12.
- 13.

### NOTA PENTING

1. Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengarah Jabatan Pengangkutan Jalan (JPJ).
2. Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengarah JPJ jika terdapat sebarang perubahan.
3. Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membaharui lesen 60 hari sebelum tempohnya tamat.
4. Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengarah JPJ sekiranya kenderaan anda tidak berlesen.
5. Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
6. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
7. Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.

# BAYARAN-BAYARAN

1014611 20/08/2014 14:00:30 VEL01001 N ABOULLAH  
 045745 E 0 JCH2441 19/08/2015  
 2203000RM\*\*\*\*\*50.00 2103000RM\*\*\*\*\*150.00  
 209062 20/08/2015 08:49:21 VEL02502 N LUOMAN  
 076863 I 0 JCH2441 19/08/2016  
 2203000RM\*\*\*\*\*90.00 RM\*\*\*\*\*90.00  
 209062 21/08/2016 08:35:45 VEL02502 N LUOMAN  
 014791 I 0 JCH2441 20/08/2017  
 2203000RM\*\*\*\*\*90.00 RM\*\*\*\*\*90.00

## PERTUKARAN-PERTUKARAN MILIKAN DAN ALAMAT

|   |                            |                           |
|---|----------------------------|---------------------------|
|   | No. K.P./Def. Negeri/Sykt. | Terdahulu Pemilik Pemilik |
| 2 | No. K.P./Def. Negeri/Sykt. | Terdahulu Pemilik Pemilik |
| 3 | No. K.P./Def. Negeri/Sykt. | Terdahulu Pemilik Pemilik |
| 4 | No. K.P./Def. Negeri/Sykt. | Terdahulu Pemilik Pemilik |
| 5 | No. K.P./Def. Negeri/Sykt. | Terdahulu Pemilik Pemilik |

## REKOD-REKOD PEMERIKSAAN

|    |    |
|----|----|
| 1  | 6  |
| 2  | 7  |
| 3  | 8  |
| 4  | 9  |
| 5  | 10 |
| 6  | 11 |
| 7  | 12 |
| 8  | 13 |
| 9  | 14 |
| 10 | 15 |
| 11 | 16 |
| 12 | 17 |
| 13 | 18 |
| 14 | 19 |
| 15 | 20 |

**THE SCHEDULE**

ORIGINAL COPY

**JADUAL**

SALINAN ASAL

|                                                                |                                                                                                                                                                                                                                                                                                                               |                                |             |
|----------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|-------------|
| <b>Agent Code (Kod Ejen)</b>                                   | D08880-000 (JOHOR BHARU)<br>X PLOER SERVICES                                                                                                                                                                                                                                                                                  | <b>Date (Tarikh)</b>           | 18 AUG 2017 |
| <b>Replacing Cover Note No. (Mengantikan Nota Lindung No.)</b> | D08880-17000003                                                                                                                                                                                                                                                                                                               | <b>Receipt No. (No. Resit)</b> |             |
| <b>Policy No. (No. Polisi)</b>                                 | 501500091400-02                                                                                                                                                                                                                                                                                                               | <b>ACT (ACT)</b>               | RM 57.44    |
| <b>The Policyholder (Yang Dinsurakan)</b>                      | LEE YOK ENG                                                                                                                                                                                                                                                                                                                   | <b>Basic Premium</b>           | RM 1,570.32 |
| <b>Address (Alamat)</b>                                        | 61, JALAN RUSA 7, TAMAN CENTURY, 80250 JOHOR BAHRU, JOHOR DARUL TAKZIM                                                                                                                                                                                                                                                        | <b>Loading 0.00%</b>           | RM 0.00     |
| <b>Business Reg. No. (No. Sykt.)</b>                           |                                                                                                                                                                                                                                                                                                                               | <b>NCD 38.33%</b>              | RM 601.90   |
| <b>I/C No. New (No. K/P Baru)</b>                              | 581014-01-5528                                                                                                                                                                                                                                                                                                                | <b>Less: Voluntary Excess</b>  | RM 0.00     |
| <b>Old I/C No. (No. K/P Lama)</b>                              | 5505162                                                                                                                                                                                                                                                                                                                       | <b>Extra Cover</b>             | RM 211.25   |
| <b>Business / Profession (Perniagaan / Pekerjaan)</b>          | OTHERS                                                                                                                                                                                                                                                                                                                        | <b>Less: Renewal Bonus</b>     | RM 58.98    |
| <b>Hire Purchase Owners (Pemilik Sewa Beli)</b>                |                                                                                                                                                                                                                                                                                                                               | <b>Gross Premium</b>           | RM 1,120.69 |
| <b>Employer / Lessors (Majikan / Pemajak)</b>                  |                                                                                                                                                                                                                                                                                                                               | <b>GST: 6.00%</b>              | RM 57.24    |
| <b>Period of Insurance (Tempoh Insurans)</b>                   | (a) From (Dari) : 21 AUG 2017 To (Hingga) : 20 AUG 2018<br>Time : 12:01AM To Midnight (Tengah Malam - dua tengah)<br>(b) Any subsequent period for which you shall pay and we shall agree to accept a renewal premium<br>Sebarang tempoh selanjutnya untuk mana anda membayar dan kami bersetuju menerima premium pembaharuan | <b>Stamp Duty (DUTI SETEM)</b> | RM 10.00    |
|                                                                |                                                                                                                                                                                                                                                                                                                               | <b>Total Premium (JUMLAH)</b>  | RM 1,197.93 |

**The Motor Vehicle**

Any of the following (Mana - mana daripada yang berikut):

**Kenderaan Motor**

| Registration No.<br>(No. Pendaftaran) | Make<br>(Buat & Jenis Badan) | Type of Body<br>(Jenis Badan) | Cubic Capacity<br>(Keupayaan Enjin) | Year of Manufacture<br>(Tahun Dipekerti) | Seating Capacity<br>Including Driver<br>(Muatan Tempat Duduk<br>termasuk Pemandu) | Your Estimate of Value<br>Including Accessories<br>(Nilai Anggaran Anda<br>termasuk Aksesori) |
|---------------------------------------|------------------------------|-------------------------------|-------------------------------------|------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|
| JQH2441                               | PERODUA<br>ALZA<br>1.5       | MPV                           | 1495.00<br>CC                       | 2014                                     | 7                                                                                 | RM53,000.00                                                                                   |

Date of Signature of Proposal and Declaration  
(Tarikh Cadangan dan Pengisytiharan)

EXCESS - All Claims: RM 0.00  
(LEBBHAN)

Engine (Enjin): G17B64B  
CHASSIS (KASIS): PM2M502G002210274

Subject to the terms and conditions of the Policy and endorsement as numbered below:  
Tertakluk kepada terma dan syarat-syarat polisi dan pengesahan seperti disenaraikan di bawah:

Named Driver: 1) THE INSURED 2) PEE POH HAI

Include Endorsement No: 02,106,21,72,89,FINANCIALSERVICESACT2013,87 W1

**Additional Extra Coverage/Endorsements :-**

| Code Description                                      | Value   | Premium |
|-------------------------------------------------------|---------|---------|
| 02 LEGAL LIABILITY TO PASSENGERS                      | 0.00    | 53.75   |
| 72 LEGAL LIABILITY OF PASSENGERS FOR NEGLIGENT ACTS   | 0.00    | 7.50    |
| 89 BREAKAGE OF GLASS IN WINDSCREEN, WINDOW OR SUNROOF | 1000.00 | 150.00  |

**Art 87 - Agreed Value**

We will pay to you the agreed amount as specified in the Schedule of the policy in the event Your Vehicle is stolen or totally destroyed during the Period of Insurance provided we are liable to pay for such loss or destruction under the Terms and Conditions of Our policy. Subject otherwise to the Terms of this Policy.

**LEGISLATION:-**

Road Transport Act, 1967 (Malaysia) Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore Motor Vehicles (Third Party Risks and Compensation) Rules (Republic of Singapore) Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam (the reference to legislation under the heading "Avoidance of Certain Terms and Right of Recovery" is limited to Section 94, 95 and 96 of the Road Transport Act 1967 (Malaysia) Section 7, 8 and 9 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

**UNDANG - UNDANG:-**

Akta Pengangkutan Jalan Raya, 1967 Malaysia, Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura, Peraturan Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) 1960 Republik Singapura, Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam (rujukan kepada undang-undang di bawah tajuk "Pengekangan Peraturan - Peraturan Dan Hak Tuntutan Tertentu" adalah terhad kepada Seksyen 94, 95 dan 96 Akta Pengangkutan Jalan Raya, 1967 Malaysia, Seksyen 7, 8 dan 9 Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura, dan Seksyen 7 Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam).

**Limits of Liability:-**

Had Tanggungan:-

Limit of the amount of Our Liability under Section B-1(a) ..... Unlimited

Had jumlah tanggungan Kami di bawah Seksyen B-1(a) .....

Limit of the amount of Our Liability under Section B-1(b) ..... RM3,000,000.00

Had jumlah tanggungan Kami di bawah Seksyen B-1(b) .....

**Limitation as to Use**

Had Penggunaan

As shown in the Certificate of Insurance  
Seperti ditunjukkan dalam Slip Insurans

Geographical Area  
Had Wilayah

Malaysia, Republic of Singapore and Negara Brunei Darussalam  
Malaysia, Republik Singapura dan Negara Brunei Darussalam

For and on behalf of / Untuk dan bagi pihak  
Zurich Insurance Malaysia Berhad



David Fike

Chief Executive Officer / Ketua Pegawai Eksekutif

*Urgent  
Finalize*

AE AUTO PTE LTD  
160, Sin Ming Drive  
Sin Ming Auto City #06-01  
Singapore 575722  
Tel: 64535654, 64591630  
Fax: 64591698

*Not Authorized  
6/1 Sep 8?  
Recovery After Repair  
6-10 days*

Date: 19/08/2019

QUOTATION - THIRD PARTY CLAIM

SOMPO INSURANCE SINGAPORE PTE LTD

Attn: Motor Claim Department Officer In Charge

Accident on: 31/07/2019

Claim : Third Party Claim  
Veh. No : JQH 2441  
Model : PERODUA ALZA  
Insured Ins. ZURICH

| QTY  | PARTICULARS                          | AMOUNT                 | SURVEYOR     |
|------|--------------------------------------|------------------------|--------------|
|      | Your Insurer Vehicle No : SJH 9261 T |                        |              |
| 1    | TAILGATE                             | \$ <i>By</i> 780.45    | ✓            |
| 1    | TAILGATE LOCK                        | \$ 225.00              | ✓            |
| 1    | TAILGATE LOCK LOWER SENSOR           | \$ 181.00              | ?            |
| 1    | TAILGATE TRIM BOARD                  | \$ <i>Ln</i> 580.00    | X            |
| 1    | TAILGATE OUTER GARNISH               | \$ <i>Ln</i> 380.00    | X            |
| 1    | TAILGATE W/SCREEN MOULDING           | \$ <i>Ln</i> 140.00    | ✓            |
| 1    | CENTER LOGO                          | \$ <i>Ln</i> 58.00     | X            |
| 1    | ALZA EMBLEMA/IVANEED EMBLEM          | \$ <i>Ln</i> 55.00     | X            |
| 2    | REAR CORNER PANELS                   | \$ <i>Ln</i> 640.80    | X            |
| 2    | TAILLAMPS                            | \$ <i>Ln</i> 857.00    | X            |
| 2    | TAILLAMP PANELS                      | REPAIR                 |              |
| 2    | REAR FENDERS                         | REPAIR                 |              |
| 2    | REAR FENDER INNER SIDE TRIMS         | \$ 777.80              | ?            |
| 2    | REAR FENDER UNDERSHIELDS             | \$ <i>Ln</i> 283.00    | X            |
| 1    | REAR BUMPER                          | \$ <i>By</i> 580.45    | —            |
| 10   | REAR BUMPER CLIPS                    | \$ <i>Ln</i> 35.00     | —            |
| 2    | REAR BUMPER SIDE RETAINERS           | \$ <i>CM</i> 220.00    | —            |
| 2    | REAR BUMPER BRACKETS                 | \$ 280.00              | ?            |
| 2    | REAR BUMPER SENSORS                  | \$ <i>Short</i> 442.60 | <i>2005m</i> |
| 1SET | REAR BUMPER SENSOR CABLE             | \$ 323.50              | ?            |
| 1    | REAR TOW COVER                       | \$ <i>Ln</i> 181.00    | X            |
| 2    | REAR BUMPER REFLECTORS               | \$ <i>Ln</i> 280.00    | X            |
| 1    | END PANEL                            | \$ <i>By</i> 458.60    | ✓            |
| 1    | END PANEL TOP GARNISH                | \$ <i>Ln</i> 229.00    | ?            |
| 1    | END PANEL TOP LATCH                  | \$ <i>Ln</i> 68.00     | X            |
| 1    | FLOOR PANEL                          | \$ 980.78              | ?            |
| 1    | FLOOR PANEL TOP BOARD                | \$ 477.85              | ?            |
| 1    | FLOOR PANEL TRAY                     | \$ 552.60              | ?            |
| 1    | REAR EXHAUST PIPE                    | \$ 398.45              | ?            |
| 1    | SPARE TYRE BRACKET                   | \$ <i>Ln</i> 336.25    | X            |
|      |                                      | \$ 10,797.63           |              |
|      | Less 10%                             | \$ 1,079.76            |              |
|      |                                      | \$ 9,717.87            |              |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AE AUTO PTE LTD  
160, Sin Ming Drive  
Sin Ming Auto City #06-01  
Singapore 575722  
Tel: 64535654, 64591630  
Fax: 64591698

*Not Notified*  
*11 Sep @ 6100h*  
*Recovery After Rain*

Date : 19/08/2019

QUOTATION -THIRD PARTY CLAIM

*-10 days*

SOMPO INSURANCE SINGAPORE PTE LTD

Attn: Motor Claim Department , Officer In Charge

Claim : Third Party Claim  
Veh. No : JQH 2441  
Model : PERODUA ALZA  
Insured Ins: ZURICH

Accident on : 31/07/2019

| QTY  | PARTICULARS                                 | AMOUNT                | SURVEYOR     |
|------|---------------------------------------------|-----------------------|--------------|
|      | <u>Your Insurer Vehicle No : SJH 9261 T</u> |                       |              |
| 1    | TAILGATE                                    | \$ <i>By</i> 780.45   | ✓            |
| 1    | TAILGATE LOCK                               | \$ 225.00             | ✓            |
| 1    | TAILGATE LOCK LOWER SENSOR                  | \$ <i>Ln</i> 181.00   | X            |
| 1    | TAILGATE TRIM BOARD                         | \$ <i>Ln</i> 580.00   | X            |
| 1    | TAILGATE OUTER GARNISH                      | \$ <i>Ln</i> 380.00   | X            |
| 1    | TAILGATE W/SCREEN MOULDING                  | \$ <i>Ln</i> 140.00   | ✓            |
| 1    | CENTER LOGO                                 | \$ <i>nn</i> 58.00    | X            |
| 1    | ALZA EMBLEMAIVANEED EMBLEM                  | \$ <i>nn</i> 55.00    | X            |
| 2    | REAR CORNER PANELS                          | \$ <i>nn</i> 640.80   | X            |
| 2    | TAILLAMPS                                   | \$ <i>Ln</i> 857.00   | X            |
| 2    | TAILLAMP PANELS                             | REPAIR                |              |
| 2    | REAR FENDERS                                | REPAIR                |              |
| 2    | REAR FENDER INNER SIDE TRIMS                | \$ <i>Ln</i> 777.80   | X            |
| 2    | REAR FENDER UNDERSHIELDS                    | \$ <i>Ln</i> 283.00   | X            |
| 1    | REAR BUMPER                                 | \$ <i>By</i> 580.45   | —            |
| 10   | REAR BUMPER CLIPS                           | \$ <i>nn</i> 35.00    | —            |
| 2    | REAR BUMPER SIDE RETAINERS                  | \$ <i>cm</i> 220.00   | —            |
| 2    | REAR BUMPER BRACKETS                        | \$ <i>nn</i> 280.00   | X            |
| 2    | REAR BUMPER SENSORS                         | \$ <i>shan</i> 442.60 | <i>2005n</i> |
| 1SET | REAR BUMPER SENSOR CABLE                    | \$ <i>Ln</i> 323.50   | ✓            |
| 1    | REAR TOW COVER                              | \$ <i>Ln</i> 181.00   | X            |
| 2    | REAR BUMPER REFLECTORS                      | \$ <i>Ln</i> 280.00   | X            |
| 1    | END PANEL                                   | \$ <i>By</i> 458.60   | ✓            |
| 1    | END PANEL TOP GARNISH                       | \$ <i>DIT</i> 224.50  | ✓            |
| 1    | END PANEL TOP LATCH                         | \$ <i>nn</i> 68.00    | X            |
| 1    | FLOOR PANEL                                 | \$ <i>By</i> 980.78   | ✓            |
| 1    | FLOOR PANEL TOP BOARD                       | \$ <i>Ln</i> 477.85   | X            |
| 1    | FLOOR PANEL TRAY                            | \$ <i>cm</i> 552.60   | ✓            |
| 1    | REAR EXHAUST PIPE                           | \$ <i>By</i> 398.45   | ✓            |
| 1    | SPARE TYRE BRACKET                          | \$ <i>By</i> 336.25   | ✓            |
|      |                                             | \$ 10,797.63          |              |
|      | Less 10%                                    | \$ 1,079.76           |              |
|      |                                             | \$ 9,717.87           |              |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AE AUTO PTE LTD  
160, Sin Ming Drive  
Sin Ming Auto City #06-01  
Singapore 575722  
Tel: 64535654, 64591630  
Fax: 64591698

| S/NETT |                                                                                        |              |          |
|--------|----------------------------------------------------------------------------------------|--------------|----------|
|        | REAR BUMPER LOWER SKIRTING                                                             | \$ 1,200.00  | 800.00   |
|        | REAR W/SCREEN SEALANT                                                                  | \$ 140.00    | 40.00    |
|        | SPARE TYRE                                                                             | \$ 480.00    | X        |
|        | TOTAL S/N :                                                                            | \$ 1,820.00  |          |
|        | TOTAL PARTS :                                                                          | \$ 11,537.87 |          |
| QTY    | LABOUR                                                                                 | AMOUNT       | SURVEYOR |
|        | Balance b/f                                                                            | \$ 11,537.87 |          |
|        | REAR LABOUR CHARGE                                                                     |              |          |
|        | Labour charges, cutting , welding , repair, replace align adjust on rear accident area | \$ 1,400.00  | 720.00   |
|        | To do spray painting on accident affected area, inner and outer                        | \$ 1,400.00  | 100.00   |
|        | To do anti rust                                                                        | \$ 120.00    | 90.00    |
|        | To do sealant seal gap, waterproofing for cutting area                                 |              | NPA      |
|        | Checking wiring system, lock switch etc                                                | \$ 100.00    | 20.00    |
|        | Replace sensor and sensor cable                                                        | \$ 100.00    | 30.00    |
|        | Replace rear exhaust                                                                   | \$ 120.00    | 60.00    |
|        | Remove refix rear w/screen                                                             | \$ 140.00    | 120.00   |
|        | Transfer tailgate parts to another tailgate                                            | \$ 100.00    | 60.00    |
|        | To remove refix, replace garnish, side trims, car seat, upholstery etc                 | \$ 380.00    | 100.00   |
|        | To do rear body chassis alignment                                                      | \$ 350.00    | X        |
|        | Total Labour :                                                                         | \$ 4,210.00  |          |
|        | Total Parts & Labour :                                                                 | \$ 15,747.87 |          |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19013821/KTF3N2

Date: 30/09/2019

## REFERENCE

|                       |                                     |                      |                 |
|-----------------------|-------------------------------------|----------------------|-----------------|
| Handling Insurer:     | Sompo Insurance Singapore Pte. Ltd. | Policy No:           | D19MTPV01010927 |
| Claimant Vehicle No : | JQH2441                             | Insured Vehicle No : | SJH9261T        |
| Date of Loss:         | 31/07/2019                          | Nature of Claim:     | TP              |
|                       |                                     | Claim No:            | CMTD1903692     |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | JQH2441                      | Engine No:  | G17B64B           |
| Make & Model:               | PERODUA ALZA, 1.5 AV (A)     | Chassis No: | PM2M502G002210274 |
| Reg. Date:                  | 20/08/2014 (Man. Year: 2014) | Odometer:   | 79193 km          |
| Colour:                     | Metallic Silver              |             |                   |
| Engine Capacity:            | 1495 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (\$\$):         | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 195/55R15    | Rear Tyre Size:  | 195/55R15    |
| Front Left Side:  | Hankook 7 mm | Rear Left Side:  | Hankook 6 mm |
| Front Right Side: | Hankook 7 mm | Rear Right Side: | Hankook 6 mm |

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

|                                           | Repairer's       | Adjuster's      | Difference      | Diff %       |
|-------------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                                     | 11,537.87        | 5,770.02        | 5,767.85        | 49.99        |
| Miscellaneous Items                       | 0.00             | 0.00            | 0.00            |              |
| Labour                                    | 4,210.00         | 2,700.00        | 1,510.00        | 35.87        |
| Paintwork Labour                          | 0.00             | 0.00            | 0.00            |              |
| Towing                                    | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (\$\$)</b>      | <b>15,747.87</b> | <b>8,470.02</b> | <b>7,277.85</b> | <b>46.21</b> |
| <b>Approved Total (Overridden) (\$\$)</b> |                  | <b>6,100.00</b> |                 |              |
| <b>Nett Amount (\$\$)</b>                 | <b>15,747.87</b> | <b>6,100.00</b> | <b>9,647.87</b> | <b>61.26</b> |

## INSPECTION

|                     |            |                                                                                                            |
|---------------------|------------|------------------------------------------------------------------------------------------------------------|
| Date of Assignment: | 06/08/2019 |                                                                                                            |
| Date Inspected:     | 19/08/2019 | Inspected At: Ae Auto Pte Ltd (HQ)<br>160 Sin Ming Drive, #06-01, Sin Ming<br>AutoCity<br>Singapore 575722 |

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

|                      |                                                                                                                                                                              |                                                           |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------|
| <b>Reference</b>     |                                                                                                                                                                              |                                                           |
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 30 Sep 2019)             |
| <b>Parts:</b>        | M1-MPV                                                                                                                                                                       | PERODUA ALZA 1.5 AV (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                         |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for JQH2441)                                                                                                                                     |                                                           |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                           |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                           |

## Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition     | Repairer's  | Amount     |
|-----|-----|----------|-------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *TAILGATE                     | Bent          | 780.45 FL   | *780.45 FL |
| 2   | 1   |          | *TAILGATE LOCK                | Dented        | 225.00 FL   | *225.00 FL |
| 3   | 1   |          | *TAILGATE LOCK LOWER SENSOR   | Serviceable   | 181.00 FL   | *- FL      |
| 4   | 1   |          | *TAILGATE TRIM BOARD          | Serviceable   | 580.00 FL   | *- FL      |
| 5   | 1   |          | *TAILGATE OUTER GARNISH       | Serviceable   | 380.00 FL   | *- FL      |
| 6   | 1   |          | *TAILGATE W/SCREEN MOULDING   | Necessary     | 140.00 FL   | *140.00 FL |
| 7   | 1   |          | *CENTER LOGO                  | Not Necessary | 58.00 FL    | *- FL      |
| 8   | 1   |          | *ALZA EMBLEMA/IVANEED EMBLEM  | Not Necessary | 55.00 FL    | *- FL      |
| 9   | 2   |          | *REAR CRONER PANELS           | Repair        | 640.80 FL   | *- FL      |
| 10  | 2   |          | *TAILLAMPS                    | Serviceable   | 857.00 FL   | *- FL      |
| 11  | 2   |          | *TAILLAMP PANELS (NPA)        | Repair        | 0.00 FL     | *- FL      |
| 12  | 2   |          | *REAR FENDERS (NPA)           | Repair        | 0.00 FL     | *- FL      |
| 13  | 2   |          | *REAR FENDER INNER SIDE TRIMS | Serviceable   | 777.80 FL   | *- FL      |
| 14  | 2   |          | *REAR FENDER UNDERSHIELDS     | Serviceable   | 283.00 FL   | *- FL      |
| 15  | 1   |          | *REAR BUMPER                  | Bent          | 580.45 FL   | *580.45 FL |
| 16  | 10  |          | *REAR BUMPER CLIPS            | Necessary     | 35.00 FL    | *35.00 FL  |
| 17  | 2   |          | *REAR BUMPER SIDE RETAINERS   | Cracked       | 220.00 FL   | *220.00 FL |
| 18  | 2   |          | *REAR BUMPER BRACKETS         | Repair        | 280.00 FL   | *- FL      |
| 19  | 1   |          | *SET REAR BUMPER SENSOR CABLE | Cut           | 323.50 FL   | *323.50 FL |
| 20  | 1   |          | *REAR TOW COVER               | Serviceable   | 181.00 FL   | *- FL      |
| 21  | 2   |          | *REAR BUMPER REFLECTORS       | Serviceable   | 280.00 FL   | *- FL      |
| 22  | 1   |          | *END PANEL                    | Bent          | 458.60 FL   | *458.60 FL |
| 23  | 1   |          | *END PANEL TOP GARNISH        | Distorted     | 224.50 FL   | *224.50 FL |
| 24  | 1   |          | *END PANEL TOP LATCH          | Repair        | 68.00 FL    | *- FL      |
| 25  | 1   |          | *FLOOR PANEL                  | Bent/Buckled  | 980.78 FL   | *980.78 FL |
| 26  | 1   |          | *FLOOR PANEL TOP BOARD        | Serviceable   | 477.85 FL   | *- FL      |
| 27  | 1   |          | *FLOOR PANEL TRAY             | Cracked       | 552.60 FL   | *552.60 FL |
| 28  | 1   |          | *REAR EXHAUST PIPE            | Bent          | 398.45 FL   | *398.45 FL |
| 29  | 1   |          | *SPARE TYRE BRACKET           | Bent          | 336.25 FL   | *336.25 FL |
| 30  | 2   |          | *SET REAR BUMPER SENSORS      | Shorted       | 398.34 FS   | *200.00 FS |
| 31  | 1   |          | *REAR BUMPER LOWER SKIRTING   | Buckled       | 1,200.00 FS | *800.00 FS |
| 32  | 1   |          | *REAR W/SCREEN SEALANT        | Necessary     | 140.00 FS   | *40.00 FS  |
| 33  | 1   |          | *SPARE TYRE                   | Serviceable   | 480.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>12,573.37</b> | <b>6,295.58</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | <b>1,035.50</b>  | <b>525.56</b>   |
| <b>Total Parts (\$\$)</b>                                  | <b>11,537.87</b> | <b>5,770.02</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                            | Lab.Type | Repairer's      | Amount          |
|--------------------------------|----------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                        |          |                 |                 |
| 1                              | LABOUR<br>CHARGES,CUTTING,WELDING,REPAIR,REPLACE ALIGN<br>ADJUST ON REAR ACCIDENT AREA | New      | 1,400.00        | 1,200.00        |
| 2                              | TO DO SPRAY PAINTING ON ACCIDENT AFFECTED<br>AREA,INNER AND OUTER                      | New      | 1,400.00        | 1,000.00        |
| 3                              | TO DO ANTI RUST                                                                        | New      | 120.00          | 90.00           |
| 4                              | CHECKING WIRING SYSTEM,LOCK SWITCH ETC                                                 | New      | 100.00          | 20.00           |
| 5                              | REPLACE SENSOR AND SENSOR CABLE                                                        | New      | 100.00          | 50.00           |
| 6                              | REPLACE REAR EXHAUST                                                                   | New      | 120.00          | 60.00           |
| 7                              | REMOVE REFIX REAR W/SCREEN                                                             | New      | 140.00          | 120.00          |
| 8                              | TRANSFER TAILGATE PARTS TO ANOTHER TAILGATE                                            | New      | 100.00          | 60.00           |
| 9                              | TO REMOVE REFIX,REPLACE GARNISH,SIDE<br>TRIMS,CAR SEAT,UPHOLSTERY ETC                  | New      | 380.00          | 100.00          |
| 10                             | TO DO REAR BODY CHASSIS ALIGNMENT                                                      | New      | 350.00          | 0.00            |
| 11                             | TO DO SEALANT SEAL GAP,WATERPROOFING FOR<br>CUTTING AREA (NPA)                         | New      | 0.00            | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |                                                                                        |          | <b>4,210.00</b> | <b>2,700.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >