From (Person): 61	ion Pau Luong	of	NMENT (Office)	I	Date/Time: 1.0.19 14:39 P
Estimated Cost:			Bill to:		
OD TP WS/TI	RES / OD RES / EV		IV / CS	*	toc (41-V
To Inspect Vehicle	No: SJC 249	FE		Insured:	FBG 60704
at Workshop m/s_				Tel:	62723872
of BIK 1008 #	01-04/06/ Bu	kil mora			(V)
Policy No: D18	MMC010049	17	Claim No:	(MTD)	903797
Sum Insured:			Excess:		
Make of Veh:					D.O.A. 5.8.2019
(Client's Record)		vip"			
	P. / REV 24 HRS	1	0.000		H.O.D. Endorsement:
Date/Time: 4.4	5.19 2.42p.m	Person Conta	cted: Shu an	V	ehicle INLOUT
Date/Time A		/ \ Ter			
The second secon	tion/Instruction ()		INVITE.		
			6 . 70		
					DOA -01/07/2019
18/19/0/11	slan varised	to an	oh fau Loon	p vin b	Menuen,
idlatia.	3.29M Pasul	Anless	sed with K	ione us	1 8 2650, 5 Says.
10/9/10					

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Attn:

GNOH PAU LOONG

Date:

27 Aug 2019

Preliminary Advice

Insured Vehicle No : FBG6070Y

TP Vehicle No

: SJC2496E

Accident Date

: 05/08/2019

Make

: MITSUBISHI DELICA

Assignment Date

: 07/08/2019

Est. Duration of Repair

: 5.00

Inspection At

Date of Inspection : 26/08/2019

: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) BLK 1008, #01-04/06/08/94, BUKIT MERAH LANE 3

SINGAPORE 159722

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,087.90
Revised Amount	:S\$	3,197.40
Check Items (Estimated)	:S\$	440.10
Total	:S\$	3,637.50

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindlet us have your authorisation.	У

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	07 Aug 2019 07 Aug 2019 07 Aug 2019						New Assignment Cancel Case	
	Main	Refere	ence	Claim De	tails	Documents	Show All	
CLAIM SI	UBFOLDER DETAI	LS						
Insured:			ZAK BIN KASIM,		В			
Main Clain	nant:	KOH CHEE	HIANG, ID: SO	0183191		05/00/20	010 21:0050	
Vehicle Reg. No.:		SJC2496	JC2496E		Date of Loss:		05/08/2019 21:00 - :59 [138 Months From LTA Reg Date (Man Yr)]	
Claim Typ	e:	TP / CMT	TP / CMTD1903797		Policy/Cover Note No.:		D18MTMC01004917	
	q. No. (Insured):	FBG60701	FBG6070Y		. (Claimant):	SI19V01	SI19V01366/VPE/R04	
				Excess:				
Repairer:		Merah - Te	1: 62723892/64763	3333		10 8 8	rah Lane 3, 159722 Bukit	
Handling 1	Insurer:	Sompo In 63295217]		re Pte. Ltd. (HC	() - Tel: 6461 65	55 [Handled by G	NOH PAU LOONG -	
Claimant's	Insurer:	Liberty In	surance Pte Ltd ((HQ) - Tel: (65)	6221 8611		(0.0.10.1.0.)	
Adjuster:		LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561 [F	inal Rpt due 20/	/08/2019]	
Adj Asg. R	lemarks:	-PLEASE B	E INFORMED THAT	OUR INSURED F	AS NOT REPORT	ED THE ACCIDENT		
ASSOCIA	ATED MAIL RECEI	VED				View All	Compose Case Mail	
There are	no mail for this case	14						
Β	OCIATED TASKS				w All Search	Tasks Seasts	New Task Complete	

Shiau Chan (LKKAuto)

From:

Keong <keong@mova.com.sg>

Sent:

Wednesday, 18 September 2019 3:29 PM

To:

Rasul (LKKAuto); 'Enny'; suann@mova.com.sg; 'Annie Lim'

Cc:

'JIAYU'

Subject:

RE: SJC2496E Ready For Finalise

Dear Rasul

Confirmed ,Thanks

Best Regards, Goh Chai Hock (Keong) Claims Estimator Mova Automotive Pte Ltd HP: 96510098

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com] Sent: Wednesday, 18 September 2019 2:27 PM

To: Keong

Subject: RE: SJC2496E Ready For Finalise

Hi Keong,

Refer to attachment Finalised amount is \$2650 / 5 days lump sum Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Pava Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth. Print only when necessary.

From: Keong [mailto:keong@mova.com.sg] Sent: Monday, 16 September, 2019 6:52 PM

To: Rasul (LKKAuto)

Subject: SJC2496E Ready For Finalise

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

wner ID Type:	Singapore NRIC
Owner ID:	3191
Vehicle Details	
/ehicle No.:	SJC2496E
Vehicle to be Exported:	No
ntended Deregistration Date:	27 Aug 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	DELICA 2.4L CVT SUNROOF
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	4B12AT0793
Chassis No.:	JMYLTCV5W7J000110
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$31,765.00
Original Registration Date:	05 Feb 2008
First Registration Date:	05 Feb 2008
Transfer Count:	0
Actual ARF Paid:	\$34,942.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	<u>-</u>
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Feb 2023
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$25,289.00
COE Rebate Amount:	\$17,395.00
Total Rebate Amount:	\$17,395.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Aug 2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available.

	ACCIDENT STATEMENT
Date Of Report	06/08/2019 08:51
Date Of Accident	05/08/2019 21:00
Exact Location Of Accident	JUNCTON OF BISHAN ST 13 & BISHAN ST 11
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJC2496E
Insured/Policyholder	
Name Of Registered Owner	KOH CHEE HIANG
NRIC No	S0018319I
Email Address	EME@PACIFIC.NET.SG
Mobile Phone No	(LOCAL) +65-96324751
Alternative Phone No	OFFICE-62558149
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	DELICA 2.4L CVT SUNROOF
Exact Purpose for which vehicle was being used time of accident	d at
Are you claiming under your own insurance poli for repair to your vehicle?	icy NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI19V01366/VPE/R04
Cover Note Number	
Driver	
Name of Driver	KOH CHEE HIANG
NRIC No	S0018319I
Date Of Birth	13/08/1951
Occupation	INDOOR

11/07/1969 Date Of Driving Pass

50 YEARS AND 0 MONTHS Driving Experience

Gender MALE

Mobile Number (LOCAL) +65-96324751

Fax Number

OFFICE-62558149 Contact Number EMail Address EME@PACIFIC.NET.SG Address 4 KENSINGTON PARK DRIVE

#01-06

Postcode 557321

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

ellide

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLIDED INTO MOTORCYCLIST

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

YES

ambulance?

111596

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

Police Station Address

ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE

ROAD: 51 ANG MO KIO AVE 9, POSTCODE: 569784, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-4849999 - FAX NO: 62181399

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

VIDEO WITH OWNER

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBG6070Y

Vehicle Make/Model/Colour

Details Of Properties

MOTORCYCLE

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Page 2 of 20

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

* **

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties;
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

16 hr

6/8 09:00 gm

Date & Time:

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



A = 50c 24968 B = Motorbike FB660764

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

CENSE PLA	TE: SJ	c2496	2		ACCIDE	NT DATE &	TIME: 5-16	Aug 201	9 aro 09	1:03
DNTACT NU	MBER: 6	225 814	(0) 963	3247511					c. 111.5	
					STURET					
	pus	REPER	- 15	Pour	e Ilai)· 11T	7/20	1908 os	/2167	_
			197							
NOTE:	PLEASE	NOTE THA	T YOUR IN	SURER MA	VY HAVE 14	DAYS TIM	E FRAME FOI	R YOU TO SL	JBMIT AN	
							UR POLICY F			
O 1111 DO										
lease state:		101-101-101								

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:
6/8 09000

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:





Police Station Of Origin: Ang Mo Kio North N.P.C 51 Ang Mo Kio Avenue 9 SINGAPORE 569784

Report No. T/20190805/2167

1 of 3

Tel No: 1800-4849999

REPORT OF A TRAFFIC ACCIDENT

	ne Report N 19 23:24	lade:	Vide Report No.: E/20190805/0148	Station Diary No. 105	
Informa	nt's Partici	ulars			
	Informant: IEE HIANG		Address: 4 KENSINGTON PARK DRIV	VE #01-06 SINGAPORE 557321	
	/ ID No.; D / S00183	191	Contact No.: Home/Office:	Mobile: 96324751	
National SINGAP	ity: ORE CITIZ	EN	Email:		
Sex: Age: Date of Birth: Male 67 13/08/1951			Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name:	
Occupat	ion: y director	111011	Driving Licence Information: Class:	Date of Expiry:	

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 05/08/2019 21:00	Type of Location Straight Road	
Location: Along Road 1 BISHAN STR BISHAN STR Weather: Clear	70 70 70 70 70 C	Road Surface:		Road Speed Limit:	
		Traffic Control:		Traffic Volume: Light	
Traffic Flow:				Light	

Details of V	Details of Vehicle Involved					
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
FBG6070Y	Motorcycle				Slightly Damaged	0
SJC2496E	Car				Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/20190805/2167

Police Station Of Origin: Ang Mo Kio North N.P.C 51 Ang Mo Kio Avenue 9 SINGAPORE 569784 2 of 3 Report No. T/20190805/2167

Tel No: 1800-4849999

CONTINUATION OF REPORT

Driver			ESAL DO SES	A CONTRACTOR	Wales In	Service Services
Name	KOH CHEE HIANG			ID No.		S0018319I
Related Vehicle	SJC2496E (Car)			Contact	t No.	96324751
Hospital/Clinic	NIL		MS17	Class o Driving Licence Expiry I	. &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc		NIL	
No. of Days gran	ted Medical Leave	NIL	Degree o		NIL	

Brief Details.

On 5/8/19 at about 2103hrs I was driving along Bishan St 13 and was going to turn left into Bishan St 11 and as such I came to a complete stop. Awhile later a biker suddenly hit onto the rear right side of my vehicle as he did not see my car as he was looking at his maps. I then went to assist him and he was injured. As such TP and Ambulance was called. Ambulance then arrived and conveyed the rider to hospital. TP then attended to this incident case reference E/20190805/0148.

I was not injured. My In car camera had captured the incident. I am lodging this report as requested by TP.





Police Station Of Origin: Ang Mo Kio North N.P.C 51 Ang Mo Kio Avenue 9 SINGAPORE 569784 Tel No: 1800-4849999 3 of 3 Report No. T/20190805/2167

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:	Signature Of Informant:
Sgt 2 SHOBAN KUMAR S/O SELVARAJAN	Kun
Signature Of Interpreter: Not applicable	Date/Time: 05/08/2019 23:24
Officer In Charge Of Case:	Classification Of Case;
Sr Staff Sgt NOR HIDAYU BINTE ABDUL SAMAD Contact No.: 65476423	
Authentication Stamp	1/2 :



Main Office: No. 22, Jalan Kllang, Singapore 159419 Tel: 6476 3333 Fax: 6271 5891

Service Centre: Block 1008, Bukit Merah Lane 3. #01-04/06/08/115, Singapore 159722 Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314 www.mova.com.sg GST Reg. No: M2-0088864-2

Mova Spray Centre 2K Oven Spray Painting System

Power-M Automotive Pte Ltd

Specialise in Car Air-con Services, Car Audio & Hi-Fi System.

Hilton Car Rental Centre Hilton Auto Trading Dealing In New/Used Cars, Hire Purchase & Insurance,

TP INSURER:

Sompo Insurance Singapore Pte. Ltd. (HQ)

UNKNOWN

Liberty Insurance Pte Ltd Claimant Insurer:

PARTICULARS OF CLAIM

Ref. No: THIRD PARTY Claim Type:

Date of Loss:

05/08/2019 Policy No: Driveable? SJC2496E Vehicle Reg. No.:

UNKNOWN Party At Fault:

KOH CHEE HIANG Driver (TP):

05/02/2008 Vehicle Reg. Date: Make/Model: MITSUBISHI DELICA, 2.4 CVT (A)

Vehicle Colour: SILVER

JMYLTCV5W7J000110 4B12AT0793 Chassis No: Engine No:

0 KM Odometer:

Paint Type:

10.00 % List Item Discount: NO Total Loss?

Est. Duration of Repair (day) 7

PLEASE REFER TO THE SKETCH PLAN Description of Accident/Loss

MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) Present Location:

Amount **COST OF CLAIMS** 2,637.90 Parts 0.00 Miscellaneous Items 1,450.00 Labour 0.00 Paintwork Labour 0.00 Towing Gross Total (S\$) 4,087.90 286.15 + GST 7.00% (S\$) 4,374.05 Nett Amount (S\$)

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 07 Aug 2019)

Parts:

M1-MPV

MITSUBISHI DELICA 2.4 CVT (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SJC2496E)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES Validity:

marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Esti	mat	es	on	Par	ts

No.	Qty Part No.	Particulars	%Disc	%Depr	Amount
1	1	*TAILLAMP RH CA	10.00	0.00	*385.00 FL
2	2	*TAILLAMP CLIPS ALL	10.00	0.00	*12.00 FL
3	1	*TAILLAMP LOWER GARNISH RH	10.00	0.00	*153.00 FL
4	3	*TAILLAMP LOWER GARNISH CLIPS X 940	10.00	0.00	*18.00 FL
5	1	*REAR BUMPER SIDE RH 42	10.00	0.00	*378.00 FL
6	1	*REAR BUMPER SIDE BRACKET RH	10.00	0.00	*39.00 FL
7	1	*REAR BUMPER LOWER SUL -	10.00	0.00	*1,533.00 FL
8	1	*REAR BUMPER REFLECTOR RH 🗡	10.00	0.00	*38.00 FL
9	1	*REAR BUMPER SENSOR RH 7. X SVC	10.00	0.00	*336.00 FL
10	10	*REAR BUMPER CLIPS AL C	10.00	0.00	*39.00 FL
11	1	*REAR FENDER RH - REPAIR	10.00	0.00	8
12	1	*ROOF SIDE PANEL RH - REPAIR *	10.00	0.00	
13	1	*REAR PANEL - REPAIR X SVC	10.00	0.00	
F=Fr	anchise part, L=ListitemDisc				
		Sub Total (S\$)			2,931.00
		- List Item Discount on L Items (S\$)			293.10
		Total Parts (S\$)			2,637.90

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Property of the second	10000	45.17.20.00	STATE OF THE PARTY.	
- ctim	nator	on I	201	OHE
Estim	lates.	ULL	au	Jul

No	Particulars	Lab.Type		Amount	
<u>Lab</u> 1	our <u>Items</u> TO REPAIR ROOF SIDE PANEL RH, REAR FENDER RH, REAR BUMPER. REMOVE & REFIX DAMAGED PARTS STRAIGHTEN AND REALIGN AFFECTED AREAS	New	400	608.00	
2	TO SPRAY ROOF SIDE PANEL RH, REAR FENDER RH, REAR PANEL,REAR BUMPER, BUMPER SIDE, BUMPER LOWER AND AFFECTED AREAS	New	600	800.00	
3	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE	New		50.00	-
	Gross Lab	our Cost (S\$)		1,450.00	

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Resul 1 218/2 40 90010068 5 days 4/5 26/08/18 @ 1485 Resun after refer

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate Report

Ref. No:



Main Office: No. 22, Jalan Kllang, Singapore 159419 Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3, #01-04/06/08/115, Singapore 159722 Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314 www.mova.com.sg GST Reg. No: M2-0088864-2

Mova Spray Centre 2K Oven Spray Painting System

Power-M Automotive Pte Ltd Specialise in Car Air-con Services, Car Audio & Hi-Fi System.

Hilton Car Rental Centre Hilton Auto Trading Dealing in New/Used Cars, Hire Purchase & Insurance.

05/08/2019

TP INSURER:

Sompo Insurance Singapore Pte. Ltd. (HQ)

UNKNOWN

Odometer:

Claimant Insurer: Liberty Insurance Pte Ltd

PARTICULARS OF GLAIN

Claim Type:

THIRD PARTY

Policy No: Date of Loss: Vehicle Reg. No.: **SJC2496E** Driveable?

Party At Fault: UNKNOWN

Driver (TP):-KOH CHEE HIANG

Make/Model: MITSUBISHI DELICA, 2.4 CVT (A)

0 KM

Vehicle Reg. Date: 05/02/2008

Vehicle Colour: SILVER

Engine No: 4B12AT0793 Chassis No: JMYLTCV5W7J000110

Paint Type:

List Item Discount: 10.00 %

Total Loss? NO Est. Duration of Repair (day)

PLEASE REFER TO THE SKETCH PLAN Description of Accident/Loss

MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) Present Location:

COST OF CLAIMS Amount Parts 2,637,90 Miscellaneous Items 0.00 Labour 1,450.00 Paintwork Labour 0.00 Towing 0.00 Gross Total (S\$) 4,087.90 + GST 7.00% (S\$) 286.15 Nett Amount (S\$) 4,374.05

This claim is handled by: KEONG

Generaled using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR	DEVAILES
Referen	
Part Source:	: MRM-SG Version: 1.0 (Last Synchronised: 07 Aug 2019)
Parts: ·	M1-MPV MITSUBISHI DELICA 2.4 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJC2495E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	: Items/values not in reference catalogue are prefixed with an asterisk *.

-			-
-01	ima	toe or	n Parts
L-01	ullia	LES UI	I Falls

No. Qty Part No.	Particulars	%Disc	%Depr	Amount
1 1	*TAILLAMP RH CA	10.00	0,00	*385,00 FL
2 2	*TAILLAMP CLIPS W	10.00	0.00	*12,00 FL
3 1	TAILLAMP LOWER GARNISH RH	10.00	0.00	*153,00 FL
4 3	*TAILLAMP LOWER GARNISH CLIPS X SVC	10.00	0.00	X *18.00 FL
5 1	*REAR BUMPER SIDE RH . CA.	10.00	0.00	*378.00 FL
6 1	*REAR BUMPER SIDE BRACKET RH . K	10.00	0.00	*39.00 FL
7 1	*REAR BUMPER LOWER SUC	10.00	0.00	1,533.00 FL
8 1	REAR BUMPER REFLECTOR RH X SYC	10.00	0.00	38.00 FL
9 1	REAR BUMPER SENSOR RH ? XIVE DLOTO	10.00	0.00 ×	. 336.00 FL
10 10	*REAR BUMPER CLIPS ALC	10.00	0.00	*39.00 FL
11 1	*REAR FENDER RH - REPAIR	10.00	0.00	· · · · · · · · · · · · · · · · · · ·
12 1	*ROOF SIDE PANEL RH - REPAIR #	10.00	0.00	
13 1 F=Franchise part, L=ListHernDisc,	*REAR PANEL - REPAIR X SUC	10.00	0.00	*
# E	Sub Total (S\$) - List Item Discount on L Items (S\$)			2,931.00 293.10
	Total Parts (S\$)			2,637.90

Report was unsubmitted during this print-out, Generated using Merimen e-Claims IEAS

2539	2875.00
10%	287.50
2285.10	1000.00 - LB
Labor - 1050	\$ 3587.50
T- 3335,10	LS\$2750/-
2060	5 days
2668.08	2
45-2,650	
- 50	lays
1.	

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars	Lab.Type		Amount
Labour Items .		-3/4/	
1 TO REPAIR ROOF SIDE PANEL RH, REAR FENDER RH, REAR BUMPER. REMOVE & REFIX DAM STRAIGHTEN AND REALIGN AFFECTED AREAS		400	608.00
2 TO SPRAY ROOF SIDE PANEL RH, REAR FENDER RH, REAR PANEL, REAR BUMPER, BUMPER LOWER AND AFFECTED AREAS	SIDE, BUMPER New	600	800.00
3 TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE	New	- 100 m flore 1 1 mm gra	50.00
\$6	Gross Labour Cost (S\$)	#1	1,450.00

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

D18MTMC01004917

Engine No:

Odometer:

Chassis No:

CS/SMO19013849/R1QF3N2

Date:

19/09/2019

REFERENCE

Vehicle No:

Date of Loss:

Handling Insurer: Claimant

Sompo Insurance Singapore Pte.

Ltd.

05/08/2019

SJC2496E

Insured Vehicle No:

FBG6070Y

Nature of Claim:

Policy No:

TP

Claim No:

4B12AT0793

397322 km

JMYLTCV5W7J000110

CMTD1903797

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Colour:

SJC2496E

Make & Model:

Reg. Date:

MITSUBISHI DELICA, 2.4 CVT (A)

05/02/2008 (Man. Year: 2007)

Grey 2360 cc

Engine Capacity: Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side:

Front Right Side:

225/50 R17

Yokohama 6 mm Yokohama 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side:

225/50 R17 Yokohama 6 mm Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,637.90	2,285.10	352.80	13.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	1,050.00	400.00	27.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,087.90	3,335.10	752.80	18.42
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	4,087.90	2,650.00	1,437.90	35.17
+ GST 7.00/7.00% (S\$)	286.15	185.50	100.65	35.17
Nett Amount (S\$)	4,374.05	2,835.50	1,538.55	35.17

INSPECTION

Date of Assignment: Date Inspected:

07/08/2019 Present Location: 26/08/2019 Inspected At:

Mova Automotive Pte Ltd (Bukit Merah) Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah

Lane 3

Singapore 159722

Estimated Period of Repair:

5.0 days

Adjuster: MOHD RASUL Manager: SHIAU CHAN NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

M1-MPV

Reference

Parts:

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 19 Sep 2019) MITSUBISHI DELICA 2.4 CVT (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SJC2496E)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
	1		*TAILLAMP RH	Cracked	385.00 FL	*385.00 FL
2	2		*TAILLAMP CLIPS	Necessary	12.00 FL	*12.00 FL
3	1 3		*TAILLAMP LOWER GARNISH RH *TAILLAMP LOWER GARNISH CLIPS	Cracked Serviceable	153.00 FL 18.00 FL	*153.00 FL *- FL
5	1		*REAR BUMPER SIDE RH *REAR BUMPER SIDE BRACKET RH	Cracked Necessary	378.00 FL 39.00 FL	*378.00 FL *39.00 FL
6 7	1		*REAR BUMPER LOWER *REAR BUMPER REFLECTOR RH	Scratched Serviceable	1,533.00 FL 38.00 FL	*1,533.00 FL *- FL
8	1		*REAR BUMPER SENSOR RH	Serviceable	336.00 FL	*- FL
9	1		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
10 11	10		*REAR FENDER RH - REPAIR	Repair	-	*-Fl
12	1		*ROOF SIDE PANEL RH - REPAIR	Repair	\$ <u>2</u>	*-Fl
13	1		*REAR PANEL - REPAIR	Serviceable	·	*- Fl
F=F	anchise	part. L=ListIte	emDisc.	CALLAND DE ACCOMONIO	YOUR HOUSE	2-2010000000000000
				Sub Total (S\$)	2,931.00	2,539.00
			- List Item Discount on L Iten	ns 10.00/10.00% (S\$)	293.10	253.90
				Total Parts (S\$)	2,637.90	2,285.10

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			400.00
1	TO REPAIR ROOF SIDE PANEL RH, REAR FENDER RH, REAR BUMPER. REMOVE & REFIX DAMAGED PARTS STRAIGHTEN AND REALIGN AFFECTED AREAS	New	600.00	400.00
2	TO SPRAY ROOF SIDE PANEL RH, REAR FENDER RH, REAR PANEL, REAR BUMPER, BUMPER SIDE, BUMPER LOWER AND AFFECTED AREAS	New	800.00	600.00
3	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE	New	50.00	50.00
	Gross Labour Cost (S\$)		1,450.00	1,050.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >