

ASS. REC. BY:

REF: CS/CT119013882/ R/H 8302

Special Instruction:

Surveyor: RasuASSIGNMENT (Office)From (Person): Tan Kah Leong of CT1 Date/Time: 7.8.19 16.33p.m

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLM 401R Insured: SJS 2705Tat Workshop m/s Borneo Motor Te 8426171of 2 Pandan CrescentPolicy No: DM PCSN 15460618033 Claim No: SNM19D203675C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 6.8.2019
(Client's Record)CA / REV / REP. / REV 24 HRS mp" 13.8.19 Before 3pm H.O.D. Endorsement:Date/Time: 7.8.19 5.00pm Person Contacted: Thomas Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLM 401R - x</u>
	<u>SJS 2705T - CS 3/10/11020377/UY 1m</u> <u>D.O.A. - 03/10/2011</u>
	<u>Confirm part by part \$5255/- (Red: 1477.30; 21%)</u>

09/11/19

Surveyor

Paul

REF: CII

72009

ASSIGNMENT

From:

Date: 13.8.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLM 401R

at Workshop m/s Borneo Motor

of 2 Pandan Crescent

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Before 3.00 p.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLM 401R

Yr Regn: 2017 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA Vios 1.5 E CVT c.c 1496

Colour

grey

A/C: Insured / Std / NI / NA

Sp. Reading

181050

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

M4 FB29F3902007806

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

WETLAKS

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

06/08/19

D.O.I.

13/08/19

Survey held at

Borneo Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/3 Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 23 AUG 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 22/8 Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I. (\$

5255

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Aug 2019		07 Aug 2019 16:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant:

GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G

Vehicle Reg. No.:

SLM401R

Date of Loss:

06/08/2019 14:00 - :59

Claim Type:

TP / SNM19D203695C02

Policy/Cover Note No.:

DMPCSN15460618033

Vehicle Reg. No. (Insured):

SJS2705T

Policy No. (Claimant):

A29114756MKF

Excess:

S\$1,000.00

Repairer:

Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]

Claimant's Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/08/2019]

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Wednesday, 7 August 2019 4:21 PM
To: Ashlyn Chng; assignments
Subject: RE: OUR REF: SNM19D203695-SJS2705T-TKL - FW: Direct Settlement (TP) - Accident involving SLM401R & SJS2705T DOA 06/08/2019

WITHOUT PREJUDICE

Dear Ashlyn,

We refer to your email of 07.08.2019.

Liability is unclear.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Ashlyn Chng [mailto:Ashlyn.Chng@inchcape.com.sg]
Sent: Wednesday, 7 August, 2019 4:00 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D203695-SJS2705T-TKL - FW: Direct Settlement (TP) - Accident involving SLM401R & SJS2705T DOA 06/08/2019

Dear Kah Leong,

We would like to choose XING QUO QIANG to conduct the assessment.

Appreciate if you can revert on the liability the soonest.

Regards,

Ashlyn Chng

D: 6631 1874 | F: 6872 7260 | E: Ashlyn.chng@inchcape.com.sg

Inchcape Centre
Level 4, Bodycare Centre
2 Pandan Crescent
Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Sent: Wednesday, 7 August 2019 3:57 PM

To: Ashlyn Chng <Ashlyn.Chng@inchcape.com.sg>

Subject: RE: OUR REF: SNM19D203695-SJS2705T-TKL - FW: Direct Settlement (TP) - Accident involving SLM401R & SJS2705T DOA 06/08/2019

CAUTION: This email originated from outside of the organization (Inchcape). Do not click links or open attachments unless you recognise the sender and know the content is safe.

Without Prejudice

Dear Ashlyn,

We refer to your email dated 7 August 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Wednesday, 7 August, 2019 3:41 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>;
Chee So Chow <sochow.chee@sg.cntaiping.com>; Ashlyn.Chng@inchcape.com.sg

Subject: OUR REF: SNM19D203695-SJS2705T-TKL - FW: Direct Settlement (TP) - Accident involving SLM401R & SJS2705T DOA 06/08/2019

Importance: High

Dear Kah Leong,

Please conduct PRS for SLM401R.

Note: officer in charge – Kah Leong 63896193

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Ashlyn Chng [<mailto:Ashlyn.Chng@inchcape.com.sg>]

Sent: Wednesday, August 07, 2019 12:28 PM

To: Claims Dept of CTI

Cc: Suraidah B Saidi PTCBC

Subject: RE: Direct Settlement (TP) - Accident involving SLM401R & SJS2705T DOA 06/08/2019

Importance: High

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured **SJS2705T** thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with **Car Rental of @ \$100 per day x no. of days** as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Thomas Pang @ 9847 6171/ 6631 1860** is located at **2 Pandan Crescent / Level 4** for an appointment to inspect our client's vehicle (currently vehicle IN workshop).

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you!

Regards,

Ashlyn Chng

D: 6631 1874 | F: 6872 7260 | E: Ashlyn.chng@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 22 August 2019 5:02 PM
To: Thomas Pang PTCBC; Rasul (LKKAUTO); Admin A; SUR
Subject: RE: Finalize Report for SLM401R

Dear Thomas,

Confirm part by part \$5255, 4days

Please submit your documents to china tai ping

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Thomas Pang PTCBC <Thomas.Pang@borneomotors.com.sg>
Sent: Thursday, 15 August 2019 5:34 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Finalize Report for SLM401R

Dear Rasul,

Attach finalize report for your perusal. 04 working days.

Thank you

Regards

thomas

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/08/2019 18:01
Date Of Accident	06/08/2019 14:30
Exact Location Of Accident	MARINA BLVD AND SHEARES AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM401R
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90697267
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	

Driver

Name of Driver	RAZALI BIN IBRAHIM
NRIC No	S1193267C
Date Of Birth	29/10/1956
Occupation	OUTDOOR
Date Of Driving Pass	09/01/1982
Driving Experience	37 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90697267
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 932 YISHUN CENTRAL 1 #02-101
Postcode	760932
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 06 AUGUST 2019 AT ABOUT 1430HRS, I WAS DRIVING MY VEHICLE SLM401R ALONG MARINA BLVD, EXECUTING A LEFT TURN TO SHEARES AVE. THERE VEHICLE SJS2705T SIDE SWIPED MY VEHICLE'S RIGHT FRONT PORTION OF MY VEHICLE. NOBODY WAS INJURED. I ALREADY SLOWED DOWN FOR VEHICLE SJS2705T AFTER SEEING HIS VEHICLE CUTTING IN FRONT OF ME.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS2705T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	YUE LEI

NRIC/Passport Number	S7889506C
Contact Number	+6596615046
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under [d] above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 06/08/19

Reporting Centre Personnel's Signature
Name: ALEXIS WONG
NRIC / FIN No:

1635 kms

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 06/08/19 at about 1430hrs I was driving my Vehicle SLM401R along Marina Blvd executing a left turn to Sheaves Ave there where Vehicle SJS2705T side swipe my Vehicle Right front portion of my vehicle. Nobody was injured. I already slow down for vehicle SJS2705T after seeing his Vehicle cutting in front of me.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time 06/08/19

Reporting Centre Personnel's Signature
Name: Adnan Shaleh
NRIC/ID No



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/S Grab Rentals Pte Ltd 6 Shenton Way #38-01 Oue Downtown Singapore 068809 Work: 65703925
	Document No 0	
	Document Date 07/08/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	CEXRKT	Q1	NSP151R	20/03/2017	SLM0401R	0	47492 72/DS/SLM0401R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MHFB29F3902007806	2NRX132456	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB SUNDRIES - DRIVER REPORT FLASH OUTSIDE SEND IN:07.08.2019 @ 1041HRS TP INS: CHINA TAIPING INSURANCE TP VEH: SJS2705T DATE OF ACC: 06.08.2019				50 100.00
2	B	BP-LAB2 R/I AND REFOCUS HEADLAMP				122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				1440 2160.00
5	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				1180 1770.00
6	1	U52119-0U920 COVER, FR BUMPER, de	1.00	495.70		495.70
7	2	U52535-0D190 RETAINER, FR BUMPER	1.00	68.70		68.70
8	3	U52536-0D190 RETAINER, FR BUMPER	1.00	68.70		68.70
9	4	T90467-05170 CLIP	2.00	2.50		5.00
10	5	U53811-K0020 PANEL, FR FENDER, RH	1.00	706.80		706.80
11	6	U53866-0D160 SEAL, FR FENDER TO	1.00	45.90		45.90
12	7	U53827-0D160 PROTECTOR, FR FENDER	1.00	48.60		48.60
13	8	U53875-0D380 LINER, FR FENDER, RH	1.00	303.40		303.40
14	9	T90467-07214 CLIP	10.00	2.60		26.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4042826

TO SECURITY GUARD

4042826

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 07/08/2019
TIME 11:41

VEHICLE NO SLM0401R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**

Inchcape

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/S Grab Rentals Pte Ltd 6 Shenton Way #38-01 Oue Downtown Singapore 068809 Work: 65703925
	Document No 0	
	Document Date 07/08/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	CEXRKT	Q1	NSP151R	20/03/2017	SLM0401R	0	47492 72/DS/SLM0401R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MHFB29F3902007806	2NRX132456	60	Thomas Pang W T	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	0	S81110-0D831 HEADLAMP ASSY, RH <i>see</i>	1.00	608.70		✓ 608.70
16	1	T53879-58010 RETAINER, FR FENDER <i>see</i>	2.00	8.60		✓ 17.20
17	2	T47749-58010 CLIP, PIN HOLD <i>see</i>	2.00	2.60		✓ 5.20
<i>Rasul</i> <i>Hp 90000068</i> <i>4-5 days</i> <i>13/08/19 @ 1450</i> <i>Resurvey before part</i> Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 2,399.90	6,732.30
		Labour 4,332.40	GST 7.00% 471.26
		Materials 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	
			Amount Due 7,203.56

PLEASE TEAR ALONG PERFORATED LINE

4042827

TO SECURITY GUARD

4042827

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 07/08/2019
TIME 11:41

Page 2 of 2

VEHICLE NO

CUSTOMER

SIGNATURE **TAX INVOICE**
FOR BORNEO MOTORS (SINGAPORE) PTE LTDBorneo Motors
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Inchcape 224 001 224 4488



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail				Account No		Customer Detail		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept				S1000003 / ICCI1		M/S Grab Rentals Pte Ltd 6 Shenton Way #38-01 Oue Downtown Singapore 068809 Work: 65703925		
				Document No				
				0				
				Document Date				
				15/08/2019				
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
17	CEXRKT Q1	NSP151R	20/03/2017	SLM0401R	0	47492	72/DS/SLM0401R	
Chassis No		Engine No		Terms	Service Engineer	Vehicle In	Collected On	
MHFB29F3902007806		2NRX132456		60	Thomas Pang W T	13/08/2019 8.00	15/08/2019 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB SUNDRIES - DRIVER REPORT FLASH OUTSIDE SEND IN:07.08.2019 @ 1041HRS TP INS: CHINA TAIPING INSURANCE TP VEH: SJS2705T DATE OF ACC: 06.08.2019 BY:LKK-RASUL @ 13.08.2019 (04 WORKING DAYS)						50.00
2	B	BP-LAB2 R/I AND REFOCUS HEADLAMP			*			122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME			18			180.00
4	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS			*			1440.00
5	B	BP-RES2 RESPRAY ACC AFFECTED AREAS			14			1180.00
6	1	S52119-0U920 COVER, FR BUMPER, L			1.00	495.70		495.70
7	2	S52535-0D190 RETAINER, FR BUMPER			1.00	68.70		68.70
8	3	T90467-05170 CLIP			2.00	2.50		5.00
9	4	S53866-0D160 SEAL, FR FENDER TO C			1.00	45.90		45.90
10	5	T90467-07214 CLIP			10.00	2.60		26.00
11	6	S81110-0D831 HEADLAMP ASSY, RH			1.00	608.70		608.70
12	7	T53879-58010 RETAINER			2.00	8.60		17.20
13	8	L47749-58010 CLIP, PIN HOLD			2.00	2.60		5.20
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total		
		Please acknowledge receipt of vehicle		Parts Labour Materials Lubrication/Fluid Others		Less		
						Amount Due		

PLEASE TEAR ALONG PERFORATED LINE

4043245

TO SECURITY GUARD

4043245

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 15/08/2019
TIME 17:25

VEHICLE NO SLM0401R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail				Account No		Customer Detail			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept				S1000003 / ICCI1		M/S Grab Rentals Pte Ltd 6 Shenton Way #38-01 Oue Downtown Singapore 068809 Work: 65703925			
				Document No					
				0					
				Document Date					
				15/08/2019					
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks		
17	CEXRKT Q1	NSP151R	20/03/2017	SLM0401R	0	47492	72/DS/SLM0401R		
Chassis No		Engine No		Terms	Service Engineer	Vehicle In	Collected On		
MHFB29F3902007806		2NRX132456		60	Thomas Pang W T	13/08/2019	8.00	15/08/2019	18.00
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
14	9	K53875-0D380 LINER, FR FENDER, RH				1.00	303.40		303.40
15	0	S53811-K0020 FENDER SUB-ASSY, RH				1.00	706.80		706.80
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.									
For & on behalf of Borneo Motors		Customer's Signature		Change Summary			Total		
		Please acknowledge receipt of vehicle		Parts	2,282.60	GST 7.00%		5,255.00	
				Labour	2,972.40	367.85			
				Materials	0.00	Less			
				Lubrication/Fluid	0.00	0.00			
				Others	0.00	Amount Due			
							5,622.85		

PLEASE TEAR ALONG PERFORATED LINE

4043246

4043246

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 15/08/2019
TIME 17:25

VEHICLE NO SLM0401R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors




































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Aug 2019		07 Aug 2019 16:33 Edit Adj Rpt	S\$5,255.00 Edit Estimates	S\$5,255.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLM401R	Date of Loss:	06/08/2019 14:00 - :59 [28 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203695C02	Policy/Cover Note No.:	DMPCSN15460618033						
Vehicle Reg. No. (Insured):	SJS2705T	Policy No. (Claimant):	A29114756MKF						
		Excess:	S\$1,000.00						
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 20/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM401R (SNM19D203695C02)
[SJS2705T]
TP
GRAB RENTALS PTE LTD
Aug 6 2019 2:00PM
[-]
Borneo Motors (S) Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
2	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
3	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
4	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
5	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
6	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
7	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
8	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
9	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
10	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
11	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
12	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
13	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
14	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
15	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
16	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
17	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
18	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
19	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
20	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
21	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
22	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
23	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
24	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
25	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
26	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
27	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
28	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
29	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
30	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
31	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
32	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
33	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
34	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
35	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
36	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	
37	22/08/19 17:55	General View								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
38	22/08/19 17:55	General View		Load JPG <input checked="" type="checkbox"/>
39	22/08/19 17:55	General View		Load JPG <input checked="" type="checkbox"/>
40	22/08/19 17:55	General View		Load JPG <input checked="" type="checkbox"/>
41	22/08/19 17:55	General View		Load JPG <input checked="" type="checkbox"/>
42	22/08/19 17:55	General View		Load JPG <input checked="" type="checkbox"/>
43	22/08/19 17:55	General View		Load JPG <input checked="" type="checkbox"/>
44	22/08/19 17:56	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
45	22/08/19 17:56	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
46	22/08/19 17:56	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Aspectus Consultancy Pte Ltd (Aspectus)	1 per page	<input checked="" type="checkbox"/>
1	06/08/19 18:11	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Aspectus Consultancy Pte Ltd (Aspectus)		Thumbnail Print
1	06/08/19 18:07	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	06/08/19 18:07	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	06/08/19 18:07	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	06/08/19 18:07	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	06/08/19 18:07	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	06/08/19 18:07	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	06/08/19 18:07	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	06/08/19 18:07	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	06/08/19 18:07	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	06/08/19 18:07	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	06/08/19 18:07	Accident Photo		Load JPG <input checked="" type="checkbox"/>
12	06/08/19 18:07	Accident Photo		Load JPG <input checked="" type="checkbox"/>
13	06/08/19 18:07	Identification Card		Load JPG <input checked="" type="checkbox"/>
14	06/08/19 18:07	Identification Card		Load JPG <input checked="" type="checkbox"/>
15	06/08/19 18:07	Driving License		Load JPG <input checked="" type="checkbox"/>
16	06/08/19 18:07	Driving License		Load JPG <input checked="" type="checkbox"/>
17	06/08/19 18:07	Vocational License		Load JPG <input checked="" type="checkbox"/>
18	06/08/19 18:07	Vocational License		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Aspectus Consultancy Pte Ltd (Aspectus)		Thumbnail Print
1	06/08/19 18:06	Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	06/08/19 18:06	Sketch Plan #2		Load JPG <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013882/R1TF3E2

Date: 27/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN15460618033

Claimant Vehicle
No : SLM401RInsured Vehicle
No : SJS2705T

Date of Loss: 06/08/2019

Nature of Claim: TP

Claim
No: SNM19D203695C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM401R**

Make & Model: TOYOTA VIOS, 1.5 E CVT (A)

Engine No: 2NRX132456

Reg. Date: 20/03/2017 (Man. Year: 2017)

Chassis No: MHFB29F3902007806

Colour: Grey

Odometer: 181050 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16

Rear Tyre Size: 195/50 R16

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,499.90	2,332.60	167.30	6.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,232.40	2,922.40	1,310.00	30.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,732.30	5,255.00	1,477.30	21.94
+ GST 7.00/7.00% (S\$)	471.26	367.85	103.41	21.94
Nett Amount (S\$)	7,203.56	5,622.85	1,580.71	21.94

INSPECTION

Date of Assignment: 07/08/2019

Date Inspected: 13/08/2019 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Aug 2019)
Parts:	143	TOYOTA VIOS 1.5 E CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM401R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*COVER, FR BUMPER,	Deformed	495.70 FS	*495.70 FS
3	1		*RETAINER, FR BUMPER	Necessary	68.70 FS	*68.70 FS
4	1		*RETAINER, FR BUMPER	Serviceable	68.70 FS	*- FS
5	2		*CLIP	Necessary	5.00 FS	*5.00 FS
6	1		*PANEL, FR FENDER, RH	Bent	706.80 FS	*706.80 FS
7	1		*SEAL, FR FENDER TO	Necessary	45.90 FS	*45.90 FS
8	1		*PROTECTOR, FR FENDER	Serviceable	48.60 FS	*- FS
9	1		*LINER, FR FENDER, RH	Cut	303.40 FS	*303.40 FS
10	10		*CLIP	Necessary	26.00 FS	*26.00 FS
11	1		*HEADLAMP ASSY, RH	Scratched	608.70 FS	*608.70 FS
12	2		*RETAINER, FR FENDER	Necessary	17.20 FS	*17.20 FS
13	2		*CLIP, PIN HOLD	Necessary	5.20 FS	*5.20 FS
Total Parts (S\$)					2,499.90	2,332.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R/I AND REFOCUS HEADLAMP	New	122.40	122.40
2	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
3	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN / REALIGN ACC AFFECTED AREAS	New	2,160.00	1,440.00
4	RESPRAY ACC AFFECTED AREAS	New	1,770.00	1,180.00
Gross Labour Cost (S\$)			4,232.40	2,922.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >