

Your Ref : S9M01W53

Date: 08th October 2019

Our Ref : CC4/ASM19013894/Kpa3s2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Lynn Khong

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKW 6376A
ACCIDENT ON 02/08/2019 INSURED VEHICLE SKF 60P**

Instruction was received to inspect the vehicle Reg. No. SKW 6376A. The inspection was conducted on 13/08/2019 at the premises of M/s Cheng Hoe Motor Pte Ltd, Blk 1019 Yishun Industrial Park A #01-374/382 Singapore 768761.

The following vehicle information was recorded:

Registration Number	: SKW 6376A
Make/Model	: Honda Vezel (A)
Year of Registration	: 2015
Body Colour	: Metallic Maroon
Chassis Number	: RU11103133
Engine Capacity	: 1496 cc

The vehicle sustained damages at the n/s and o/s body. The Estimated repair cost of such vehicle is S\$20,000.00 (Sin Dollars: Twenty Thousand only.) (Exclude check items S\$4,792.80Nett) (Details see photographs enclosed).

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "**uneconomical Total Loss**".

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 60,000.00(est)

Less: LTA Reimbursement Value (RV)

(S\$ 40,271.00)(est)

Nett Liability

S\$ 19,729.00(est)

S\$ 19,729.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 20,000.00

(Exclude check items S\$4,792.80Nett)

Nett Liability

S\$ 20,000.00

(a) - (b) =

(S\$ 271.00)

The amount of estimated saving of S\$271.00 if the vehicle to be written off as "**Total Loss**" instead of to be repair.

Vehicle Inspected By:


KONG SENG CHEONG

Licensed Appraiser


K.K. LAU

MSQ(Eng M), B Eng(Hons), Peng(UK),

MSME(USA), B Bus(Aust), MBA(UK),

IEng(UK), MIE(mech), MinstAEA, MFIEA,

MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),

AMCATARI(CAN), M.MATA(USA), M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.