

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

7-Aug-19

## ESTIMATE REPAIR BILL FOR HYUNDAI AVANTE REGN NO: SJL 9013 L

1 pc	Front bumper /	\$ /	452.00
1 pc	Front bumper reinforcement /	\$ /	279.00
1 pc	Front bumper sponge /	\$ -	124.00
1 pc	Front bumper n/s side bracket /	\$ /	20.50
1 pc	Front bumper n/s fog lamp /	\$ /	150.00
1 pc	Front bumper centre grille /	\$ /	167.50
1 pc	Front bumper lower lip ?	?	
1 pc	n/s headlamp /	\$ /	456.60
1 pc	Support panel /	\$ -	791.30
1 pc	Bonnet /	\$ -	992.00
2 pcs	Bonnet hinge x repair	\$ /	128.00
1 pc	Bonnet grille ?	\$ /	366.00
1 pc	Front n/s fender /	\$ /	477.60
1 pc	Front n/s fender inner shield /	\$ -	47.50
1 pc	Front n/s wheel housing /	FM /	
1 pc	Front n/s wheel cover /	\$ -	104.00
1 pc	Front n/s tyre x	x	
1 pc	Front n/s lower arm ?	\$ /	297.00
1 pc	Front n/s shock absorber ?	\$ /	349.60
1 pc	Front n/s wheel hup ?	\$ /	192.80
1 pc	Front n/s knuckle arm ?	\$ /	376.40
1 pc	Front n/s bearing ?	?	
1 pc	Front n/s door x repair	\$ /	1,258.00
		\$	2,577.80
		Less 20%	\$ 746.70
			\$ 2,240.10
<b>S/NETT</b>			
1 set	Front bumper clips /	\$	35.00
1 set	Front fender clips /	\$	28.00
1 pc	Battery /	\$	150.00

100

7-Aug-19

**ESTIMATE REPAIR BILL FOR HYUNDAI AVANTE REGN NO: SJL 9013 L**

Towing Fee	\$	50.00 /
Sundry	\$	<del>50.00</del> 20
To check headlamp wiring	\$	<del>40.00</del> 20
To top up air con	\$	<del>120.00</del> 80
To check wheel alignment	\$	<del>80.00</del> 60
To lift engine to facilitate repair on the front n/s wheel housing	\$	<del>450.00</del> 150
To dismantle dashboard to facilitate repair on the front n/s wheel housing	\$	<del>450.00</del> X
To labour charge for dismantle and renew the accident damaged parts. To heat/weld and cut off the front n/s wheel house. Including knock-out, straighten, repair, reshape and adjust of the front n/s chassis member	\$	<del>1,800.00</del> 1000
To putty and spray painting on the Front bumper, bonnet, front n/s fender, front n/s fender wheel house, front n/s door, front n/s chassis member	\$	<del>1,500.00</del> 1080
To apply rustproofing on the repaired and replaced panels.	\$	<del>250.00</del> 50
	\$	<u>7,243.10</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

*Kalin Uley*  
*7/8/19 1705 hrs.*  
*5 Days*  
*U/S*  
*After Rep't photo*

Applicant hereby notifies the insurer of the following:

- To survey and water spray painting
- To repair damaged parts during resurvey
- Parts price subject to confirmation
- Third party survey & on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: