



FALCON-AIR

AXA INSURANCE SINGAPORE PTE LTD  
NO. 8 SHENTON WAY,  
#24-01 AXA TOWER, 068811  
SINGAPORE

Attention : Motor Claim Department

Estimate : ES003510

Date : 08/08/2019  
Vehicle Num. : SCP810J  
Make/Model : HONDA INSIGHT-2012  
Chassis/Eng# : JHMZE2850CS203886  
Accident Date : 07/08/2019  
Claim No. :  
Reference : TP NTUC VS AXA  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER TOP		681.20 <i>de</i>
2.	1	REAR BUMPER LOWER		399.80 <i>cut</i>
3.	1	REAR BUMPER SIDE RETAINER RH		30.10 <i>kei?</i>
List TotalS\$ :				1,111.10
20.00% Discount S\$ :				222.22
				888.88
SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR		200.00 <i>nw</i>
Special Nett Total S\$ :				200.00
LABOUR :				
TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING				100.00 <i>30</i>
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER				600.00 <i>400</i>
TO REPAIR REAR END PANEL, INCLUDES KNOCKING & REPLACEMENT OF PARTS				450.00 <i>300</i>
Labour Total S\$ :				1,150.00

SingDollars : Two Thousand Two Hundred Thirty-Eight & Cents Eighty-Eight Only

E. & O.E.

Total S\$ : 2,238.88



for FALCON AIR AUTO SERVICES PTE LTD

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**FALCON-AIR AUTO SERVICES PTE LTD**

(a subsidiary of Falcon-Air Holdings Pte Ltd)

*Taufik 97415749*  
*WP*  
*9/9/19 @ 230pm*  
*Receiving after repair*  
*45 to %*  
*No 2nd hand part.*  
*30 days*  
*Taufik Intertek.com*

*Before & After*  
*\* End panel take photo*

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862  
Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg