



FALCON-AIR

AXA INSURANCE SINGAPORE PTE LTD
NO. 8 SHENTON WAY,
#24-01 AXA TOWER, 068811
SINGAPORE

Attention : Motor Claim Department

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003510

Date : 08/08/2019
Vehicle Num. : SCP810J
Make/Model : HONDA INSIGHT-2012
Chassis/Eng# : JHMZE2850CS203886
Accident Date : 07/08/2019
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1	REAR BUMPER TOP		681.20
2.	1	REAR BUMPER LOWER		399.80
3.	1	REAR BUMPER SIDE RETAINER RH		30.10
		List TotalS\$:		1,111.10
		20.00% Discount S\$:		222.22
				888.88
		SPECIAL NETT ITEMS :		
1.	1	REVERSE SENSOR		200.00
		Special Nett Total S\$:		200.00
		LABOUR :		
		TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING		100.00
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER		600.00
		TO REPAIR REAR END PANEL, INCLUDES KNOCKING & REPLACEMENT OF PARTS		450.00
		Labour Total S\$:		1,150.00

SingDollars : Two Thousand Two Hundred Thirty-Eight & Cents Eighty-Eight Only

E. & O.E.

Total S\$: 2,238.88



for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg