



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
ATTN : **MOTOR CLAIM DEPT.**

T/P VEH. NO. : _____

ESTIMATE REPORT 1st QUOTATION

JOB NO : _____

OWNER'S PARTICULAR

NAME : **SELVA BRYAN RAYNAM**
ADDRESS :

CONTACT :

LICENSE NO. : **SBR8268Z TRANS.**
MAKE / MODEL : **LEXUS CT200**
OWNER'S INSURER **CHINA INSURANCE**
JOB-CODE : **OD** S/A : **JOEY**

CHASSIS NO : **JTHKD5BHX02018831**
ENGINE NO :

ACCIDENT DATE : **2-Aug-19**

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC +15%	DISC-PRICE	SUR. DISP	REV. PRICE
1 FRONT BUMPER <i>Buc</i>	1.00	420.00	15.00	483.00	Y	_____
2 FRONT BUMPER TOP INNER RUBBER SEAL <i>nec</i>	1.00	50.00	15.00	57.50	Y	_____
3 FRONT BUMPER INNER GARNISH <i>?</i>	1.00	190.00	15.00	218.50	Y	_____
4 FRONT BUMPER LOWER GRILLE <i>?</i>	1.00	145.00	15.00	166.75	Y	_____
5 FRONT BUMPER FOGLAMP LH <i>SVC</i>	1.00	140.00	15.00	161.00	Y	<i>X</i>
6 FRONT BUMPER FOGLAMP COVER LH <i>SVC</i>	1.00	50.00	15.00	57.50	Y	<i>X</i>
7 FRONT BUMPER FOGLAMP RH <i>SVC</i>	1.00	180.00	15.00	207.00	Y	<i>X</i>
8 FRONT BUMPER FOGLAMP COVER RH <i>SVC</i>	1.00	50.00	15.00	57.50	Y	<i>X</i>
9 FRONT BUMPER SPONGE <i>gra</i>	1.00	110.00	15.00	126.50	Y	_____
10 FRONT BUMPER RETAINER RH <i>SVC</i>	1.00	35.00	15.00	40.25	Y	<i>X</i>
11 FRONT BUMPER RETAINER LH <i>SVC</i>	1.00	35.00	15.00	40.25	Y	<i>X</i>
12 FRONT BUMPER LOWER COVER <i>SVC</i>	1.00	35.00	15.00	40.25	Y	<i>X</i>
13 FRONT BUMPER REINFORCEMENT <i>B+</i>	1.00	290.00	15.00	333.50	Y	_____
14 FRONT BUMPER BRACKET RH <i>R</i>	1.00	60.00	15.00	69.00	Y	<i>X</i>
15 FRONT BUMPER BRACKET LH <i>?</i>	1.00	60.00	15.00	69.00	Y	_____
16 FRONT NUMBER PLATE GARNISH <i>gra</i>	1.00	115.00	15.00	132.25	Y	_____
17 FRONT FENDER INNER GARNISH LH <i>SVC</i>	1.00	120.00	15.00	138.00	Y	_____
18 FRONT FENDER INNER GARNISH RH <i>SVC</i>	1.00	120.00	15.00	138.00	Y	<i>X</i>
19 FRONT FENDER SIDE RUBBER LH <i>SVC</i>	1.00	50.00	15.00	57.50	Y	<i>X</i>
20 FRONT FENDER SIDE RUBBER RH <i>SVC</i>	1.00	50.00	15.00	57.50	Y	<i>X</i>
21 FRONT HEADLAMP HID LH <i>?</i>	1.00	1200.00	15.00	1380.00	Y	_____

22	FRONT HEADLAMP HID RH	mtg crg	1.00	1200.00	15.00	1380.00	Y	
23	FRONT HEADLAMP NOZZLE CHROME COVER RH	SVC	1.00	280.00	15.00	322.00	Y	X
24	FRONT HEADLAMP NOZZLE CHROME COVER LH	SVC	1.00	280.00	15.00	322.00	Y	X
25	RADIATOR GRILLE	Crg	1.00	330.00	15.00	379.50	Y	
26	RADIATOR GRILLE CHROME	Crg	1.00	120.00	15.00	138.00	Y	
27	RADIATOR GRILLE LOGO	NRC	1.00	185.00	15.00	212.75	Y	
28	HORN - HIGH	?	1.00	75.00	15.00	86.25	Y	
29	HORN - LOWER	SVC	1.00	75.00	15.00	86.25	Y	X
30	BRACE PANEL	BT	1.00	105.00	15.00	120.75	Y	
31	BONNET	BT	1.00	790.00	15.00	908.50	Y	
32	BONNET LOCK	DIS	1.00	105.00	15.00	120.75	Y	
33	BONNET HINGE LH	R	1.00	50.00	15.00	57.50	Y	X
34	BONNET HINGE RH	R	1.00	50.00	15.00	57.50	Y	X
35	BONNET SEAL	SVC	1.00	25.00	15.00	28.75	Y	X
36	BONNET STOPPER 2PCS	SVC	2.00	20.00	15.00	23.00	Y	X
37	WIPER SIDE COVER	SVC	1.00	95.00	15.00	109.25	Y	X
38	ENGINE LOWER COVER	SVC	1.00	200.00	15.00	230.00	Y	X
39	RADIATOR ASSY	?	1.00	680.00	15.00	782.00	Y	
40	RADIATOR FAN COWLING	SVC	1.00	120.00	15.00	138.00	Y	X
41	RADIATOR FAN MOTOR	SVC	1.00	190.00	15.00	218.50	Y	X
42	RADIATOR FAN BLADE	SVC	1.00	110.00	15.00	126.50	Y	X
43	RADIATOR SIDE AIR GUARD LH	?	1.00	60.00	15.00	69.00	Y	
44	RADIATOR SIDE AIR GUARD RH	?	1.00	60.00	15.00	69.00	Y	
45	AIRCON FAN BLADE	SVC	1.00	120.00	15.00	138.00	Y	X
46	AIR CON CONDENSOR	SVC	1.00	680.00	15.00	782.00	Y	X
47	AIR CON FAN MOTOR	SVC	1.00	190.00	15.00	218.50	Y	X
48	AIR CON PIPE (CONDENSOR TO COMPRESSOR)	?	1.00	160.00	15.00	184.00	Y	
49	AIR CON PIPE (CONDENSOR TO COILING COIL)	?	1.00	350.00	15.00	402.50	Y	
50	AIRCON CONDENSOR	?	1.00	690.00	15.00	793.50	Y	
51	AIRCON WATER COOLER	?	1.00	380.00	15.00	437.00	Y	
52	AIRCON CONDENSOR COWLING	SVC	1.00	180.00	15.00	207.00	Y	X
53	SUPPORT PANEL ASSY	Buc	1.00	700.00	15.00	805.00	Y	

TOTAL (PARTS):

12160.00 13984.00

SPECIAL NETT ITEM

1	FRONT PARKING SENSOR	SVC	1.00	280.00	0.00	280.00	Y	<u>X</u>
2	FRONT FENDER INNER SHIELD CLIPS LH	NN	1.00	100.00	0.00	100.00	Y	<u>X</u>
3	FRONT FENDER INNER SHIELD CLIPS RH	NN	1.00	100.00	0.00	100.00	Y	<u>X</u>
4	FRONT FENDER INNER GARNISH CLIPS (1SET)	NN	1.00	50.00	0.00	50.00	Y	<u>X</u>
5	FRONT RADIATOR GRILLE CLIPS	NEC	1.00	50.00	0.00	50.00	Y	_____
6	FRONT BUMPER CLIPS	NEC	1.00	50.00	0.00	50.00	Y	_____
7	FRONT BUMPER INNER GARNISH CLIPS	NN	1.00	50.00	0.00	50.00	Y	<u>X</u>
8	COOLANT	NEC	1.00	80.00	0.00	80.00	Y	<u>30</u>
9	FRONT ENGINE COVER AND SIDE COVER CLIPES RH	?	1.00	80.00	0.00	80.00	Y	_____
10	FRONT ENGINE COVER AND SIDE COVER CLIPES LH	?	1.00	80.00	0.00	80.00	Y	_____
TOTAL (PARTS) :				920.00		920.00		

LABOUR

1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA		1.00	1200.00	0.00	1200.00	Y	<u>600</u>
2	SPRAY PAINTING ON ACCIDENT AREA		1.00	1400.00	0.00	1400.00	Y	<u>900</u>
3	RESET FRONT PARKING SENSOR SYSTEM		1.00	120.00	0.00	120.00	Y	<u>50</u>
4	CHECK & REPAIR WIRING SYSTEM		1.00	180.00	0.00	180.00	Y	<u>30</u>
5	R&R RADIATOR ASSY		1.00	180.00	0.00	180.00	Y	<u>50</u>
6	CONDUCT FULL COMPUTER ALIGNMENT		1.00	120.00	0.00	120.00	Y	<u>X</u>
7	R&R AIRCON CONDENSOR & CHARGE UP GAS		1.00	180.00	0.00	180.00	Y	<u>100</u>
8	RESET & CALIBRATE HEADLAMP SYSTEM		1.00	120.00	0.00	120.00	Y	<u>?</u>
TOTAL (LABOUR) :				3500.00		3500.00		
TOTAL PARTS & LABOUR				16580.00		18404.00		

NO. OF DAY : _____

PART-BY-PART OR LUMP-SUM : SS _____

DATE OF SURVEY : ___/___/___

SURVEY BY : _____

CONTACT NO: _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

FAX NO

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p>
