

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 13 Aug 2019

Preliminary Advice

Vehicle No	: SBR8268Z	Accident Date	: 02/08/2019
Make	: TOYOTA LEXUS	Policy No.	: DMPCSN3075831801
Assignment Date	: 13/08/2019	Excess	: S\$750.00
Date of Inspection	: 13/8/2019	Est. Duration of Repair	: 6
Inspection At	: S THREE AUTOMOTIVE RECOVERY PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,720.19
Revised Amount	:S\$	10,336.84
Check Items (Estimated)	:S\$	7,888.84
Total	:S\$	18,225.68
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	42,000.00
COE / PARF Rebate	:S\$	29,009.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,991.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Pending repair cost from repairer