

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 7 Aug 2019

ASSESSMENT FOR REPAIR: HONDA 400X MANUAL FZ2999Y

Chassis No.: NC471005094

Engine No.: NC47E1005074

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$280.00 X
1 pc	Steering stem	\$480.00 X
2 pcs	Steering stem bearings @ \$45.00	\$90.00 X
1 pc	Handle bar	\$220.00 <i>bt</i> ✓
1 set	Handguards	\$330.00 <i>int</i> ✓
1 pc	Right mirror	\$175.00 X
1 pc	Left mirror	\$175.00 <i>at</i> ✓
1 pc	Windshield mount	\$280.00 <i>int</i> ✓
1 pc	Front windshield	\$270.00 <i>#cr</i> ✓
1 set	Crash bar	\$380.00 X
1 set	Fog lamp	\$250.00 <i>at</i> ✓
1 pc	Left front cover	\$270.00 X
1 pc	Left front cover labels	\$70.00 X
1 pc	Left black cover	\$250.00 X
1 pc	Side stand	\$140.00 <i>bt</i> ✓
1 pc	Big foot (side stand)	\$80.00 X
1 pc	Rear left footrest	\$115.00 <i>at</i> ✓
1 pc	Rear left footrest holder	\$195.00 X
1 pc	Front left footrest	\$135.00 X
1 pc	Front left footrest holder	\$245.00 <i>at</i> ✓
		\$3,580.00
	Less discount 10%	\$358.00
		\$3,222.00
	<u>Special nett items</u>	
1 pc	Front number plate	\$20.00 <i>10 at</i> ✓
1 pc	Top box	\$280.00 <i>at</i> ✓
1 pc	Box bracket	\$250.00 X
2 pcs	Front sport rim	\$700.00 X
1)	Towing charges	\$100.00 <i>80</i> ✓
	Replace, realign and adjust above	
	damaged parts, check wiring and	
2)	lighting system	\$800.00 <i>200</i> ✓
	To replace and balance front wheel	
3)	rim	\$150.00 <i>#0</i> ✓
	To knock, straighten chassis & body	
4)	balancing	\$380.00 X
	To remove/refit, replace (if damage) check and	
5)	straighten front fork tubes.	\$180.00 <i>100 plus</i> ✓

6)


Spray painting

Total Estimate

\$300.00 X

\$6,382.00

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

Taufik 97495749

Not Authorise.

20/9/19 @ 1730.

4 days

Resume after repair.

sure/khanto.com.