

LKW AUTO SERVICES

C/O : 176 SIN MING AUTOCARE DRIVE #02-01 SINGAPORE 575721

TEL : 6452 8211 FAX 6451 7420

CO REG NO : 199404214H

ESTIMATE

PYRO CARS PTE LTD

c/o 46 Lenton Plain

Singapore 786548

Date : 13/08/2019

7 days

Not Notified

1/1 Long 8500dp

Resurvey After Paint

Quantity	Particulars	Amount (\$)
RE : SLW5140H / Mazda 3		
1 pc	Rear Door ✓	1085.90
1 pc	Rear Door Hinge Upper ✓	83.50
1 pc	Rear Door Hinge Lower ✓	82.70
1 pc	Rear Door Regulator Gear ? 158	317.20
1 pc	Rear Door Regulator Motor ? 195	263.50
1 pc	Rear Door Weatherstrip ✓	258.70
1 pc	Rear Door Frame Sticker ✓	93.60
1 pc	Rear Fender ✓	1129.30
1 pc	Rear Fender Dust Cover ?	138.70 X
1 pc	Alloy Rim ✓ 1156.80	1195.80
1 pc	Rear Shock Absorber ?	324.50 X
1 pc	Rear Lower Arm ? 233	262.80
1 pc	Rear Knuckle Arm ? 472	681.30
1 pc	Rear Wheel Bearing Hub Assy ?	436.90
1 pc	Rear Windscreen Moulding ✓	128.30
1 pc	Rear Windscreen Seal ✓	93.70
Sub-total		\$ -
1 tube	Windscreen Glass Sealant ✓ S.nett	70 405.30
1 pc	Control Arm	205.30 X
1 pc	Trailing Arm	363.70 X
To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.		880.00 700l
To apply rust proofing on affected areas.		100.00 60l
To apply waterproof sealant on affected areas.		80.00 60l
To apply putty & spray painting on affected areas.		800.00 680l
To remove rear windscreen glass to enable repair.		120 150.00
To remove carpet, trimming and seats to enable repair.		150.00 100l
To transfer door(s) accessories		100.00 60l
To remove and install rear undercarriage parts to enable repair.		280.00 140l

Quantity	Particulars	Amount (\$)
	To replace steel rim(s) / alloy rim(s) & perform wheel balancing.	80.00 20/-
	To perform 4 wheels computerised alignment.	100.00 60/-
	Sub-total	\$ -
	Grand Total	9935.40

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: