

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$	11	80.00	X
1	Rear tyre	\$	11	400.00	X
1	Rear sport rim - R/H	\$	64	750.00	X
		\$		1,230.00	

S/N LABOUR CHARGES

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring.	\$		80.00	20
2	To remove and refit inner garnishes.	\$	11	150.00	X
3	To remove and refit rear undercarriage.	\$	11	350.00	X
4	To conduct wheel alignment.	\$	11	150.00	X
5	To remove and refit rear windscreen glass.	\$	11	180.00	X
6	To remove, refit doors fittings and replace damaged parts, transfer all fittings to new door.	\$		400.00	120
7	To apply undercoating.	\$		180.00	60
8	Panel beating.	\$		1,800.00	300
9	To re-spray painting on the affected areas.	\$		1,800.00	800
		\$		5,090.00	

1300

GRAND TOTAL :

\$ 14,393.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: