



FALCON-AIR

SUNDAR NEWS AGENCY  
BLK 701 WEST COAST RD #05-318  
SINGAPORE 120701

Attention : Motor Claim Department  
Contact : 90294009

Estimate : ES003501

Date : 24/07/2019  
Vehicle Num. : GBE9446M  
Make/Model : TOYOTA HIACE  
Chassis/Eng# : KDH201-0192252  
Accident Date : 23/07/2019  
Claim No. :  
Reference : TP NTUC VS AXA  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAILGATE		1,765.10
2.	1	TAILGATE LOCK		275.03
3.	1	TAILGATE LOGO		75.80
4.	1	TAILGATE STICKER HI ACE		48.50
5.	1	TAILGATE STICKER 1250KG		44.20
6.	1	REAR BUMPER		415.80
List TotalS\$ :				2,624.43
25.00% Discount S\$ :				656.11
				1,968.32
SPECIAL NETT ITEMS :				
1.	1	70 KM/HR STICKER		10.00
2.	1	SEALANT		45.00
3.	1	REAR END PANEL		545.00
Special Nett Total S\$ :				600.00
LABOUR :				
TO TRANSFER TAILGATE PARTS/MECHANISM				50.00
TO REMOVE/REFIX REAR WINDSCREEN GLASS				120.00

CONTINUE / ...

**FALCON-AIR AUTO SERVICES PTE LTD**

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

SUNDAR NEWS AGENCY  
BLK 701 WEST COAST RD #05-318  
SINGAPORE 120701

Attention : Motor Claim Department

Contact : 90294009

Estimate : ES003501

Date : 24/07/2019  
Vehicle Num. : GBE9446M  
Make/Model : TOYOTA HIACE  
Chassis/Eng# : KDH201-0192252  
Accident Date : 23/07/2019  
Claim No. :  
Reference : TP NTUC VS AXA  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER TO CUT OUT/REWELD RADIATOR SUPPORT PANEL, REPAIR FLOOR PANEL, REAR CHASSIS INCLUDES KNOCKING & REPLACEMENT OF PARTS		700.00
				550.00
		Labour Total S\$ :		1,420.00

SingDollars : Three Thousand Nine Hundred Eighty-Eight &amp; Cents Thirty-Two Only

E. &amp; O.E.

Total S\$ : 3,988.32

=====



for FALCON AIR AUTO SERVICES PTE LTD

**FALCON-AIR AUTO SERVICES PTE LTD**

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg