

LKK

Arthur Kenneth

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

SML9486E

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
TEL: 64193000 FAX: 64153727  
ATTN: Motor Claim Department

Estimate No: ES1991859  
Date: 13 Aug 2019  
Policy No: 5110003369  
Veh Reg No: SML9486E  
Make/Model: HONDA SHUTTLE 1.5G CVT  
Chassis No: GK82002282  
Engine No: L15B6002687  
Reg. Date: 12/06/2019

WS Ref: TP-AIG  
Claim Type: Third Party  
Accident Date: 08/08/2019  
TP Veh Reg No: SDJ3535D

*Not Authorized*  
*Repair by paint*  
*5 days*

## Estimate Repair Cost to Vehicle No :SML9486E

PAGE: 1/1

Description	U/Price	Quantity	List Price	Amount
List Price			SS	SS
1 REAR TAILGATE	1,193.60	1 PC	1,193.60	
2 TAILGATE EMBLEM -SHUTTLE	55.00	1 PC	55.00	
3 TAILGATE OUTER GARNISH WITH MOULDING	383.10	1 PC	383.10	
4 TAILGATE LOGO	27.40	1 PC	27.40	
5 TAILGATE INNER LOCK	157.80	1 PC	157.80	
6 TAILGATE INNER BOARD	320.70	1 PC	320.70	
7 TAILGATE REFLECT STICKER	395.00	2 PCS	790.00	
8 REAR WINDSCREEN GLASS MOULDING	131.80	1 PC	131.80	
9 REAR BUMPER	1,156.60	1 PC	1,156.60	
10 REAR BUMPER CLIP	3.90	6 PCS	23.40	
11 TAILLAMPS	520.50	2 PCS	1,041.00	
		Less 20%	1,056.08	4,224.32

### SPECIAL NETT

12 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	
13 REVERSE SENSOR	200.00	1 PC	200.00	
			240.00	240.00

### Labour

14 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	
15 TO REMOVE AND REFIX TAILGATE ASSY, REAR SPOILDER, REAR WIPER ASSY, TAILLAMPS AND TAILGTE REFLECTORSS, KNOCK AND REPAIR REAR PANEL AND RE-ALIGN TO SAME	700.00	1 LA	700.00	
16 TO PUTTY AND RESPRAY ON REAR PANEL, TAILGATE, REAR BUMPER	700.00	1 LA	700.00	
17 RUSTPROOFING	30.00	1 LA	30.00	
18 TO REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM	50.00	1 LA	50.00	

Parts \$4959.70

1,600.00 1,600.00

Total SS 6,064.32  
Add GST @ 7% 424.50  
Total Amount Payable SS 6,488.82

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

991.94  
3967.76  
240.00  
1200 Labour  
Total P/L \$5407.76 ✓ ok  
5 days