

SERVICE ESTIMATE

90048 - C00001 SL: SERVICE SALES - PC

Ms Chia Guek Li
6 Tai Thong Crescent
#08-03

Singapore 347840

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 13/08/2019

WIP No. . : 30358

Veh.In/Out:

*Tel.No. . : Mobile: 92391009

Reg.No. . : SFP9797U

Reg.date .: 16/06/2017

Mileage .: 0

Chassis No: SADCA2AV9HA494224

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Ms Chia Guek Li

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, ETC	0	1800.00	0		1,800.00	S
800	TO PUTTY SPRAYPAINT ON	0	1600.00	0		1,600.00	S
REAR BUMPER							
802	TO REPLACE REAR	0	1800.00	0		1,800.00	S
RH EXHAUST ASSY							
280	TO CHECK WIRING INCLUDE	0	510.00	0		510.00	S
RESETTING OF ALL ELECTRICAL							
MODULES							
	COVER-BUMPER	1.0 EA	1519.40			1,519.40	S
	BRACKET-BUMPER	1.0 EA	96.50			96.50	S
	BRACKET-BUMPER	1.0 EA	96.50			96.50	S
	MOUNTING-BRACKET	1.0 EA	109.70			109.70	S
	MOUNTING-BRACKET	1.0 EA	109.70			109.70	S
	LAMP-FOG	1.0 EA	252.90			252.90	S
	SILENCER-EXH RR ASSY	1.0 EA	1258.10			1,258.10	S
	CLAMP	1.0 EA	75.80			75.80	S
	ADHESIVE SEALER FL2	1.0 EA	669.10			669.10	S

Gross Total. 9,897.70

Labour Total 5,710.00
Parts Total 4,187.70
Package Total 0.00

Net..... 9,897.70
GST @ 7.0% 692.84
Total..... 10,590.55
Paid..... 0.00
Please Pay.. 10,590.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated