

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

13 AUG 2019

E S T I M A T E

Estimate No. : b1 52281
Date Estimated : 13/08/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Boh Thai See
132 Pasir Panjang Road
#05-03

Singapore 118549

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGW2011B	5L53297	25/09/2018	216i GT	0

DESCRIPTION

VALUE

To replace right front door, right rear door & R/i rear bumper, right rear fender and side skirt and attachment include knocking cause by the accident.

4250 5,100.00

Painting right front door and handle, right rear door and handle, right rear fender, right roof frame, right side skirt, rear bumper.

4528 5,032.00

To carry out body cavity preservation.
(Per panel).

200 236.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To transfer lock mechanism from old to new doors including conduct checks on new door power window system for proper functions. (2 doors).

902 1,062.00

Sundries.

150.00

Total Labour 1: 11,757.00

DESCRIPTION

QTY

PRIC

VALUE

FRT RH DOOR / DD	1	1,131.25	1,131.25
RR RH DOOR / DD	1	1,131.25	1,131.25
RH LOWER REAR DOOR HINGE X	1	58.60	58.60
RH UPPER REAR DOOR HINGE Y	1	58.60	58.60
DOOR HANDLE PAINTED OUTER RH (A96 M X R	1	533.55	533.55
RH OUTER DOOR HANDLE PRIMED X R	1	95.05	95.05
RH COVERING PRIMEND X MC	1	47.55	47.55
RH COVERING PRIMEND X MC	1	47.55	47.55
REAR DOOR BRAKE X	1	73.85	73.85
FRT RH DOOR INSIDE CHANNEL SEALING X	1	60.90	60.90
FRT RH DOOR EXTERIOR CHANNEL COVER X MC	1	94.10	94.10
RH SEALING COLUMN B BOTTOM X MC	1	54.30	54.30
REAR RH DOOR OUTER WEATHERSTRIP (AL X MC	1	94.10	94.10

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52281
Date Estimated : 13/08/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGW2011B	5L53297	25/09/2018	216i GT	0

DESCRIPTION	QTY	PRIC	VALUE
REAR DOOR JOINT SEAL ✓ <i>AK</i>	1	31.95	31.95
REAR DOOR EDGE PROTECTION ?	1	157.05	157.05
FRT DOOR EDGE PROTECTION ?	1	157.05	157.05
RH SEAL A PILLAR ✓ <i>AK</i>	1	48.35	48.35
FRT DOOR JOINT SEAL ✓ <i>AK</i>	1	31.95	31.95

Total Parts : 3,907.00

LKK Auto Centre will notify the Repairer of the following:

- To resurvey the work after painting
- To display the work for resurvey
- Parts price information
- Third party work on "Without Prejudice" basis
- No illegal modification allowed
- Supplementary item must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 20/8/19, 1.20pm Excess S\$ _____
Surveyor's Name Steve (LKK) Sign _____
Surveyor's Tel 8322 8813 Authorised Yes / No
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
Surveyor's E-mail _____
No. of Working Days Recommend _____

WML Original

*8 days
P/P
Ry Bel sm*

Labour 1	:	11,757.00
Parts	:	3,907.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,096.48
Grand Total	:	16,760.48

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **