

CT AUTO PTE LTD

160 Sin Ming Drive, #02-14, Sin Ming AutoCity, Singapore 575722

Tel: 62666727 Fax: 62666358 Email: admin@ctauto.com.sg

Business Registration No. 201420132H

GST Registration No. 201420132H

ESTIMATE

Date: 13/8/2019

DOA: 9/7/2019

Vehicle No: XE1707C

Make & Model: Hino RK1JMK 10034

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Frt L/H Head Lamp	\$ 1,020.00	<i>Repair</i>
2	1	Frt L/H Head Lamp Outer Cage	\$ 234.20	<i>Repair</i>
3	1	Frt L/H Signal Lamp	\$ 467.20	<i>X</i>
4	1	Frt L/H Side Lamp	\$ 164.20	<i>X</i>
5	1	Frt L/H Corner Bumper	\$ 864.20	<i>Repair</i>
6	1	Frt L/H Lower Foot Step Garnish	\$ 242.50	<i>con</i>
7	1	Frt L/H Centre Foot Step Garnish	\$ 462.20	<i>con</i>
8	1	Frt L/H Upper Foot Step Garnish	\$ 687.50	<i>X</i>
9	1	Frt L/H Upper Foot Step Garnish Reflector Lamp	\$ 124.20	<i>X</i>
			\$ 4,266.20	
		Less 10%	\$ 426.62	
			\$ 3,839.58	
		Special Nett Items		
1		Sundries	\$ 50.00	<i>X</i>
2	1 set	Frt L/H Corner Bumper Clips	\$ 80.00	<i>X</i>
3	1 set	Frt L/H Lower Foot Step Garnish Clips	\$ 80.00	<i>X</i>
4	1 set	Frt L/H Centre Foot Step Garnish Clips	\$ 80.00	<i>X</i>
5	1 set	Frt L/H Upper Foot Step Garnish Clips	\$ 80.00	<i>X</i>
			\$ 320.00	
		Total parts	\$ 4,159.58	
S/N	Labour Description		Amount	Amount
1	Labour for panel beating, cut, weld, straighten panels and replace damaged parts.		\$ 1,500.00	<i>400</i>
2	To putty and spray painting damage portion.		\$ 1,000.00	<i>200</i>
3	To check lighting and wiring.		\$ 150.00	<i>30</i>
4	To apply anti rust proofing to affected area.		\$ 250.00	<i>X</i>
5	To perform 4 wheel alignment and balancing.		\$ 450.00	<i>X</i>
	Total labour :		\$ 3,350.00	
	Total parts :		\$ 4,159.58	
	Total labour :		\$ 3,350.00	
	Total repair cost : (Before GST)		\$ 7,509.58	

Repair
Hp 900 10068
3 days
h/s
15/08/19 @ 1420
Recovery after repair