

14/08/2019

CT AUTO PTE LTD

160 Sin Ming Drive, #02-14, Sin Ming AutoCity, Singapore 575722
Tel: 62666727 Fax: 62666358 Email: admin@ctauto.com.sg
Business Registration No. 201420132H
GST Registration No. 201420132H

ESTIMATE

Date: 13/8/2019
DOA: 9/7/2019

Vehicle No: XE1707C
Make & Model: Hino RK1JMK 10034

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Frt L/H Head Lamp	\$ 1,020.00	Chai
2	1	Frt L/H Head Lamp Outer Cage	\$ 234.20	Repair
3	1	Frt L/H Signal Lamp	\$ 467.20	X SUC
4	1	Frt L/H Side Lamp	\$ 164.20	X SUC
5	1	Frt L/H Corner Bumper	\$ 864.20	Repair
6	1	Frt L/H Lower Foot Step Garnish	\$ 242.50	Chai
7	1	Frt L/H Centre Foot Step Garnish	\$ 462.20	Chai
8	1	Frt L/H Upper Foot Step Garnish	\$ 687.50	X SUC
9	1	Frt L/H Upper Foot Step Garnish Reflector Lamp	\$ 124.20	X SUC
			\$ 4,266.20	
Less 10%			\$ 426.62	
			\$ 3,839.58	
<u>Special Nett Items</u>				
1		Sundries	\$ 50.00	X 2
2	1 set	Frt L/H Corner Bumper Clips	\$ 80.00	X X
3	1 set	Frt L/H Lower Foot Step Garnish Clips	\$ 80.00	X X
4	1 set	Frt L/H Centre Foot Step Garnish Clips	\$ 80.00	X X
5	1 set	Frt L/H Upper Foot Step Garnish Clips	\$ 80.00	X X
			\$ 320.00	
Total parts			\$ 4,159.58	
S/N	Labour Description		Amount	Amount
	Labour for panel beating, cut, weld, straighten panels and replace			
1	damaged parts.		\$ 1,500.00	400
2	To putty and spray painting damage portion.		\$ 1,000.00	200
3	To check lighting and wiring.		\$ 150.00	30
4	To apply anti rust proofing to affected area.		\$ 250.00	X 11
5	To perform 4 wheel alignment and balancing.		\$ 450.00	X 11
Total labour :			\$ 3,350.00	
Total parts :			\$ 4,159.58	
Total labour :			\$ 3,350.00	
Total repair cost : (Before GST)			\$ 7,509.58	

1724.70
10%
1552.23

0

630

1552.23
630.00
2182.23
20%
1745.78
4/5-1,750
3 days

Repair
Hp 900 10065
3 days
1/1
15/08/19 @ 1420
Recovery after repair