

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SH 7382J (Supplementary)

DATE : 14.08.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (LH/RH) <i>monky make</i>		\$ 1,388.00	\$ 2,776.00
				\$ 2,776.00
	SUB TOTAL			\$ 555.20
	LESS 20%			\$ 2,220.80
	DISCOUNTED TOTAL			
	<i>24k Ant</i>			
	<i>8</i>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				