



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 19/08/2019

Survey Details:

Date of loss	12-Aug-19
Date of appointment	14-Aug-19
Date of survey	16-Aug-19
Location of survey	BH AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLF 493L
Make and Model	VOLKSWAGEN GOLF
Date of registration	11/8/2016
Excess	
Market Value	\$73,000
Parf Rebate	\$48,298
Nett Loss	\$24,702

Repair details:

Initial Estimate	\$ 4,905.27
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ -
Check items (estimate)	\$ 1,920.95
Labour	\$ 380.00
Total	\$ 2,300.95
Lump Sum(if applicable)	\$ -
Number of days for repair	1-2



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs. We will seek mandate after our surveyor have verify the check items.

Mandate:

Liability(TP)	%	
Proposed repair cost	TBA	
Loss of use		no. of days
Loss of rental		no. of days
Loss of income		no. of days
LTA search fees		
Others		
Proposed Total	TBA	