



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

AXA INSURANCE SINGAPORE PTE LTD
NO. 8 SHENTON WAY,
#24-01 AXA TOWER, 068811
SINGAPORE

Attention : Motor Claim Department

Estimate : ES003512

Date : 13/08/2019
Vehicle Num. : SLN8361P
Make/Model : TOYOTA ALTIS
Chassis/Eng# : MR053REH104561285
Accident Date : 11/08/2019
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	LH SIDE MIRROR		1,250.00
2.	1	LH SIDE MIRROR BACK COVER		90.40
3.	1	LH FRONT FENDER		781.20
4.	1	LH FRONT FENDER EMBLEM VVTI		54.00
5.	1	FRONT BUMPER		485.00
6.	1	LH FRONT DOOR		1,100.00
7.	1	LH FRONT DOOR BLACK TAPE		66.10
List TotalS\$:				3,826.70
25.00% Discount S\$:				956.68
				2,870.02
LABOUR :				
TO TRANSFER SLIDING DOOR PARTS/MECHANISMS				50.00
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS				800.00
COMPUTERISED WHEEL ALIGNMENT				120.00
TO REMOVE/REPLACE PARTS & PANEL BEATING				450.00
TO REPAIR RESPRAY LH FRONT SPORTS RIM				150.00
Labour Total S\$:				1,570.00

SingDollars : Four Thousand Four Hundred Forty & Cents Two Only

E. & O.E.

Total S\$: 4,440.02

for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ■ No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg