

Estimate



Cecilg

EQ

Your Ref Vehicle No:
SKK7404J(TP claim)

Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

Date: 14/8/2019
Vehicle No: SLD9062Z
Model: HONDA CRV
Date of loss: 7/8/2019
Our ref: SLSA300TJS
Year: 2016

Qty	Description	List Price	Remarks
1.00	FRONT BUMPER	\$ 598.20	de ✓
10.00	FRONT BUMPER CLIP	\$ 30.00	per ✓
2.00	FRONT BUMPER RETAINER	\$ 32.40	L4X ⁿⁿ R4 ✓
1.00	FRONT RHS FENDER	\$ 631.20	R ✓
1.00	FRONT RHS HEADLAMP	\$ 1,548.20	cut ✓
1.00	FRONT BUMPER LOWER LIP	\$ 482.20	cut ✓
1.00	FRONT FENDER ARC GARNISH	\$ 188.60	cut ✓
1.00	FRONT RHS DOOR		
REPAIR			
TOTAL: \$		3,510.80	2847.20
LESS 20 %: \$		702.16	569.44
		\$ 2,808.64	2277.76 ✓

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 900.00	600
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 800.00	600
1.00	CHECK WIRING	\$ 80.00	30
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$ 80.00	30
TOTAL: \$		1,860.00	1260.00 ✓

SUBTOTAL: \$ 4,668.64 3537.76 -20% (45)
= \$2830.00

Estimate prepared by: TOH KHAR KIAN

Telephone: 83987469

tohkk_90@hotmail.com

Tanlim 97495449 = \$2800 ✓

wp'
15/8/19 1220

sur e (lilanto.com)

Review after repair.
4 days

4/12 Email to Toh
1592800, 4 days