

AlGAsia Insured's Veh No : SKJ2477L

Date of Accident : 07 August 2019

Messrs Kwong Woh Hing Sauce Factory Pte Ltd

not submit
2300
4 dr.
15/8/19

LIK Auto Consultants hence notify
the Repair of the following
TAN LIM MOTOR PTE LTD
10 Resurvey, Refurbish, Spray painting
• Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
• GST Regn. No. : M2-8922054-2
• No modification(s) is allowed
• Supplementary item(s) must be resurveyed and
subject to final approval from Insurance Company
Acknowledged by Repair Date: 07 August 2019
Signature:
Date:

Estimate To Repair GBG4210Z - Toyota HIACE 2.0DX A

Chassis No : KDH2010205133

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	right sliding door <i>5050</i>	\$ 1,268.10
02	1 pc	right sliding door upper hinge <i>11</i>	\$ 68.00
03	1 pc	right sliding door lower hinge <i>11</i>	\$ 68.00
04	1 pc	right sliding door lower mechanical lock <i>11</i>	\$ 249.10
05	1 pc	right sliding door lower mechanical lock cable <i>11</i>	\$ 90.00
06	1 pc	right sliding door inner trimboard <i>20.1</i>	\$ 435.80
07	1 pc	right sliding door weatherstrip <i>11</i>	\$ 236.70
08	1 pc	right sliding door roller rear <i>11</i>	\$ 162.90
09	1 pc	right sliding door roller top <i>11</i>	\$ 98.10
10	1 pc	right sliding door roller bottom <i>7w1</i>	\$ 322.90
11	1 pc	right sliding door handle <i>11</i>	\$ 182.40
12	1 pc	right sliding door rail track <i>11</i>	\$ 279.80
13	2 ps	right sliding door rail track stopper @ \$35.00 <i>11</i>	\$ 70.00
14	1 pc	right sliding door outer handle inner base <i>11</i>	\$ 98.00
15	1 pc	right sliding door channel weatherstrip <i>11</i>	\$ 374.00
			\$ 4,003.80
Less 25 %			\$ 1,000.95
			\$ 3,002.85
SPECIAL NETT ITEMS			
16	1 pc	right sliding door window glass sealant <i>rel</i>	\$ 120.00
17	1 pc	right sliding door window glass inner sponge seal <i>rel</i>	\$ 80.00
18	1 pc	right sliding door advertisement sticker <i>rel</i>	\$ 1,000.00
			\$ 1,200.00
LABOUR & MISC. CHARGES			
01		To transfer of right sliding door fittings and perform water seepage test.	\$ 200.00
02		To remove and refit right sliding door window glass.	\$ 120.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 600.00
04		Putty and spray painting of the affected portion.	\$ 400.00
			\$ 1,320.00
Total			\$ 5,522.85

✓
X
X
X
X
2
X
X
X
2
X
X
X
X
X
X
X
X
2026.80
1520.1
40
30
800
870
60
80
200
200
540
2930.1
202
2344



EBT ART ENTERPRISE

2 Bukit Batok Street 24, #03-01 Skytech, Singapore 659480
Tel: 6565 5128 Fax: 6562 2238
Registration No.: 53141896X

Invoice

Bill No	: 12741
Date	: 20/8/19
Terms	:
Order By	:
Contact No.	:

ms Tan Lim Motor Pte Ltd

Item	Description	Unit Price	Amount
	Supply Remove &		
	Replace Existing Vental		
	part to Full print on		
	CASPERM sticker only		
	GBG 4702		8650 +
	(Duration time: 2 working days)		

Cheques should be crossed, and made payable to "EBT ART ENTERPRISE"

Total \$ 650 +

Received by

Authorised by

8/10