

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

(SUPPLEMENTARY)

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
LOCHERS TRADING

Singapore

Claimant Insurer: MSIG Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	70778
Policy No:	DMCVSN15574919033	Date of Loss:	13/08/2019
Vehicle Reg. No.:	SGA9802E	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LOH CHION YAU		
Make/Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Vehicle Reg. Date:	15/05/2015
Vehicle Colour:	SILVER	Chassis No:	JM6BM42A8G0310353
Engine No:	P520282586		
Odometer:	92229 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	466.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	466.00
+ GST 7.00% (S\$)	32.62
Nett Amount (S\$)	498.62
+ Previous Estimates (S\$)	3,844.15
Claim Total (S\$)	4,342.77

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 29 Nov 2019)**Parts:** 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SGA9802E/29/11/2019 15:23**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*UPP RAD GRILLE COVER	0.00	0.00	<i>nd</i> *160.00 F —
2	1		*L/F BUMPER COVER	0.00	0.00	<i>nd</i> *15.00 F —
3	1		*L/R COVER	0.00	0.00	<i>nd</i> *16.00 F —
4	1		*L/BUMPER BRACKET	0.00	0.00	<i>Di</i> *15.00 F —
5	1		*R/BUMPER BRACKET	0.00	0.00	<i>Di</i> *15.00 F —
6	1		*L/REINF EXTENSION	0.00	0.00	<i>B</i> *180.00 F —
7	1		*L/F WING DEFLECTOR	0.00	0.00	<i>cm</i> *65.00 F —

F=Franchise part.

Total Parts (\$\$)**466.00****Lai Huat (Meng Kee) Motor Pte Ltd/SGA9802E/29/11/2019 15:23.** Not valid without Reference section.Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Lai Huat (Meng Kee) Motor Pte Ltd/SGA9802E/29/11/2019 15:23. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >