

ASS. REC. BY:

REF: CS/FCI 19014190/UV 8302 Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Henny Kao of FCI Date/Time: 15.8.19 9.47am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLN 4669D Insured: SHB 34305at Workshop m/s RICO 60 Auto Tel: 9187 8064of 8 kaki Bukit Ave 4 #02-26 PremierPolicy No: _____ Claim No: D19005227 MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11.8.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 15.8.19 9.45am Person Contacted: Shanellu Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLN 4669D - NA/ FWD 19014032/14 D.O.A - 11/08/2019
	SHB 34305 - NA/ FWD 19014032/14 D.O.A - 11/08/2019
16/8/19	Email preli revised to FCI

08/11/13) wef

ASS. REC. BY: *Morley*

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

21/8 - typist

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

) S + RS, \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

CWS

1200/2

TX15:105

170 + 105

50

50

45

21/8/19

420

RECEIVED 21 AUG 2019

21/8/19 2/5 # 1200 confirmed with John. (Ref 16.475.55, 939)

MY: \$12K (EST) LTA: \$8441 NV: \$3559



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19005227MFSH

Our ref: CS/FCI19014190/Uvf3

DATE: 16/8/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO SLN 4669D


We thank for your instruction on 15/8/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 15/8/2019 at the premises of M/s RICO 60 AUTO SERVICES PTE LTD

Workshop Estimate Amount	: S\$17,672.55
Revised Estimate Amount	: S\$1,764.46
"Check" Items Amount	: S\$928.42
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front n/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	14-08-2019	Our Ref No. D19005227MFSH
Accident Date	11-08-2019	Claim Type. Third Party
Insured Vehicle	SHB3430S	Third Party Vehicle. SLN4669D
Survey Location	8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT	
Contact Person.	SHANELLE LIM	
Contact No.	62866060/ 91878064	Fax No. 62867060
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	RICO 60 AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 16 August 2019 12:22 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Henry Kao'
Subject: RE: SURVEY ASSESSMENT - D19005227MFSH/1-SLN 4669D
Attachments: SLN 4669D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLN 4669D
Date of survey: 15/8/2019
Number of days (estimated) :3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 15 August 2019 9:47 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005227MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 15 August, 2019 9:37 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005227MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

**Budget
Direct
insurance**

Car insurance due?
Pay Less or Get \$100*, even if you don't buy.

[Get a Quote >](#)

*Terms and conditions apply.

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Coe Renewal Toyota Estima 2.4A



1 owner & \$4000 Down 50
Admin 2 Year Warranty Sta
Green & No Major Org Merit
F&S
GV Credit Pte Ltd [Search](#)

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years
of car sale

Sort by Date Posted 20 results/page

6 vehicles

TOYOTA VIOS

Basic Search

Price Any price Depre Any depre Reg Date 2010 to 2010 Eng Cap Any Veh Type All types
Fuel Any fuel Mileage Any OMV Any Gear Any Gear Past Owners Any
Category All categories Scheme All schemes Dealer Any Dealer Location Any Status Available

Make & Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Toyota Vios 1.5A G (OPC) One Meticulous Owner. G Model Highest Specs Among All. OPC Car Converted To Normal Car Usage. 93,849km Mileage Clocked Only. Under-Usage Low Mileage. Well Maintained In Tip Top Condition Great For Short Term Commitment Or COE Renewal. Most Reliable Jap... Posted: 06-Aug-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota	\$16,800	\$9,950 /yr	13-Aug-2010	1,497 cc	93,849 km	Sedan	Available
Toyota Vios 1.5A E High Loan! High Trade In! Popular Car Suitable For COE Renewal! Make Use Of The Low COE Prices! Call Now! Posted: 06-Aug-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota	\$15,800	\$12,340 /yr	25-May-2010	1,497 cc	-	Sedan	Available
Toyota Vios 1.5M E In Excellent Running Condition. No Repairs/replacements Needed. Definitely Able To Renew 10/5 Year COE. Most Value For Money Reliable Japanese Sedan On The Market Now. Posted: 31-Jul-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota	\$12,888	\$10,290 /yr	19-Apr-2010	1,497 cc	150,000 km	Sedan	Available
Toyota Vios 1.5A E (New 5-yr COE) New 10 Years COE At \$44,800. Low Mileage Done. Well Kept. In House Loan/Bank Loan Available. Posted: 28-Jul-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota	\$29,800	\$5,950 /yr	25-Jan-2010	1,497 cc	142,000 km	Sedan	Available
Drop-top MINI Cooper S is a charming car The facelifted MINI Cooper S Convertible offers buckets load of charm and driving performance. Find out more!							
Toyota Vios 1.5A E Accident Free. Very Well Maintained, Genuine Low Mileage. Immaculate Condition, Easy Maintenance And Very Good Fuel Consumption. Female Owner. Call Us For A Viewing Anytime! Posted: 25-Jul-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota	\$15,000	\$11,310 /yr	25-May-2010	1,497 cc	103,098 km	Sedan	Available
Toyota Vios 1.5A E Sports 100% Loan Approval With Low Interest Rate! Interest As Low As 2.78%, Coolest Low Mileage Unit, Definitely Not The Cheapest But For Sure One Of The Better Condition Unit, Quality Is The Key Not The Price! New Paintwork Done, Borneo Agent Servicing Done, Superb C... Posted: 16-Jun-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota	\$18,800	\$11,810 /yr	08-Sep-2010	1,497 cc	93,000 km	Sedan	Available

Make & Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For Compare

s, view Expired ads

20 results/page

> Back to OneMotoring


Summary

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	740A
Vehicle Details	
Vehicle No.:	SLN4669D
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	1NZY075309
Chassis No.:	MR053HY9305160759
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,331.00
Original Registration Date:	15 Apr 2010
First Registration Date:	15 Apr 2010
Transfer Count:	2
Actual ARF Paid:	\$12,331.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Apr 2020
PARF Rebate Amount:	\$6,165.00
Intended COE Rebate Details	
COE Expiry Date:	14 Apr 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$34,001.00
COE Rebate Amount:	\$2,276.00
Total Rebate Amount:	\$8,441.00

The information contained herein is correct as at 13 Aug 2019

OK



not Adult
nln
^/ < #1200/
15/8/19
3 dy.

ATTN			Tehphl. Hlong		3a
NO.	DESCRIPTION - PARTS		QTY	PRICE	
1	BONNET		11	1	\$ 482.60
2	BONNET LOCK		11	1	\$ 118.58
3	BONNET CATCH		11	1	\$ 46.90
4	BONNET INSULATOR		11	1	\$ 247.40
5	BONNET HINGE (L+R)		11	2	\$ 178.00
6	BONNET STOPPER (L+R)		11	2	\$ 24.00
7	HEADLAMP (L+R)		11	2	\$ 1,031.58
8	HEADLAMP BRACKET (L+R)		11	2	\$ 170.00
9	FRONT GRILLE	292.30	11	1	\$ 365.00
10	FRONT LOGO (TOYOTA)		11	1	\$ 65.00
11	FRONT BUMPER		11	1	\$ 393.66
12	FRONT BUMPER RETAINER (L+R)		11	2	\$ 109.48
13	FRONT BUMPER REINFORCEMENT BAR	299.50	11	1	\$ 346.30
14	FRONT BUMPER BRACKET (L+R)		11	2	\$ 243.20
15	FRONT BUMPER BEAM		11	1	
16	FRONT BUMPER SPONGE		11	1	
17	FRONT BUMPER GRILLE		11	1	\$ 296.70
18	FRONT BUMPER TOWING CAP		11	1	\$ 28.65
19	FRONT BUMPER FOG LAMP (L+R)		11	2	\$ 669.40
20	FRONT BUMPER FOG LAMP GARNISH (L+R)		11	2	\$ 436.60
21	FRONT FENDER (L+R)		11	2	\$ 1,002.40
22	FRONT FENDER COWLING (L+R)		11	2	\$ 156.00
23	FRONT FENDER EMBLEM (VVT-i)		11	1	\$ 37.30
24	FRONT SUPPORT PANEL		11	1	\$ 771.60
25	FRONT SUPPORT PANEL TOP GARNISH		11	1	\$ 236.90
26	AIR CON CONDENSOR		11	1	\$ 980.70
27	HIGH PRESSURE HOSE		11	1	\$ 146.90
28	LOW PRESSURE HOSE		11	1	\$ 143.60
29	RADIATOR		11	1	\$ 1,522.71
30	DISCHARGE PIPE		11	1	\$ 213.40
31	SUCTION PIPE		11	1	\$ 211.30
32	RADIATOR FAN COWLING		11	1	\$ 457.90
33	RADIATOR FAN BLADE		11	1	\$ 126.70
34	RADIATOR FAN MOTOR		11	1	\$ 296.70
35	WIPER WASHER TANK		11	1	\$ 279.60
36	WIPER WASHER MOTOR		11	1	\$ 188.30
		9-985.46			
		25%			
		739.09			
			SUBTOTAL		\$ 12,025.06
			LESS 10%		\$ 1,202.51

		PARTS TOTAL		\$ 10,822.55
	SPECIAL NETT		QTY	PRICE
1	BONNET INSULATOR CLIP	11	10	\$ 100.00
2	FRONT BUMPER CLIP	per	10	\$ 100.00
3	FRONT CARPLATE	11	1	\$ 120.00
4	FRONT CARPLATE FRAME	11	1	\$ 120.00
5	FRONT FENDER COWLING CLIP	11	10	\$ 100.00
6	RADIATOR COOLANT	11	1	\$ 100.00
	SPECIAL NETT TOTAL			\$ 640.00
	LABOUR		QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	300	1	\$ 2,400.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	400	1	\$ 2,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	11X	1	\$ 250.00
4	TO RNR UPHOSTERY, GARNISH AND ATTACHMENT PARTS	11X	1	\$ 400.00
5	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	11X	1	\$ 120.00
6	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	20	1	\$ 120.00
7	TO CHECK WIRING LAYOUT AND FOG LAMP FOCUS	11X	1	\$ 120.00
8	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11X	1	\$ 200.00
9	TO DO WATER LEAK TEST .	11X	1	\$ 80.00
10	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	11X	1	\$ 120.00
	TOTAL			\$ 6,210.00
	GRAND TOTAL COST			\$ 17,672.55

PAGE 2 OF 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No additional modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

1509.09
202
1207



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19014190/Uvf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3430S	Veh. Inspected	SLN 4669D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005227MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	15/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MR053HY9305160759	Colour	GREY	
Odometer	203643	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	ALTIMEX	6 mm	
L/H Front Tyre	185/60 R15	ALTIMEX	6 mm	
R/H Rear Tyre	185/60 R15	FALKEN	6 mm	
L/H Rear Tyre	185/60 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/08/2019	Inspection Date	15/08/2019	
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 4669D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	NOT NECESSARY	482.60	-
1	BONNET LOCK	NOT NECESSARY	118.58	-
1	BONNET CATCH	NOT NECESSARY	46.90	-
1	BONNET INSULATOR	NOT NECESSARY	247.40	-
2	BONNET HINGE (L+R)	NOT NECESSARY	178.00	-
2	BONNET STOPPER (L+R)	NOT NECESSARY	24.00	-
2	HEADLAMP (L+R)	NOT NECESSARY	1,031.58	-
2	HEADLAMP BRACKET (L+R)	NOT NECESSARY	170.00	-
1	FRONT GRILLE	CRACKED	365.00	292.30
1	FRONT LOGO (TOYOTA)	NOT NECESSARY	65.00	-
1	FRONT BUMPER	TORN	393.66	393.66
2	FRONT BUMPER RETAINER (L+R)	NOT NECESSARY	109.48	-
1	FRONT BUMPER REINFORCEMENT BAR	BENT	346.30	299.50
2	FRONT BUMPER BRACKET (L+R)	NOT NECESSARY	243.20	-
1	FRONT BUMPER BEAM (NPA)	NO SUCH PARTS	-	-
1	FRONT BUMPER SPONGE (NPA)	NO SUCH PARTS	-	-
1	FRONT BUMPER GRILLE	NOT NECESSARY	296.70	-
1	FRONT BUMPER TOWING CAP	NOT NECESSARY	28.65	-
2	FRONT BUMPER FOG LAMP (L+R)	NOT NECESSARY	669.40	-
2	FRONT BUMPER FOG LAMP GARNISH (L+R)	NOT NECESSARY	436.60	-
2	FRONT FENDER (L+R)	NOT NECESSARY	1,002.40	-
2	FRONT FENDER COWLING (L+R)	NOT NECESSARY	156.00	-
1	FRONT FENDER EMBLEM (VVT-I)	NOT NECESSARY	37.30	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	771.60	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	236.90	-
1	AIR CON CONDENSOR	NOT NECESSARY	980.70	-
1	HIGH PRESSURE HOSE	NOT NECESSARY	146.90	-
1	LOW PRESSURE HOSE	NOT NECESSARY	143.60	-
1	RADIATOR	NOT NECESSARY	1,522.71	-
1	DISCHARGE PIPE	NOT NECESSARY	213.40	-

Report Ref No. CS/FCI19014190/Uvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUCTION PIPE	NOT NECESSARY	211.30	-
1	RADIATOR FAN COWLING	NOT NECESSARY	457.90	-
1	RADIATOR FAN BLADE	NOT NECESSARY	126.70	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	296.70	-
1	WIPER WASHER TANK	NOT NECESSARY	279.60	-
1	WIPER WASHER MOTOR	NOT NECESSARY	188.30	-
	LESS 10% DISCOUNT		-1,202.51	-
	LESS 25% DISCOUNT		-	-246.37
			10,822.55	739.09
	SPECIAL NETT ITEMS			
10	BONNET INSULATOR CLIP (SN)	NOT NECESSARY	100.00	-
10	FRONT BUMPER CLIP (SN)	NECESSARY	100.00	50.00
1	FRONT CARPLATE (SN)	NOT NECESSARY	120.00	-
1	FRONT CARPLATE FRAME (SN)	NOT NECESSARY	120.00	-
10	FRONT FENDER COWLING CLIP (SN)	NOT NECESSARY	100.00	-
1	RADIATOR COOLANT (SN)	NOT NECESSARY	100.00	-
			640.00	50.00
	LABOUR			
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD,KNOCK & REALIGN.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		2,400.00	300.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		2,400.00	400.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.	NOT NECESSARY	250.00	-
	TO RNR UPHOLSTERY,GARNISH AND ATTACHMENT PARTS.	NOT NECESSARY	400.00	-
	TO RNR A/C CONDENSOR ASSY AND REFILL GAS.	NOT NECESSARY	120.00	-
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS.		120.00	20.00
	TO CHECK WIRING LAYOUT AND FOG LAMP FOCUS.	NOT NECESSARY	120.00	-
	TO DO DIAGNOSIS AND RESET,REPROGRAM OR CODING DAULT CODE.	NOT NECESSARY	200.00	-
	TO DO WATER LEAK TEST.	NOT NECESSARY	80.00	-
	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD.	NOT NECESSARY	120.00	-
			6,210.00	720.00

Report Ref No. CS/FCI19014190/Uvf3n2



GRAND TOTAL		17,672.55	1,509.09
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00

Report Ref No. CS/FCI19014190/Uvf3n2

MARKET VALUE: \$12,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$8,441.00=NETT VALUE: \$3,559.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.