

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

15 AUG 2019

Estimate No. : b1 52327
Date Estimated : 15/08/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Teo Yi Sheng Jason
Blk 150 Ang Mo Kio Avenue 5
#05-3048
Singapore
Singapore 560150

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ625R	5H48085	27/06/2017	X1 sDrive18i	0

DESCRIPTION

To replace front bumper, fender right and attachments.

1700 2,550.00

Painting front bumper and fender right.

1996 2,218.00

To replace left or right headlight.

408 481.00

To replace tyre and wheel rim including balancing. (1x).

80 94.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)

451 531.00

To carry out body cavity preservation.
(Per panel).

100 118.00

Sundries.

? 80.00

Total Labour 1: **6,072.00**DESCRIPTION

LIGHT ALLOY WHEEL Y SPK 569
RH WHEEL HOUSING STRUT EXTENSION
FRT RH SIDE PANEL
FRT BUMPER PANEL PRIMED (PDC/PMA)
RH OPEN GRID (BASIC PDC)
FRT BUMPER PANEL LOWER SECTION (PDC)
FRT RH WHEEL ARCH TRIM
RH HEADLIGHT LED TECHNOLOGY

QTY	PRIC	VALUE
1	1,006.00	ut ✓ 1,006.00
1	147.10	? 147.10
1	664.00	bt ✓ 664.00
1	854.55	de ✓ 854.55
1	111.45	? 111.45
1	281.80	ut ✓ 281.80
1	151.00	ut ✓ 151.00
1	2,670.85	ut ✓ 2,670.85

Total Parts : **5,886.75**

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 52327**
Date Estimated : **15/08/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ625R	5H48085	27/06/2017	X1 sDrive18i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 2/9/19 10:20 Excess S\$ _____

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 97495419 Authorised Yes / No

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanjiah@lkkauto.com

No. of Working Days Recommend 05 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,072.00
Parts	:	5,886.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	837.11
Grand Total	:	12,795.86

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **