

ASS. REC. BY:

REF: CS/C71 K014232 / K9F3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chong Bron Sen

of

C71

Date/Time: 15.8.19 3.30pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 992K

Insured:

SLC 1812J

at Workshop m/s:

E M Solution

Tel:

910 18302

of 160 sin ming drive #03-18/19

Policy No:

DMP CSN 3013311 9000

Claim No:

SNM19D203769 602

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13.8.2019

CA / REV / REP. / REV 24 HRS

"up"

Date/Time:

15.8.19

4.40pm

Person Contacted:

Bernard

H.O.D. Endorsement:

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SLP 992K - X
	SLC 1812J - X
26/8	11 Pgs @ 83000 email & confirm (RED @ 10382.65, 56%)

REF: C12

Surveyor

ASSIGNMENT

From:

Date: 16.8.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 992K

at Workshop m/s EM Solution

of 160 Sin Ming Drive #03-18/19

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

rep.

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLP 992K

Yr Regn:

05/17

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Lexus

A)

ES250 c.c

2494

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

428/43

T/Radio: Insured / Std / NI / NA

Eng/No:

JTHBJGG 402095678

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

2

mm

L/Bal.

7

mm

L/Bal.

P

mm

D.O.A.

13/8/19

D.O.I.

16/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R & L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 04 OCT 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 04/10 10:45

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

220

Report Format: MER-TP

Lump Sum / I.D.I. (\$) 8300

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 15 August 2019 3:30 PM
To: Sally Chong
Cc: 'EM Solution Pte Ltd'; derekkeh@singnet.com.sg; judysoh@visionlawllc.com; Tanvin13@yahoo.com.sg; assignments
Subject: RE: OUR REF: SNM19D203769-SLC1812J-CBS - RE: OUR REF.: E21.111266.19 (SLP 992K @ 13.08.2019)// CHINA TAIPING REF NO : SLC 1812J

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Sally Chong [mailto:sallychong@visionlawllc.com]
Sent: Thursday, 15 August, 2019 3:17 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: 'EM Solution Pte Ltd' <emautosolution@singnet.com.sg>; derekkeh@singnet.com.sg; judysoh@visionlawllc.com; Tanvin13@yahoo.com.sg
Subject: RE: OUR REF: SNM19D203769-SLC1812J-CBS - RE: OUR REF.: E21.111266.19 (SLP 992K @ 13.08.2019)// CHINA TAIPING REF NO : SLC 1812J
Importance: High

URGENT

Dear Boon Sen,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES
CLAIMANT: ONG CHONG CHUAM SMAUEL
ACCIDENT INVOLVING SLP 992K & SLC 1812J ON 13 AUG 2019 ALONG HOUGANG AVE 4 AT ABOUT 16:43 HRS

We refer to your email of even date below and your list of surveyors therein.

Our client now confirms the appointment of **KENNETH KONG** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

Venue : **E M SOLUTION PTE LTD**
160, Sin Ming Drive, #03-18/19, Sin Ming Autocity,
Singapore 575722
Contact : Mr. Bernard (Tel.: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

Sent: Thursday, 15 August, 2019 1:31 PM

To: Sally Chong

Cc: EM Solution Pte Ltd; derekkeh@singnet.com.sg; judysoh@visionlawllc.com; Tanvin13@yahoo.com.sg

Subject: RE: OUR REF: SNM19D203769-SLC1812J-CBS - RE: OUR REF.: E21.MISC.19 (SLP 992K @ 13.08.2019)//
CHINA TAIPING REF NO : SLC 1812J

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, 15 August, 2019 12:06 PM

To: Sally Chong <sallychong@visionlawllc.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Cc: EM Solution Pte Ltd <emautosolution@singnet.com.sg>; derekkeh@singnet.com.sg; judysoh@visionlawllc.com; Tanvin13@yahoo.com.sg; LOD <lod@sg.cntaiping.com>

Subject: OUR REF: SNM19D203769-SLC1812J-CBS - RE: OUR REF.: E21.MISC.19 (SLP 992K @ 13.08.2019)// CHINA TAIPING REF NO : SLC 1812J

Dear Boon Sen,

Please conduct PRS for SLP992K.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Sally Chong [<mailto:sallychong@visionlawllc.com>]

Sent: Wednesday, 14 August, 2019 1:40 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>

Cc: EM Solution Pte Ltd <emautosolution@singnet.com.sg>; derekkeh@singnet.com.sg; judysoh@visionlawllc.com; Tanvin13@yahoo.com.sg; LOD <lod@sg.cntaiping.com>

Subject: OUR REF.: E21.MISC.19 (SLP 992K @ 13.08.2019) // CHINA TAIPING REF NO : SLC 1812J

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: ONG CHONG CHUAM SMAUEL

ACCIDENT INVOLVING SLP 992K & SLC 1812J ON 13 AUG 2019 ALONG HOUGANG AVE 4 AT ABOUT 16:43 HRS

We are instructed by **ONG CHONG CHUAM SMAUEL** to notify you of a road traffic accident **ON 13 AUG 2019 ALONG HOUGANG AVE 4 AT ABOUT 16:43 HRS** involving our client's vehicle registration number **SLP 992K** and vehicle registration number **SLC 1812J** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

C.c.: VEHICLE OWNER OF SLC 1812J

TANG WENG KAY

220 Ang Mo Kio Ave 1,

#02-817,

Singapore 560220

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/08/2019 14:20
Date Of Accident	13/08/2019 16:45
Exact Location Of Accident	HOUGANG AVE 4
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLP992K
Insured/Policyholder	
Name Of Registered Owner	ONG CHONG CHUAN SAMUAL (WANG CHONGQUAN, SAMUAL)
NRIC No	S8101133H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90028713
Alternative Phone No	OTHERS-90028713
Vehicle Particulars	
Manufacturer	LEXUS
Model	250 ES
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI18V15263/VPC/R00
Cover Note Number	
Driver	
Name of Driver	ONG CHONG CHUAN SAMUAL (WANG CHONGQUAN, SAMUAL)
NRIC No	S8101133H
Date Of Birth	13/01/1981
Occupation	INDOOR
Date Of Driving Pass	03/04/2014
Driving Experience	5 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90028713
Fax Number	
Contact Number	OTHERS-90028713
EMail Address	NOEMAIL

Address	BLK 930 HOUGANG STREET 91 #13-119
Postcode	530930
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC1812J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MR LIAU ZHAN YI
NRIC/Passport Number	T00085811
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/8/19 at about 4:43pm I was driving my vehicle - SLP 992 K along HONGKONG AVE 4 extreme right lane going straight. Out of a sudden - a vehicle - SLC 1812 J from the left side of the road did not stop at the stop line junction and collided onto the left-side of my vehicle. My vehicle's camera captured the whole incident and I submitting for TPI claim against SLC 1812 J for my losses.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax:

64584500

Registration No: 201016308K

15.08.2019

Ong Chong Chuan, Samuel

Not Authorized

*Resurvey After Paint
C/Smp @ 8300/hr*

5 days

*T
JT1HBJGG 402095678*

REPAIR ESTIMATE FOR LEXUS ES250 - SLP 992 K

1 pc	front bumper
2 pcs	front bumper side retainers
2 pcs	front bumper fog lamps
2 pcs	front bumper fog lamp grilles
1 pc	front bumper tow hood cover
4 pcs	front bumper parking sensors
1 pc	front bumper reinforcement
1 pc	front bumper inner foam
1 pc	front grille
1 pc	front grille chrome moulding
1 pc	front grille emblem
1 pc	LH headlamp assy → 4789.30
1 pc	LH front fender → 1314.70
1 pc	LH front fender inner shield
1 pc	LH front shock absorber
1 pc	LH front lower arm
1 pc	LH front knuckle arm → 774.90
1 pc	LH front wheel bearing

<i>mg cm / Bu</i>	960.30	✓
<i>nl/cm</i>	75.10	✓
<i>nl/mg cm</i>	194.50	✓
	136.70	✓
	93.50	✓
	412.95	✓
	1,651.80	✓
	493.95	✓
	137.80	✓
	1,181.40	✓
	383.90	✓
	459.90	✓
<i>cm</i>	6,007.80	✓
<i>B</i>	1,370.90	✓
<i>cm</i>	242.95	✓
<i>B</i>	460.70	✓
<i>D.I</i>	549.80	✓
<i>B</i>	897.40	✓
<i>m</i>	112.95	✓
	15,817.65	
Less 10%	1,581.77	
	14,235.89	

1 set	front bumper clips
1 set	RH front fender inner shield clips
1 pc	RH front sport rim

<i>m</i>	45.00	SN	✓
<i>m</i>	30.00	SN	✓
<i>nd / an</i>	580.00	SN	✓

- 1) Check electrical wirings
- 2) Repair damages and renew parts.
- 3) Renew front parking sensors
- 4) Lower front suspension to facilitate repair
- 5) Computerize wheel alignment
- 6) Spray paint on affected portions.
- 7) Rust proofing on affected portions.

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

60.00	201
800.00	4501
100.00	501
300.00	2001
100.00	601
800.00	4801
50.00	301

\$ -18,682.65

17160.88

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119014232/KQF3N2
Date: 08/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN30133119000
Claimant Vehicle No : SLP992K	Insured Vehicle No : SLC1812J
Date of Loss: 13/08/2019	Nature of Claim: TP
	Claim No: SNM19D203769C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP992K	Engine No: 2ARF260435
Make & Model: LEXUS ES250, 2.5 (A)	Chassis No: JTHBJ1GG402095678
Reg. Date: 26/05/2017 (Man. Year: 2016)	Odometer: 42843 km
Colour: Metallic Grey	
Engine Capacity: 2494 cc	
Market Value/New Car Price: N/A	
Sum Insured (\$\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17	Rear Tyre Size: 215/55 R17
Front Left Side: Yokohama 7 mm	Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 7 mm	Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,890.88	9,164.68	5,726.20	38.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,290.00	920.00	41.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,100.88	10,454.68	6,646.20	38.86
Approved Total (Overridden) (\$\$)		8,300.00		
(\$\$)	17,100.88	8,300.00	8,800.88	51.46
+ GST 7.00/7.00% (\$\$)	1,197.06	581.00	616.06	51.46
Nett Amount (\$\$)	18,297.94	8,881.00	9,416.94	51.46

INSPECTION

Date of Assignment: 04/10/2019	
Date Inspected: 16/08/2019	Inspected At: E M Solution Pte Ltd (HQ) 160 Sin Ming Drive., #03-18, Sin Ming Autocity Singapore 575722
Estimated Period of Repair: 5.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2019)
Parts: 143	LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLP992K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked/Buckled	960.30 FL	*960.30 FL
2	1		*FRONT BUMPER SIDE RETAINERS	N/s Cracked	150.20 FL	*75.10 FL
3	1		*FRONT BUMPER FOG LAMPS	Ns Mtg Cracked/Os Serviceable	389.00 FL	*194.50 FL
4	2		*FRONT BUMPER FOG LAMP GRILLES	Serviceable	273.40 FL	*- FL
5	1		*FRONT BUMPER TOW HOOD COVER	Serviceable	93.50 FL	*- FL
6	4		*FRONT BUMPER PARKING SENSORS	Serviceable	1,651.80 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Repair	493.95 FL	*- FL
8	1		*FRONT BUMPER INNER FOAM	Serviceable	137.80 FL	*- FL
9	1		*FRONT GRILLE	Serviceable	1,181.40 FL	*- FL
10	1		*FRONT GRILLE CHROME MOULDING	Serviceable	383.90 FL	*- FL
11	1		*FRONT GRILLE EMBLEM	Serviceable	459.90 FL	*- FL
12	1		*LH HEADLAMP ASSY	Cracked	6,007.80 FL	*4,769.30 FL
13	1		*LH FRONT FENDER	Bent	1,370.90 FL	*1,314.70 FL
14	1		*LH FRONT FENDER INNER SHIELD	Cracked	242.95 FL	*242.95 FL
15	1		*LH FRONT SHOCK ABSORBER	Bent	460.70 FL	*460.70 FL
16	1		*LH FRONT LOWER ARM	Distorted	549.80 FL	*549.80 FL
17	1		*LH FRONT KNUCKLE ARM	Bent	897.40 FL	*774.90 FL
18	1		*LH FRONT WHEEL BEARING	Necessary	112.95 FL	*112.95 FL
19	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
20	1		*SET RH FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
21	1		*RH FRONT SPORT RIM	Dented/Cut	580.00 FS	*580.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 16,472.65 10,110.20
 - List Item Discount on L Items 10.00/10.00% (\$\$) 1,581.77 945.52

Total Parts (\$\$) 14,890.88 9,164.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ELECTRICAL WIRINGS	New	60.00	20.00
2	REPAIR DAMAGES AND RENEW PARTS	New	800.00	450.00
3	RENEW FRONT PARKING SENSORS	New	100.00	50.00
4	LOWER FRONT SUSPENSION TO FACILITATE REPAIR	New	300.00	200.00
5	COMPUTERIZE WHEEL ALIGNMENT	New	100.00	60.00
6	SPRAY PAINT ON AFFECTED PORTIONS	New	800.00	480.00
7	RUST PROOFING ON AFFECTED PORTIONS	New	50.00	30.00
Gross Labour Cost (\$\$)			2,210.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >