


Kp

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SHD 3624 P

OUR REF.: SMK 2751 R



TO: INDIA

CC: MOTOR CLAIMS DEPARTMENT

FAX:

DATE: 15/8/2019

FROM: CASSANDRA

FAX: 6452 5333

CONTACT: 8686 5188

MAKE & MODEL: HONDA FIT

CHASSIS NO.: GP51341083

ENGINE NO.: LEB149910

YEAR MADE: 2018

ACCIDENT DATE: 5 August 2019

FINALISED ESTIMATE FOR VEHICLE NO.: SMK 2751 R

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	FRONT BUMPER <i>755.00</i>		1	\$ 950.80
2	FRONT BUMPER CLIP		10	\$ 70.00
TOTAL: \$				1,020.80
LESS 20%: \$				(204.16)
PARTS TOTAL: \$				816.64

SPECIAL NETTLABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	200.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	15.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	220.00
TOTAL: \$		1,251.64
7% GST: \$		87.61
GRAND TOTAL: \$		1,339.25

PART BY PART: \$ ~~1,251.64~~

BEFORE GST

02 REPAIR DAYS

81095.00