



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985		NAME : Mr Tan Suan Peng ADDRESS : 41 Cambridge Road #06-17 Singapore 210041 TEL : 81822980		WIP : 44735 EXCESS : DATE: 28-Jun-19	
ATTN : MOTOR CLAIMS FAX :		VEH NO : SMK9769U		DATE IN :	
CHASSIS NO : JM6GL1072K0311919		MILEAGE :		CONTACT PERSON : Vion 63957877	
MODEL : MAZDA6		DATE REG.: 30-Apr-19		TYPE OF CLAIM : THIRD PARTY CLAIM	
POLICY NO. :					
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	1	FRONT BUMPER <i>sch</i>		\$ 1,211.90	
2	1	RETAINER RHS ?		\$ 17.10	
3	1	PROTECTOR RHS, FOGLAMP ?		\$ 65.80	
4	1	COVER RHS, FOGLAMP <i>X</i>		\$ 20.50	
5	2	SPRING, COVER <i>X</i>		\$ 21.80	
6	1	SENSOR SIDE, ULTRASONIC <i>X</i>		\$ 180.90	
7	1	RETAINER SIDE, SENSOR <i>X</i>		\$ 15.50	
8	12	CLIP, FRONT BUMPER <i>see</i>		\$ 44.40	
9	2	FASTENER, FRONT BUMPER <i>see</i>		\$ 6.00	
10	2	GROMMET, FRONT BUMPER <i>see</i>		\$ 5.80	
11	4	RIVET, FRONT BUMPER <i>see</i>		\$ 18.00	
12	8	RIVET, FRONT BUMPER <i>see</i>		\$ 32.00	
13	6	RIVET, FRONT BUMPER <i>see</i>		\$ 55.20	
14	8	RIVET, FRONT BUMPER <i>see</i>		\$ 32.00	
15	4	FASTENER, FRONT BUMPER <i>see</i>		\$ 12.80	
16	1	CHROME RHS ?		\$ 251.40	
17	1	BRACKET RHS, CHROME ?		\$ 37.10	
18	4	RIVET, BRACKET ?		\$ 32.00	
19	1	HEADLAMP RHS <i>see</i>		\$ 4,759.30	
20	1	PROTECTOR RHS, HEADLAMP ?		\$ 102.00	
21	3	CLIP, HEADLAMP <i>see</i>		\$ 12.00	
22	1	RIVET, HEADLAMP <i>see</i>		\$ 3.50	
		Front Fender RH <i>see</i>			
TOTAL PARTS				\$ 6,937.00	
LESS 10%				\$ 693.70	
TOTAL PARTS COST				\$ 6,243.30	
Labour Description					

1	MZ-BR-FRONT1	TO REPLACE FRONT BUMPER. TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.	1320	\$ 1,320.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER RH.		\$ 1,260.00
3	MZ-BR-FRTSEN	TO TRANSFER FRONT PEDESTRIAN SENSORS.	NETT	\$ 330.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X	\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7		TO SUPPLY BRILA PREMIUM COATING. (invoice)?	NETT	\$ 250.00
8	MZ-BR-SUNDRI	SUNDRIES.	20 NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 4,110.00
TOTAL PARTS	\$ -	\$ 6,243.30
TOTAL	\$ -	\$ 10,353.30
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Rasul
Hp 90010068
5 days
15/08/19 @ 1640
Remedy before paint