



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/ASM19014288/Kpa3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:KIAN CHUAN

Date : 19-05-2020



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHD 363L	<b>Veh. Inspected</b>	SHD 248L
<b>Policy No.</b>	VFX/P1680520	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S9M01WUM	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	15/08/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	RENAULT LATITUDE (A)	<b>c.c</b>	1995
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	VF1ABL15AUC282395	<b>Colour</b>	METALLIC WHITE / RED
<b>Odometer</b>	581778	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/60 R16	GITI	9 mm
<b>L/H Front Tyre</b>	215/60 R16	GITI	9 mm
<b>R/H Rear Tyre</b>	215/60 R16	GITI	8 mm
<b>L/H Rear Tyre</b>	215/60 R16	GITI	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	09/08/2019	<b>Inspection Date</b>	15/08/2019
<b>Survey held at</b>	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**