



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19014320/Gpa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 13-08-2020



ATTN: STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 1606K	Veh. Inspected	GBJ 5178L
Policy No.	CN040048	Coverage (\$)	0.00
Claim No.	S9M01X6X	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	16/08/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KDY2318038154	Colour	WHITE
Odometer	8974	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/75 R15	BRIDGESTONE	9 mm
L/H Front Tyre	175/75 R15	BRIDGESTONE	9 mm
R/H Rear Tyre	145 R13	BRIDGESTONE	9 mm
L/H Rear Tyre	145 R13	BRIDGESTONE	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/08/2019	Inspection Date	19/08/2019
Survey held at	53 DEFU LANE 12 SINGAPORE 539144		
Repairer	YONG SING MOTOR WORKS		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**