

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YL 9949U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT SIDE LAMP RH	CRACKED	140.00	140.00
1	FRONT HEAD LAMP RH	CRACKED	305.00	305.00
1	FRONT HEAD LAMP LOWER APRON PANEL RH	CRACKED	62.00	62.00
1	FRONT BUMPER	CRACKED	540.00	540.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	294.00	re-
2	FRONT BUMPER BRACKET @ \$108.00	NOT NECESSARY	216.00	-
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,425.00	-
1	FRONT DOOR GLASS OUTER MOULDING RH	NOT NECESSARY	117.00	-
1	FRONT DOOR PROTECTOR RH	NECESSARY	72.00	72.00
1	FRONT DOOR STEP PLATE RH	NOT NECESSARY	160.00	-
1	FRONT DOOR STEP GARNISH RH	CRACKED	126.00	126.00
	LESS 15% DISCOUNT		-518.55	-186.75
			2,938.45	1,058.25
	LABOUR			
	TO CHECK & RECTIFY WIRING SYSTEM.		80.00	30.00
	TO RUST PROOF ON AFFECTED AREAS.	NOT NECESSARY	60.00	_
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DMAGED BODYPARTS, REPAIR, RE-ALIGN & DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH.		800.00	400.00
	TO RE-SPRAY PAINTING ON THE CHANGED BODYPARTS, REPAIRED PORTION & WHERE CONSISTENT TO THE ACCIDENT.		800.00	400.00
			1,740.00	830.00
	GRAND TOTAL		4,678.45	1,888.25

RECOMMENDED COST OF LUMP SUM REPAIRS		1,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SPF19014388/Gvf3s2

NOTE: THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,400.00 - \$1,500.00

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk,