

# JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4  
#02-37 Premier @ Kaki Bukit  
Singapore 415875  
Tel : 94513429

EQ Insurance Co Ltd  
5 Maxwell Road  
#17-00 Tower Block MND Complex  
Singapore 069110  
Attn: Motor Claims Department

## ESTIMATE

*ANM20*

Vehicle No : SGD 61U  
Make/Model: TOYOTA ALPHARD 2.4  
Accident Date 17.08.2019

### Parts

|                                    |                |    |                 |                 |
|------------------------------------|----------------|----|-----------------|-----------------|
| 01) Rear bumper                    | <i>Deepans</i> | \$ | 850.90          | <i>—</i>        |
| 02) Rear bumper clips              | <i>see</i>     | \$ | 60.00           | <i>—</i>        |
| 03) Rear bumper retainer rh        | <i>see</i>     | \$ | 125.00          | <i>—</i>        |
| 04) Rear fende rh                  | <i>3.500</i>   | \$ | 1,250.00        | <i>—</i>        |
| 05) rear fender inner shield rh    | <i>11</i>      | \$ | 280.00          | <i>X</i>        |
| 06) Rear fender inner shield clips | <i>11</i>      | \$ | 60.00           | <i>X</i>        |
| 07) Rear Aircon blower             | <i>one</i>     | \$ | 2,650.10        | <i>3,250.00</i> |
|                                    |                | \$ | 5,875.90        |                 |
| Less 25%                           |                | \$ | (1,468.98)      |                 |
|                                    |                | \$ | <u>4,406.92</u> |                 |

*p- 5186.80*  
*25%*  
*3890.1*

### S/Nett

|                         |            |    |               |          |
|-------------------------|------------|----|---------------|----------|
| 08) Tail lamp assy rh   | <i>one</i> | \$ | 650.00        | <i>—</i> |
| 09) Tail lamp chrome rh | <i>11</i>  | \$ | 150.80        | <i>X</i> |
|                         |            | \$ | <u>800.80</u> |          |

### Labour Charges

|   |                      |    |                 |            |
|---|----------------------|----|-----------------|------------|
| 10) To dismantle aircon blower                          | <i>9 ref. 11 gas</i> | \$ | 150.00          | <i>120</i> |
| 11) To check wiring                                     |                      | \$ | 100.00          | <i>20</i>  |
| 24) To knock out dents on affected areas nd renew parts |                      | \$ | 900.00          | <i>750</i> |
| 25) To putty & respray painting                         |                      | \$ | 1,000.00        | <i>600</i> |
|   |                      | \$ | <u>2,150.00</u> |            |

*6090.10*  
*4872.08*

JKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- To resurvey subject to confirmation
- To resurvey is on a "Without Prejudice" basis
- To resurvey (condition(s) is allowed

for JA AUTOCARE PTE LTD  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

*not about ok*  
*2/5 # 4850*  
*26/8/19*  
*Wh, 20 Atkaya*

# JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4  
#02-37 Premier @ Kaki Bukit  
Singapore 415875  
Tel : 94513429

EQ Insurance Co Ltd  
5 Maxwell Road  
#17-00 Tower Block MND Complex  
Singapore 069110  
Attn: Motor Claims Department

## SUPPLEMENTARY ESTIMATE

Vehicle No : SGD 61U  
Make/Model: TOYOTA ALPHARD 2.4  
Accident Date 17.08.2019

### Parts

01) Rear bumper top garnish rh

|                 |    |               |   |
|-----------------|----|---------------|---|
| <i>Deep cut</i> | \$ | 250.80        | ✓ |
|                 | \$ | 250.80        |   |
| Less 25%        | \$ | (62.70)       |   |
|                 | \$ | <u>188.10</u> |   |

### Labour Charges

02) To refill aircon gas  
03) To dismantle upholstery , seat etc

|                  |               |    |
|------------------|---------------|----|
| \$ <i>Refuel</i> | 120.00        | X  |
| \$               | 200.00        | 60 |
| \$               | <u>320.00</u> |    |

---

\$ 508.10

---

for JA AUTOCARE PTE LTD