

> Back to OneMotoring

## Enquiry on Vehicle Recall - Vehicle Specific

\* ONLY INFORMATION ON VEHICLE RECALLS SUBMITTED FROM 9 APRIL 2007 IS AVAILABLE

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID:	828W	
Vehicle Details		
Vehicle Registration number:	YN5078Z	
Make:	MITSUBISHI	
Vehicle Model:	CANTER FEB21ER4SDEB	
Engine No.:	4P10A99900	
Chassis No.:	FEB21EA00275	
Recall Details		
1	Recall No.:	R2016050246
	Manufacturer Recall Date:	27 Apr 2016
	Estimated Completion Year of Recall:	2017
	Brief Description (As Provided by Motor Dealer):	MATERIALS OF FUEL RETURN HOSE WERE NOT SUITABLE AGAINST CHEMICALS FROM PAINT, SHAMPOO OR GREASE, WHICH ARE USED DURING REAR BODY BUILDING OR WASHING.
	Date Rectified:	18 Jan 2017
	<b>For more details, contact GOLDBELL ENGINEERING PTE LTD</b>	
	Hotline Information:	CALL CENTRE at 68640698
2	Recall No.:	R2018080566
	Manufacturer Recall Date:	30 Jul 2018
	Estimated Completion Year of Recall:	2020
	Brief Description (As Provided by Motor Dealer):	The airbag ECU wiring harness, which has been secured between cabin front metal bracket and front top edge of ECU bracket may in isolated cases be squashed or sheared off due to this routing.
	Date Rectified:	09 Jan 2019
	<b>For more details, contact GOLDBELL ENGINEERING PTE LTD</b>	
Hotline Information:	EUGENE SEE CHAO-SHAN at 68640680	

OK