

# ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	11:35hrs
ACCIDENT DATE	3-Aug-19
BUS CAPTAIN NAME	MARISEENIVASAGAM SOMASUDARAM
EMPLOYEE NUMBER	

BUS REGISTRATION NUMBER	SB6404E
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

## SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

Part No.	Part or Item Description	Quantity	Total Cost
	WHITE & GREY COLOR STICKER	1	\$80.00
		7% GST	\$5.60
		<b>PARTS TOTAL COST</b>	<b>\$85.60</b>

## SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO REMOVE & REPLACE STICKER	\$650.00
TO REMOVE & REFIX WHEEL ARCH PANEL	\$650.00
TO PUTTY & SPRAY PAINT WHEEL ARCH PANEL	\$1,280.00
	7% GST
	\$180.60
	<b>LABOUR TOTAL COST</b>
	<b>\$2,760.60</b>

# ESTIMATED ACCIDENT REPAIR COST



## SECTION 3: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST	-
---------------------------------	---

## SECTION 4: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

## SECTION 5: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	
		Date Out From Repairs	
BUS TYPE (SD / DD)		Number of Days Under Repair	2
LOSS OF USE COST			\$600.00

SUMMARY	
SECTION NO.	COST
1	\$85.60
2	\$2,760.60
3	-
4	-
5	\$600.00
<b>GRAND TOTAL</b>	<b>\$3,446.20</b>