

ASS. REC. BY:

REF: CS/FCI 1004519/GVf3n2

Special Instruction:

SURV/OY:

GA

ASSIGNMENT (Office)

From (Person): Jason Teachu kiat of FCI Date/Time: 20.8.11 11.59 a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FW 3694K Insured: SH 8028B

at Workshop m/s VW Tcc Automobile Tel: 67 653373

of BIK 6 woodland Road 399F

Policy No: Claim No: D19005092MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 2.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 20.8.19 1.13 p.m Person Contacted: Shu Yi Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FW 3694K - X
	SH 8028 B - CS/smo/602X127/mivbm2 DOA - 16/11/2016
	21/4/19 Sent Preli Revise by e-mail
21/8/19	LS \$ 1500 confirmed by email (Red 3528.80, 7090) mv: \$ 2500 (est) LTA: \$ 608 HV: \$ 1892

Surveys

602.

REF:

Fci

ASSIGNMENT

(C-2023)

From:

Date:

Estimated Cost:

OD / TP DWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt.:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FW3694K

Yr Regn:

06 Mar 2003

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda TA200

C.C.

197

Colour:

Blue & white

A/C:

Insured / Std / NI / NA

Sp. Reading

95953

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

TA 200 500 / 522

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 100/80-17

R: 130/90-15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

METSELER

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

D.O.I.

20-08-19

Survey held at

w/s

4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 22 AUG 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

: Final Report

Date/Time, File Return to?

2) >> 18 - typist

Report Format :

CWS

Lump Sum / I.B.I. (\$

1500/-)

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

: S + RS, St

: Photos

: Others

TOTAL

140
50
44
134



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005092MFSH
Our Ref: CS/FCI19014519/Gvf3

Date: 21 Aug 2019

The Motor Claims Department
MS First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. FW3694K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/08/2019 at the premises of M/s YEW TEE AUTOMOBILE. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,028.80</u> .
Revised Estimate Amount	: S\$ <u>2,801.10</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the n/s & o/s body.



Yours faithfully

Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date 05-08-2019 Our Ref No. D19005092MFSH

Accident Date 02-08-2019 Claim Type. Third Party

Insured Vehicle SH8028B Third Party Vehicle. FW3694K

Survey Location BLK 6 WOODLANDS ROAD 399F YEW TEE INDUSTRIAL ESTATE

Contact Person. SHUYI

Contact No. 67653373/ 0 Fax No. 676044895

Survey Type WITHOUT PREJUDICE: LIABILITY UNCLEAR: WE WILL WAIT FOR THE
POLICE INVESTIGATION RESULTS OR INSURED V

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA Fax No. 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on
NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop YEW TEE AUTOMOBILE
TECH PTE LTD Attention. NIL

Cc : TP Solicitor NA TP Solicitor Fax No. NA

Officer Incharge JASON TEA CHEE KIAT

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Wednesday, August 21, 2019 2:19 PM
To: 'CWS Motor Claims'
Cc: 'Jason Tea'
Subject: SURVEY ASSESSMENT - D19005092MFSH/1
Attachments: FW3694K DOA 02082019 REVERT.pdf

Dear Jason Tea

Enclosed preliminary revised of vehicle FW3694K
Date of Survey : 20/08/2019
Number of days : 3 days

Thank you.

Best Regards,

YC Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, August 20, 2019 1:15 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005092MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Tuesday, 20 August, 2019 11:59 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005092MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 22 August 2019 8:41 AM
To: YT(HQ)
Cc: 'Yew Tee (HQ)'; SUR
Subject: RE: FW 3694K-DOA: 2/8/2019

Dear Vinnie,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) <info@yewteegroup.com>
Sent: Wednesday, 21 August 2019 4:14 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: 'Yew Tee (HQ)' <utauto@singnet.com.sg>
Subject: RE: FW 3694K-DOA: 2/8/2019

Hi Veron,

Ok we accept

Thank you

Best Regards

Vinnie Lim



Yew Tee Automobile Tech Pte Ltd

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 /6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID:62562081
Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Wednesday, 21 August 2019 3:24 pm
To: YT(HQ) <info@yewteegroup.com>; SUR <sur@lkkauto.com>
Subject: FW 3694K-DOA: 2/8/2019

Dear Vinnie,

WITHOUT PREJUDICE

Offer Lump Sum \$1500 @ 3 working days

PARTS-\$1141 (less 10%)=\$1026.90
SN-\$471
LABOUR-\$410
TOTAL-\$1907.90 (less 20%)=\$1526.32

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Bike model

Honda TA200 Phantom

Type

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS ▼

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH ▼

Honda TA200 Phantom (/listing/usedbike/honda-honda-ta200-phantom/13626/)



(/listing/usedbike/honda-honda-ta200-phantom/13626/)

SGD\$3900

Reg : 20/05/2004

Type: Cruiser

197cc

44250km

May 2005 Registered Honda TA200 Phantom. COE Till Jan 2024. Original Condition. Well Maintained. Well Kept With Regular Wash. Re Wrapped Seat. Number Plate..etc

Posted on : 30/07/2019

★ PAID AD ★ DIRECT SELLER

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-TA200-PHANTOM/13626/)

Honda TA200 Phantom (/listing/usedbike/honda-honda-ta200-phantom/13392/)



(/listing/usedbike/honda-honda-ta200-phantom/13392/)

SGD\$5800

Reg : 20/03/2003

Type: Cruiser

197cc

Owner Upgrading. Very Good Transportation Bike. Problem Free. Smooth Acceleration Yet Fuel Saving Proven. Bike Is In Good Working Condition. No Repair Needed. Call/Visit Us Now For No Ob...

Eligible For NEA Cash Incentive Of \$3500.

Posted on : 11/08/2019

★ PAID AD ★ DEALER AD

Honda TA200 Phantom (/listing/usedbike/honda-honda-ta200-phantom/13555/)



(/listing/usedbike/honda-honda-ta200-phantom/13555/)

SGD\$4500

Reg : 16/04/2004

Type: Cruiser

197cc

89108km

Honda TA200 For Sale. Welcome Trade In. Loan Available. Ambra Enterprises Is Located At Block 5034 Ang Mo Kio Industrial Park 2 #01-327.

Posted on : 24/07/2019

★ PAID AD ★ DEALER AD

Honda TA200 Phantom (/listing/usedbike/honda-honda-ta200-phantom/13770/)



(/listing/usedbike/honda-honda-ta200-phantom/13770/)

SGD\$6000

Reg : 30/03/2002

Type: Cruiser

197cc

50578km

Note: Bike Price Is \$2,500 Buyer, New Owner Eligible For \$3,500 Nea Cash Rebate. Owner Retiring. Bike Is In Good Working Condition, Nice Number. No Repair Needed. Call Me, Price Negotiable. ...

Posted on : 12/08/2019

★ DIRECT SELLER

Honda TA200 Phantom (/listing/usedbike/honda-honda-ta200-phantom/13611/)



(/listing/usedbike/honda-honda-ta200-phantom/13611/)

SGD\$6500

Reg : 11/06/2002

Type: Cruiser

197cc

35000km

Guarantee In Good Condition Condition You Can Take A Thorough Check When Viewing. Just For \$3000 Bucks You Can Ride For Another 3 Years And Also Eligible To Renew Option Available. Eligible for N...

Posted on : 29/07/2019

★ DIRECT SELLER

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	848E
Vehicle No.:	FW3694K
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	TA200
Primary Colour:	White
Manufacturing Year:	2002
Engine No.:	TA200E5001522
Chassis No.:	TA2005001522
Maximum Power Output:	-
Open Market Value:	\$3,271.00
Original Registration Date:	06 Mar 2003
First Registration Date:	06 Mar 2003
Transfer Count:	1
Actual ARF Paid:	\$491.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	05 Mar 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,721.00
COE Rebate Amount:	\$608.00
Total Rebate Amount:	\$608.00

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.

For more information, please visit <http://www.nea.gov.sg/mtcincentive> or contact NEA at 1800-2255-632.

The information contained herein is correct as at 20 Aug 2019

OK

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : FIRST CAPITAL INSURANCE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTHQ/TP/1908/017
Policy No:	0089590395-15	Date of Loss:	02/08/2019
Vehicle Reg. No.:	FW3694K	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SH8028B
Any Injuries?	no	Contact No:	
Insured/Claimant:	CHETIARMURTHY S/O RETNASAMY	Driver:	CHETIARMURTHY S/O RETNASAMY

Make/Model:	Honda, Tiger	Vehicle Reg. Date:	06 Mar 2003
Vehicle Colour:		Engine Number:	TA200E5001522
Chassis No:	TA2005001522	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - CHANGE/CROSS LANE
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	3,358.80
Miscellaneous Items	690.00
Labour	620.00
Paintwork Labour	360.00
Towing	0.00
Gross Total(S\$):	5,028.80
GST 7.00%(S\$):	352.02
Nett Amount(S\$):	5,380.82

This claim is handled by: SHUYI

**L&L Auto Consultants hereby notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT FORK LH X <i>NN</i>	190.00	-10.00	171.00 X
2	1	FRONT FORK RH X <i>NN</i>	190.00	-10.00	171.00 X
3	1	FRONT SIGNAL LAMP LH X <i>NN</i>	88.00	-10.00	79.20 X
4	1	FRONT SIGNAL LAMP RH X <i>CRA</i>	88.00	-10.00	79.20 X 48
5	1	FRONT HEADLAMP X	145.00	-10.00	130.50 X
6	1	FRONT HEADLAMP CHROME X <i>NN</i>	85.00	-10.00	76.50 X
7	1	FRONT DISC ROTOR X	230.00	-10.00	207.00 X
8	1	FRONT BRAKE CALIPER X	280.00	-10.00	252.00 X
9	1	FRONT HANDLE BAR X <i>BT</i>	180.00	-10.00	162.00 X 55
10	1	FRONT STEERING STEM X	55.00	-10.00	49.50 X
11	1	FRONT STEERING UPPER BRACKET X <i>NN</i>	70.00	-10.00	63.00 X
12	1	FRONT STEERING LOWER BRACKET X	70.00	-10.00	63.00 X
13	1	FRONT SIDE MIRROR LH X <i>Q's</i>	120.00	-10.00	108.00 X 28
14	1	FRONT SIDE MIRROR RH X <i>Q's</i>	120.00	-10.00	108.00 X 28
15	1	FRONT BRAKE LEVER X <i>Cut</i>	25.00	-10.00	22.50 X
16	1	FRONT CLUTCH LEVER X <i>NN</i>	25.00	-10.00	22.50 X 485
17	1	FUEL TANK X <i>BT</i>	680.00	-10.00	612.00 X 38
18	1	FUEL TANK LOWER CHROME PROTECTOR RH X <i>CRA</i>	110.00	-10.00	99.00 X
19	1	FUEL TANK EMBLEM RH X <i>McC.</i>	75.00	-10.00	67.50 X
20	1	FUEL TANK EMBLEM LH X <i>McC.</i>	75.00	-10.00	67.50 X
21	1	FRONT FOOT BRAKE RH X <i>BT</i>	60.00	-10.00	54.00 X
22	1	FRONT FOOT REST RH X <i>Cut</i>	20.00	-10.00	18.00 X
23	1	FRONT FOOT REST LH X <i>BT</i>	20.00	-10.00	18.00 X
24	1	FRONT FOOT REST BRACKET LH X <i>BT</i>	120.00	-10.00	108.00 X 35
25	1	REAR NUMBER PLATE BRACKET X <i>BT</i>	120.00	-10.00	108.00 X 50
26	1	REAR SIGNAL LAMP LH X <i>BT</i>	96.00	-10.00	86.40 X 79
27	1	REAR FOOT REST LH X <i>BT</i>	20.00	-10.00	18.00 X
28	1	REAR SWING ARM ASSY X <i>NN</i>	375.00	-10.00	337.50 X 1141
Total Parts (\$\$)					3,358.80 <i>10% 1026.9</i>

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT NUMBER PLATE X <i>NN</i>	35.00	0.00	35.00 X
2	1	REAR BOX X <i>mis</i>	260.00	0.00	260.00 X 140
3	1	REAR BOX BRACKET X <i>BT</i>	120.00	0.00	120.00 X
4	1	REAR BOX TRAY X <i>mis</i>	40.00	0.00	40.00 X
5	1	REAR NUMBER PLATE X <i>BT</i>	35.00	0.00	35.00 X 15
6	1	ERP UNIT X <i>Cut</i>	200.00	0.00	200.00 X 156
Sub Total (\$\$)					690.00 <i>315</i>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 <i>20</i>
2	1	To Conduct Wheel Balancing	60.00	0.00	60.00 X <i>NN</i>
3	1	Towing Charges.	80.00	0.00	80.00 X <i>40</i>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	450.00	0.00	450.00

200

Gross Labour Cost (\$\$) 620.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	0.00	60.00
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	300.00	0.00	300.00

X
150

410

Gross Labour Cost (\$\$) 360.00

< END OF ESTIMATES >

[Signature]
21/8/19
3 Days.
Lumpsum Repair.
After repair photos.
Gno Qiap - 8288 0282
20/8/19.

1751.9
20%: 1400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

100/80-17



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19014519/Gvf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8028B	Veh. Inspected	FW 3694K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005092MFSH	Excess (\$)	0.00	
Assign From	JASON TEA CHEE KIAT	Assign Date	20/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA TA200	c.c	197	
Engine No.	HIDDEN	Year of Reg.	2003	
Chassis No.	TA2005001522	Colour	BLUE / WHITE	
Odometer	95953	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	100/80-17	METZELER	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	130/90-15	METZELER	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/08/2019	Inspection Date	20/08/2019	
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FW 3694K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FORK LH	NOT NECESSARY	190.00	-
1	FRONT FORK RH	NOT NECESSARY	190.00	-
1	FRONT SIGNAL LAMP LH	NOT NECESSARY	88.00	-
1	FRONT SIGNAL LAMP RH	CRACKED	88.00	48.00
1	FRONT HEADLAMP	NOT NECESSARY	145.00	-
1	FRONT HEADLAMP CHROME	NOT NECESSARY	85.00	-
1	FRONT DISC ROTOR	NOT NECESSARY	230.00	-
1	FRONT BRAKE CALIPER	NOT NECESSARY	280.00	-
1	FRONT HANDLE BAR	BENT	180.00	55.00
1	FRONT STEERING STEM	NOT NECESSARY	55.00	-
1	FRONT STEERING UPPER BRACKET	NOT NECESSARY	70.00	-
1	FRONT STEERING LOWER BRACKET	NOT NECESSARY	70.00	-
1	FRONT SIDE MIRROR LH	DISTORTED	120.00	28.00
1	FRONT SIDE MIRROR RH	DISTORTED	120.00	28.00
1	FRONT BRAKE LEVER	CUT	25.00	25.00
1	FRONT CLUTCH LEVER	NOT NECESSARY	25.00	-
1	FUEL TANK	DENTED	680.00	485.00
1	FUEL TANK LOWER CHROME PROTECTOR RH	CRACKED	110.00	38.00
1	FUEL TANK EMBLEM RH	NECESSARY	75.00	75.00
1	FUEL TANK EMBLEM LH	NECESSARY	75.00	75.00
1	FRONT FOOT BRAKE RH	BENT	60.00	60.00
1	FRONT FOOT REST RH	CUT	20.00	20.00
1	FRONT FOOT REST LH	BENT	20.00	20.00
1	FRONT FOOT REST BRACKET LH	BENT	120.00	35.00
1	REAR NUMBER PLATE BRACKET	BENT	120.00	50.00
1	REAR SIGNAL LAMP LH	BROKEN	96.00	79.00
1	REAR FOOT REST LH	BENT	20.00	20.00
1	REAR SWING ARM ASSY	NOT NECESSARY	375.00	-
	LESS 10% DISCOUNT		-373.20	-114.10
			3,358.80	1,026.90

Report Ref No. CS/FCI19014519/Gvf3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	35.00	-
1	REAR BOX (SN)	MISSING	260.00	140.00
1	REAR BOX BRACKET (SN)	BENT	120.00	120.00
1	REAR BOX TRAY (SN)	MISSING	40.00	40.00
1	REAR NUMBER PLATE (SN)	BENT	35.00	15.00
1	ERP UNIT (SN)	CUT	200.00	156.00
			690.00	471.00
	<u>LABOUR</u>			
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS.		30.00	20.00
	TO CONDUCT WHEEL BALANCING.	NOT NECESSARY	60.00	-
	TOWING CHARGES.		80.00	40.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.		450.00	200.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	60.00	-
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		300.00	150.00
			980.00	410.00
GRAND TOTAL			5,028.80	1,907.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/FC119014519/Gvf3n2

MARKET VALUE: \$2,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$608.00=NETT VALUE: \$1,892.00

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.