

Cheng Hoe Motor Pte Ltd

BK 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJK 8249X
TP/India

M/S : INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100
ATTN: Motor Claim Department
WS Ref: TP/INDIA/YS

FAX: 62247743

Claim Type: Third Party
Accident Date: 17/08/2019

TP Veh Reg No: SHD3533T

Estimate No: ES1991893/YISHUN
Date: 19 Aug 2019
Policy No: 5102519161
Veh Reg No: SJK8249X
Make/Model: HONDA CIVIC 1.6L 5AT
Chassis No: JHMFD46209S00141
Engine No: R16A14000741
Reg. Date: 05/11/2008

Estimate Repair Cost to Vehicle No :SJK8249X

Description	U/Price	Quantity	List Price	Amount
List Price			SS	SS
1 FRONT BUMPER	638.00	1 PC	CM 638.00	—
2 FRONT BUMPER REINFORCEMENT	218.40	1 PC	B 218.40	—
3 FRONT BUMPER CENTRE LOWER GRILLE	194.50	1 PC	Dij 194.50	—
4 FRONT BUMPER UNDER COVER	62.40	1 PC	CM 62.40	—
5 FRONT BUMPER UNDER COVER CLIPS	3.90	8 PCS	MC 31.20	—
6 FRONT BUMPER CLIPS	3.90	6 PCS	MC 23.40	—
7 FRONT RH FOG LAMP	303.50	1 PC	MC 303.50	7
8 FRONT RH FOG LAMP GARNISH	95.10	1 PC	MC 95.10	—
9 FRONT BUMPER SIDE RETAINERS	13.60	2 PCS	CM 27.20	—
10 FRONT RH FENDER	537.50	1 PC	B 537.50	—
11 FRONT RH FENDER INNER SHIELD	94.80	1 PC	CM 94.80	—
12 FRONT RH FENDER INNER SHIELD CLIPS	3.90	6 PCS	MC 23.40	—
13 FRONT RH FENDER LAMP	38.10	1 PC	MC 38.10	7
14 FRONT RH FENDER INNER GARNISH CLIPS	3.90	3 PCS	MC 11.70	—
15 AIR-CON CONDENSER	729.40	1 PC	B 729.40	—
16 RADIATOR	1,507.40	1 PC	1,507.40	7
17 RADIATOR FAN COWLING	109.40	1 PC	109.40	7
18 FRT SUPPORT PANEL	426.30	1 PC	B 426.30	—
19 FRONT SUPPORT PANEL TOP GARNISH CLIPS	3.90	4 PCS	MC 15.60	—
20 FRONT NUMBER PLATE GARNISH	51.80	1 PC	MC 51.80	—
21 FRONT WIPER TANK	72.90	1 PC	MC 72.90	—
22 FRONT RH SPORT RIM	753.70	1 PC	MC 753.70	—
23 FRONT RH SHOCK ABSORBER	334.50	1 PC	334.50	7
24 FRONT RH KNUCKLE ARM	243.50	1 PC	243.50	7
25 FRONT RH WHEEL BEARING	129.40	1 PC	129.40	7
			6,673.10	
			Less 20%	1,334.62
				5,338.48

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/YS

Claim Type: Third Party

Accident Date: 17/08/2019

TP Veh Reg No: SHD3533T

Estimate No: ES1991893/YISHUN

Date: 19 Aug 2019

Policy No: 5102519161

Veh Reg No: SJK8249X

Make/Model: HONDA CIVIC 1.6L 5AT

Chassis No: JHMFD46209S00141

Engine No: R16A14000741

Reg. Date: 05/11/2008

Estimate Repair Cost to Vehicle No :SJK8249X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
26 TOWING	50.00	1 LA	50.00	✓
27 REMOVE & REFIX FRT BUMPER ASSY,FOG LAMP,GRILLE,FRT RH FENDER,HEADLAMPS,RADIATOR & MOTOR,STRAIGHTEN,KNOCK & REPAIR FRT BOTH CHASSISS,BONNET,FENDER INNER HOUSING,CUT,WELD & RENEW FRT SUPPORT PANEL & REALIGN THE SAME	1,100.00	1 LA	1,100.00	✓
28 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
29 REMOVE & REFIX FRT RH UNDER CARRIAGE,CHECK DRIVE SHAFT & STEERING	200.00	1 LA	200.00	?
30 PUTTY & RESPRAY ON FRT SUPPORT PANEL,FRT BUMPER,REINFORCEMENT,BONNET,HINGES,FRT FENDERS,FENDER INNER PANEL & ALL AFFECTED AREAS	900.00	1 LA	900.00	800
31 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
32 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,470.00	2,470.00
Total				S\$ 7,808.48
Add GST @ 7%				546.59
Total Amount Payable				S\$ 8,355.07

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE