

(RMK)

INS. CASE OWNER:

CC 4/FWD1901

4525, Amb...

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

20/8/19

Date / Time:

20/8/19

Registered in Merimen:

22/8/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLR 8016 R

Name of Insured:

NG YUEN YEE

Insured Tel No.:

HP:

Excess See II :SS

D.O.A.:

12/8/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Tan Yee Keng

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

1201910024214

Policy No.:

PMPV 2018-00010380

Make / Model:

Mazda

Place of Accident:

USBE CHAMBER 1P

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKZ 6065G

INSRS:
WSP:
Tel:
Liability:
RMKS:

Leang Automotive

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

12/8/19

SLR 8016 R

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

23/9/19

File -> typem and case

4/12/19

bv snc by fox

4/11/19

File -> sm per to etc

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email:

Call:

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email:

Call:

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. 24

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

5W.W (S 1W x 5 days)

Loss of Income (LOI):

S\$

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

S\$

29.W

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

Total:

S\$

4829.W

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

S\$

4829.W

Name 1:

Leang Automotive

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Non-Report/Private Settle

2) Report Format:

3) Survey fee:

97

1500.W

COPY SENT

ASE REC BY:

REF: CSI/FWD/17014525/Asf3

Special Instruction:

Survefor Adrian

ASSIGNMENT (Office)

From (Person): Vanessa Chan

of FWD

Date/Time: 20.8.19 11.034.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 60659

Insured:

SLR 8016R

at Workshop m/s

Leang Automotive

Tel:

90286516

of 101 Kaki Bukit Ave 6 #01-68

Policy No:

Claim No: 1201900024314

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12.8.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 20.8.19 1.56p.m

Person Contacted:

Leang

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SKZ WESG:006/16215012262/1607/12 20.8.25/07/2018

SLR 8016R -X

22/08/19

checked with Leang (repairer), if liability 100% then will proceed direct settlement. Hsio Tong ~~not~~ instruction will settle with Leang. File pass to Hsio Tong.

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

TP FWD.

US # 43w upel # 6307-145941

MV :

PV :

Nett :

Veh No: SK 26065 G Yr Regn: 2016 Jan.Type: M. Cap / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier cc 1986Colour: Black A/C: Insured / Std / Nil / NASp. Reading: 1336/9 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: ZSU600061870Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 235/55R18R: 235/55R18BS / DUN / EXNOVA / QY / FS / LIZA / MMIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.L. 20/08/19Survey held at LeangDes. of Damages: Frt / Rear / Q/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S+RS, \$

Photos

Others

TOTAL

SKZ606SG

Toyota Harrier

ZSU600061870

TPFWD

Vivian

Front Bumper	torn	1450.50 ✓
Front Bumper Clips	NA	30 ✓
Front Bumper Side Holder RH.	not in	67 x
Front RH Fender	dented	781.90 ✓
Front RH Fender Inner Shield	no in	218.30 x
Front RH Fender Inner Shield Clips	no in	30 x
Headlamp RH.	cracked	3303.10 ✓
Front RH wheel rim int		880(SN) 500(SN)
Front RH Lower Arm		435.10 x
Front RH Knuckle Arm		665.10 x
Front RH Wheel Hub c/w Bearings		371.50 x
Front RH Shock Absorber		591.60 x

5565.50

SN: 500

417412

SKZ606SG,

Panel Beating

~~600~~ 300

Spray Painting

~~600~~ 400

Wiring.

~~50~~ 30

To dismantle front undercarriage.

380 X

To perform wheel alignment

150 X 730

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary damage must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 5404.12

L/S 4.3K

04 Days

1060710

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Tuesday, 20 August 2019 11:03 AM
To: admin-d@lkkauto.com; admin-a@lkkauto.com
Cc: motorclaims.sg@fwd.com; josey.loh@fwd.com
Subject: Urgent: Pre-Repair Inspection: Your Vehicle: SLR 8016 R; Leang Auto's Vehicle: SKZ 6065 G; DOA: 12.08.2019 OUR CLAIM REF: 1201900024314
Attachments: SLR8016R OI GIA.pdf

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.


Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Venessa Chan - SGUser
Sent: Tuesday, August 20, 2019 11:02 AM
To: 'bonnie kwok'
Cc: Motor Claims SG - SG Common; Josey Loh Kah Wai - SGUser
Subject: Urgent: Pre-Repair Inspection: Your Vehicle: SLR 8016 R; Leang Auto's Vehicle: SKZ 6065 G; DOA: 12.08.2019 OUR CLAIM REF: 1201900024314

Dear ST,

Thank you for your selection of LKK Auto Consultants.
We will proceed to assign survey.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: bonnie kwok (<mailto:litigation@bonniekwok.com>)

Sent: Tuesday, August 20, 2019 10:50 AM

To: Venessa Chan - SGUser

Cc: Motor Claims SG - SG Common; Josey Loh Kah Wai - SGUser

Subject: Re: Urgent: Pre-Repair Inspection: Your Vehicle: SLR 8016 R; Leang Auto's Vehicle: SKZ 6065 G; DOA: 12.08.2019 OUR CLAIM REF: 1201900024314

Dear Sirs,

Please ignore our earlier email as it was sent in error.

Our client agrees to LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE).

Please let us have their report in due course.

Kindly request for the SJE to contact the repairers, M/s Leang Automotive at 9028 6516 to make the necessary arrangements.

Regards

ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Tue, 20 Aug 2019 at 10:44, <venessa.chan@fwd.com> wrote:

WITHOUT PREJUDICE

Dear ST,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s **LKK Auto Consultants Pte Ltd**, to conduct the pre-repair survey (PRS) on your client's vehicle, SKZ6065G . We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.*

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: bonnie kwok [mailto:litigation@bonniekwok.com]

Sent: Tuesday, August 20, 2019 10:42 AM

To: Venessa Chan - SGUser

Cc: Motor Claims SG - SG Common; Josey Loh Kah Wai - SGUser

Subject: Re: Urgent: Pre-Repair Inspection: Your Vehicle: SLR 8016 R; Leang Auto's Vehicle: SKZ 6065 G; DOA: 12.08.2019 OUR CLAIM REF: 1201900024314

Dear Sirs,

Your list of surveyors is rejected.

We have been instructed to propose the following list of surveyors for the Single Joint Expert:-

1. Fong Kok Heng
2. Danny Yap
3. Willy Goh
4. Francis Ng
5. Dennis Yap
6. Louis Ng
7. Michael Yap
8. Lim Yong Tian
9. Patrick Ng
10. Philip Foo

Kindly contact the repairers, M/s Eng Soon Painting Services at 6760 6271 for pre-repair inspection arrangements.

Regards,

ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Tue, 20 Aug 2019 at 10:34, <venessa.chan@fwd.com> wrote:

WITHOUT PREJUDICE

Dear ST,

We refer to your email dated on 20.08.2019 of the PRI Notice of your client's vehicle SKZ6065G.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT Appraisal Pte Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.

Best Regards,

Venessa Chan
Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: bonnie kwok [<mailto:litigation@bonniekwok.com>]

Sent: Tuesday, August 20, 2019 10:22 AM

To: Motor Claims SG - SG Common

Subject: Urgent: Pre-Repair Inspection: Your Vehicle: SLR 8016 R; Leang Auto's Vehicle: SKZ 6065 G; Accident Involving SKZ 6065 G & SLR 8016 R on 12 August 2019

Urgent

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. SKZ 6065 G at M/s Leang Automotive, No. 1 Kaki Bukit Avenue 6 #01-68 Singapore 417883.

Regards,
ST

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	22 Aug 2019 14:17	Cim Dtl Modified	Claimant's Name: -> LIM SOON CHUAN. Claimant's ID: -> S1795630B.	[A] LEE SU THING
2	22 Aug 2019 14:17	Cim Veh Model Changed	(204756) TOYOTA HARRIER 2.0 (A).	[A] LEE SU THING
3	22 Aug 2019 14:17	Cim Created	Reg No: SKZ6065G, Acct Date: 2019/08/12, Claim Type: TP, Insurer: FWD Singapore Pte. Ltd. (HQ), Workshop: Leang Automotive (Kaki Bukit)	[A] LEE SU THING
4	22 Aug 2019 14:17	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : Infiniti Appraisal Service.	[A] LEE SU THING
5	22 Aug 2019 14:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/02	[A] LEE SU THING
6	22 Aug 2019 14:17	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] LEE SU THING
7	22 Aug 2019 14:17	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
8	22 Aug 2019 14:52	Cim Registration Modified	Pol No:->PNPV2018-00010780.	[I] Venessa Chan
9	23 Aug 2019 15:20	Label Added	(20005):Direct Settlement .	[A] Lau Shu Pei
10	04 Oct 2019 14:13	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
11	04 Oct 2019 14:13	Cim Dtl Modified	JPJ Reg. Date: -> 2016/01/28.	[A] Elaine Kuan Hwa Meen
12	04 Oct 2019 14:13	Cim Details Notified		[A] Elaine Kuan Hwa Meen
13	23 Oct 2019 09:03	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/09/02	[A] CHEW HSIAO TONG
14	29 Oct 2019 08:03	Adj Mandate Request	Cur.Reg:4929.00:LIABILITY: 100%(BOLA 24) QUANTUM: (a) COR: \$4,300.00 + (b) LOU: \$600.00 (6days x \$100) + (c) DISBURSEMENT: \$29.00 Total: a+b+c = \$4,929.00 * VEH MODEL: Toyota Harrier(1986cc). FOR YOUR APPROVAL/INSTRUCTION.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2254194	22 Aug 2019 14:52:28	TP Case (Insurer)	Motor	FWD Singapore Pte. Ltd. (HQ)	FWD Singapore Pte. Ltd. (HQ)	SKZ6065G	NG YUEN YEE	xx.xx
2302586	04 Oct 2019 14:13:36	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKZ6065G	SLR8016R	11.77

Print Received Message

This mail is associated with :

***SKZ6065G (1201900024314)**
[SLR8016R]

TP
LIM SOON CHUAN
Aug 12 2019 10:00AM
[NG YUEN YEE]
Leang Automotive

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 02/12/2019 09:10 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4829.00) - SKZ6065G - Claim Handler: Josey Loh

Approved:4829.00:Hi! Please offer LOU at 5 days.

RELEASE

Claim Reference:	TP / 1201900024314
Surveyor's Reference:	CC4/FWD19014525/Apb3
TP Reference:	SKZ6065G

We, Leang Automotive ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle SKZ 6065G ("Vehicle") to accept the sum of \$ 4,829.00, being the amount claimed for \$ 4,300.00 (repair costs), \$ 500.00 (loss of rental/ use), --- (loss of income), \$ 29.00 (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on 12/08/2019 (date of accident) at / along NSRCC Carpark (location) involving vehicle no/s. SKZ 6065G and SLR 8016R.

This is pursuant to the inspection conducted on 20/08/2019 (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of SLR 8016R be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this ____ day of _____ 20__

CLAIMANT

[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Aug 2019 Edit Reg		20 Aug 2019 00:00 Edit Adj Rpt	S\$4,300.00 Edit Estimates	S\$4,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: NG YUEN YEE , ID: S1825165E									
Main Claimant: LIM SOON CHUAN , ID: S17956308									
Vehicle Reg. No.: SKZ6065G		Date of Loss: 12/08/2019 10:00 - :59 [42 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1201900024314		Policy/Cover Note No.: PNPV2018-00010780 (Comprehensive) Coverage: 29/08/2018 - 28/08/2019							
Vehicle Reg. No. (Insured): SLR8016R		Policy No. (Claimant): D19MPC0000168							
		Excess:							
Repairer: Leang Automotive (Kaki Bukit) AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68, 417883 Kaki Bukit - Tel:									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]									
Claimant's Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/09/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> FWD_SG (02/12/2019): Alert - Adj Mandate Approved (S\$4829.00) - SKZ6065G - Claim Handler: Josey Loh FWD_SG (30/10/2019): Alert - Adj Mandate Maintained - SKZ6065G - Claim Handler: Josey Loh 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKZ6065G (1201900024314)
[SLR8016R]
TP
LIM SOON CHUAN
Aug 12 2019 10:00AM
[NG YUEN YEE]
Leang Automotive

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/10/19 09:03	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
2	22/08/19 15:15	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
4	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
5	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
6	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
7	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
8	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
9	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
10	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
11	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
12	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
13	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
14	22/08/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>
15	13/09/19 15:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
16	13/09/19 15:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
17	13/09/19 15:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
18	13/09/19 15:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
19	13/09/19 15:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
20	13/09/19 15:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
21	13/09/19 15:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
22	13/09/19 15:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
23	13/09/19 15:03	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/08/19 15:20	EMAIL FROM FWD DD 20082019		Load PDF	
2	23/08/19 15:20	OI GIA REPORT.		Load PDF	
3	23/08/19 16:47	TP GIA REPORT		Load PDF	
4	23/10/19 08:57	TP ESTIMATE_MARKED		Load PDF	
5	29/10/19 08:02	WORKSHOP FINAL BILL		Load PDF	
6	29/10/19 08:02	GIA RPT SEARCH FEE		Load PDF	
7	04/11/19 09:43	TP LOD		Load PDF	
8	09/12/19 08:47	AUTHORISATION TO ACT FORM		Load PDF	
9	09/12/19 08:47	Release Voucher		Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	22/08/19 14:50	SLR8016R OI GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR8016R (Insd veh)	Model:	TOYOTA HARRIER 2.0 (A)
	SKZ6065G (TP veh)		
Date of Accident:	12/08/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	10,607.10
Final Repair Cost	:	\$	4,300.00
Loss of Use	:	\$	500.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	29.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,829.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Leang Automotive	:	\$ 4,829.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

09 Dec

2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19014525/APB3Q2

Date: 09/12/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00010780

Claimant Vehicle No : SKZ6065G Insured Vehicle No : SLR8016R

Date of Loss: 12/08/2019 Nature of Claim: TP Claim No: 1201900024314

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ6065G

Make & Model: TOYOTA HARRIER, 2.0 (A)

Engine No: 3ZR8665791

Reg. Date: 28/01/2016 (Man. Year: 2015)

Chassis No: ZSU600061870

Colour: Black

Odometer: 133619 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,827.10	4,674.12	4,152.98	47.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	730.00	1,050.00	58.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,607.10	5,404.12	5,202.98	49.05
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	10,607.10	4,300.00	6,307.10	59.46
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		4,829.00		

INSPECTION

Date of Assignment: 20/08/2019

Date Inspected: 20/08/2019 Inspected At:

Leang Automotive (Kaki Bukit)
AUTOBAY @ KAKI BUKIT 1 KAKI
BUKIT AVE 6 #01-68
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2019)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ6065G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,450.50 F	*1,450.50 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*FRONT BUMPER SIDE HOLDER RH	Not Necessary	67.00 F	*- FL
4	1		*FRONT RH FENDER	Dented	781.90 F	*781.90 FL
5	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	218.30 F	*- FL
6	1		*FRONT RH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 F	*- FL
7	1		*HEADLAMP RH	Cracked	3,303.10 F	*3,303.10 FL
8	1		*FRONT RH WHEEL RIM	Cut	880.00 FS	*500.00 FS
9	1		*FRONT RH LOWER ARM	Not Necessary	435.10 F	*- FL
10	1		*FRONT RH KNUCKLE ARM	Not Necessary	665.10 F	*- FL
11	1		*FRONT RH WHEEL HUB C/W BEARING	Not Necessary	374.50 F	*- FL
12	1		*FRONT RH SHOCK ABSORBER	Not Necessary	591.60 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,827.10	6,065.50
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,391.38
Total Parts (\$\$)	8,827.10	4,674.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	300.00
2	SPRAY PAINTING	New	600.00	400.00
3	WIRING	New	50.00	30.00
4	TO DISMANTLE FRONT UNDERCARRIAGE	New	380.00	0.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (\$\$)			1,780.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >